

APR 8 1992

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

Docket No. 50-382/92-05
License No. NPF-38

Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box B
Killona, Louisiana 70066

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-382/92-05 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Messrs T. W. Dexter and A. B. Earnest of this office on February 10-14, 1992. The inspection included a review of activities authorized for your Waterford Steam Electric Station, Unit 3, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violations involved the response of metal detectors, logging of safeguards events, and protection of safeguards information. Although your violation regarding the metal detectors is a repeat, we note that your procedure tests these devices aggressively. The NRC does not have definitive standards in this area, and therefore you must meet the standards which you establish for yourself. In addition, a violation regarding the logging of certain security events was also identified.

A commitment from you regarding timeliness of maintenance performed on security equipment is discussed in paragraph 3.6 of the enclosed inspection report. Please inform us if your understanding of the commitment is different than stated in the report.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

*RIV:FIPS *C:FIPS
TWDexter:nh BMurray
/ /92 / /92
Previously concurred.

for B:DRSS D:DRP
LJCallan ABBoach
4/2/92 4/7/92

ZE-04

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

9204140086 920408
PDR ADOCK 05000382
Q PDR

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

Docket No. 50-382/92-05
License No. NPF-38

Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box B
Killona, Louisiana 70066

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-382/92-05 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Messrs T. W. Dexter and A. B. Earnest of this office on February 10-14, 1992. The inspection included a review of activities authorized for your Waterford Steam Electric Station, Unit 3, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violations involved the response of metal detectors, logging of safeguards events, and protection of safeguards information. We are particularly concerned about the metal detectors and control of safeguards information violations because they are repeat violations; therefore, it appears that your previous corrective action for these violations was not adequate. In addition, a violation regarding the logging of certain security events was also identified.

A commitment from you regarding timeliness of maintenance performed on security equipment is discussed in paragraph 3.6 of the enclosed inspection report. Please inform us if your understanding of the commitment is different than stated in the report.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

*RIV:FIPS	*C:FIPS	D:DRSS	D:DRP
TWDexter:nh	BMurray	LJCallan	ABBeach
/ /92	/ /92	/ /92	/ /92

Previously concurred.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

Docket No. 50-382/92-05
License No. NPF-38

Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box B
Killona, Louisiana 70066

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-382/92-05 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Messrs T. W. Dexter and A. B. Earnest of this office on February 10-14, 1992. The inspection included a review of activities authorized for your Waterford Steam Electric Station, Unit 3, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violations involved the response of metal detectors, logging of safeguards events, and protection of safeguards information. We are particularly concerned about the metal detectors and control of safeguards information, because they are repeat violations; therefore, it appears that your previous corrective action for these violations was not adequate. In addition, a violation regarding the logging of certain security events was also identified.

A commitment from you regarding timeliness of maintenance performed on security equipment is discussed in paragraph 3.6 of the enclosed inspection report. Please inform us if your understanding of the commitment is different than stated in the report.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

*RIV:FIPS
TWDexter:nh
/ /92

C:FIPS
BMurray
3 / 10/92

EO
GFSanborn
/ /92

D:DRSS
LJCallan
/ /92

D:DRP
ABB
/ /92

Previously concurred.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

Docket No. 50-382/92-05
License No. NPF-38

Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box B
Killona, Louisiana 70066

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-382/92-05 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Messrs T. W. Dexter and A. B. Earnest of this office on February 10-14, 1992. The inspection included a review of activities authorized for your Waterford Steam Electric Station, Unit 3, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violations involved the response of metal detectors, logging of safeguards events, and protection of safeguards information. We are particularly concerned about the metal detectors and control of safeguards information violations because they are repeat violations; therefore, it appears that your previous corrective action for these violations was not adequate. In addition, a violation regarding the logging of certain security events was also identified.

A commitment from you regarding timeliness of maintenance performed on security equipment is discussed in paragraph 3.6 of the enclosed inspection report. Please inform us if your understanding of the commitment is different than stated in the report.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

*RIV:FIPS *C:FIPK
TW D: Dexter:nh BMurray
3/a/92 / /92
Previously concurred.

~~ES~~ D: DRSS
~~GFSamborn~~ LJCallan
/ /92 / /92

D: DRP
ABB
PREVIOUS CONFORMANCE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

Docket No. 50-382/92-05
License No. NPF-38

Entergy Operations, Inc.
ATTN: Ross P. Barkhurst, Vice President
Operations, Waterford
P.O. Box B
Killona, Louisiana 70066

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-382/92-05 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Messrs T. W. Dexter and A. B. Earnest of this office on February 10-14, 1992. The inspection included a review of activities authorized for your Waterford Steam Electric Station, Unit 3, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of violation (Notice). We are concerned about the Safeguards Information and access control violations because they are repeat violations; therefore, it appears that your previous corrective action for these violations was not adequate. In addition, a violation regarding the logging of certain security events was also identified.

A commitment regarding timeliness of maintenance performed on security equipment is discussed in paragraph 3.6 of the enclosed inspection report.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR Part 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will not be placed in the Public Document Room.

<i>TD</i>	RIV:FIPS	C:FIPS	EO	D:DRSS
	TWdexter:nh	BMurray	GFSanborn	LJCallan
	5/13/92	/ /92	/ /92	/ /92

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
SEPARATION THIS
PAGE IS UNCONTROLLED

Entergy Operations, Inc.

-2-

APR 8 1992

The material enclosed herewith contains Safeguards Information as defined by 10 CFR Part 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will not be placed in the Public Document Room.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original signed by

A. Bill Beach, Director
Division of Reactor Projects

Enclosure:

1. Appendix A - Notice of Violation
2. Appendix B - NRC Inspection Report
50-382/92-05

cc: w/copy of Notice of Violation and summary page only:

Entergy Operations, Inc.

ATTN: Donald C. Hintz, Executive Vice
President & Chief Operating Officer

P.O. Box 31995

Jackson, Mississippi 39286

Entergy Operations, Inc.

ATTN: John R. McGaha, Vice President
Operations Support

P.O. Box 31995

Jackson, Mississippi 39286

Wise, Carter, Child & Caraway

ATTN: Robert B. McGehee, Esq.

P.O. Box 651

Jackson, Mississippi 39205

Entergy Operations, Inc.

ATTN: D. F. Packer, General
Manager Plant Operations

P.O. Box B

Killona, Louisiana 70066

APR 8 1992

Entergy Operations, Inc.

-3-

Entergy Operations, Inc.
ATTN: L. W. Laughlin
Licensing Manager
P.O. Box B
Killona, Louisiana 70066

Chairman
Louisiana Public Service Commission
One American Place, Suite 1630
Baton Rouge, Louisiana 70825-1697

Entergy Operations, Inc.
ATTN: R. F. Burski, Director
Nuclear Safety
P.O. Box B
Killona, Louisiana 70066

Glenn Miller, Administrator
Radiation Protection Division
P.O. Box 82135
Baton Rouge, Louisiana 70884-2135

President, Parish Council
St. Charles Parish
Hahnville, Louisiana 70057

Mr. William A. Cross
Bethesda Licensing Office
3 Metro Center
Suite 610
Bethesda, Maryland 20814

Winston & Strawn
ATTN: Nicholas S. Reynolds, Esq.
1400 L Street, N.W.
Washington, D.C. 20005-3502

bcc: (see next page)

Entergy Operations, Inc.

-4-

APR 8 1992

bcc copy of entire report:

RIV Security File
Elaine Koup, RSGB/NRR (9D24)
R. D. Martin, RA
Resident Inspector
Security File
G. F. Sanborn, EO
M. J. Virgilo, NRR (13E4)

bcc copy of letter, NOV, and inspection summary only:

DMB IE-04
DRS
DRP
Lisa Shea, RM/ALF (4503)
MIS
RIV File
Section Chief, DRP/A
RSTS Coordinator
Project Engineer, DRP/A

Entergy Operations, Inc.

-4-

APR 8 1992

bcc copy of entire report:

RIV Security File
Elaine Koup, RSGB/NRR (9D24)
R. D. Martin, RA
Resident Inspector
Security File
G. F. Sanborn, ED
M. J. Virgilo, NRR (13E4)

bcc copy of letter, NOV, and inspection summary only:

DMB IE-04 111
DRS
DRP
Lisa Shea, RM/ALF (4503)
MIS
RIV File
Section Chief, DRP/A
RSTS Coordinator
Project Engineer, DRP/A

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

130018

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED