

South Carolina Electric & Qas Company P.O. Pox 88 Jankinsville, SC 29065 (803) 345-4040 John L. Skolda VI. e President Nuclear Operations

1661017 ANN L NON 16

Mr. S. D. Ebneter Regional Administrator U. S. Nuclear Regulatory Commission Region II, Suite 2900 101 Marietta Street, NW Atlanta, GA 30323

Dear Mr. Ebneter:

SUBJECT:

VIRGIL C. SUMMER NUCLEAR STATION

DOCKET NO. 50/395

OPFRATING LICENSE NO. NPF-12 SPECIAL REPORT (SPR 910007)

This Special Report is being submitted pursuant to the requirements of the Virgil C. Nummer Nuclear Station Technical Specifications, Section 4.4.5.5.a. This section requires a report be submitted, following the completion of inservice inspection of steam generator tubes, indicating the number of tubes plugged or repaired in each generator. Summarized in the table below are the results of the inspections performed during the sixth refueling outage.

ALTERNATION OF BELLEVIEW SECTION AND ARCHIVES	A	8	C	Total
Plugged	13	21	169	203
Repaired	211	309	92	612

Should you have any questions, please call at your convenience.

Very truly yours,

John L. Skolds

ARR: JLS: 1cd

C: U.

O. W. Dixon dr.

R. R. Mahan

R. J. White

General Managers

G. F. Wunder

C. A. Price

NRC Resident Inspector

J. B. Knotts Jr.

R. E. Kelso

Marsh & McLennan

Document Control Desk

INPO Records Center

ANI Library

NSRC

RTS (ONO 910060)

File (818.05 & 818.08)

9111220224 911101 PDR ADOCK 05000025

Terr