9

D. Danielm Begal Jones Knop

Midland Project: P.O. Box 1963, Midland, Michigan 48640 • Area Code 517 631-0951

June 29, 1981

Mr. Cordell Williams, Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr. Williams:

Attached for your information is a copy of our letter to Mr. Dennis Saunders along with our complete evaluation of his allegations that we were not living up to the intent of the NRC Immediate Action Letter of May 22, 1981. We feel we have fully investigated his concerns.

D B Milder Site Manager

CC: D. Saunders

W R Bird, P-14-418A J W Cook, P-26-336B R J Cook, NRC-Site

Attachment



Midland Project: P.O. Box 1963, Midland, Michigan 48640 • Area Code 517 631-0951

June 29, 1981

Mr. Dennis Saunders P.O. Box 2101 Midland, MI 48640

Dear Mr. Saunders:

On June 17, 1981 Mr. R. E. Whitaker of Consumers Power Company met with you at your offices in Auburn, Michigan to discuss your concerns with small pipe design at the Midland Nuclear Plant. Attachment #1 to this letter was prepared and given to you on June 19. Attachment #2 was returned to Consumers Power Company on June 26 with essentially the same information contained in Attachment #1. There were some minor changes in the descriptions and your job position.

Since the meeting at your offices, we have tried to investigate your concerns to the extent possible. We have talked to you numerous times on the phone asking you to be more specific with those concerns. You provided us with a specific reference on June 26, 1981 (FSK-M-1HBC-184-1).

During the period between learning of your general concerns and actually receiving your specific concerns, we have done the following:

- 1. We have gathered together all hanger drawing transmittal sheets issued since the May NRC Inspection. We have verified these sheets against the stress calculation status report or the calculation package and have found that all transmittals of new or revised hanger drawings were backed up by stress calculations which were Committed Preliminary Design Calculations.
- We have reviewed the hanger drawing red lines approved since the NRC Inspection. Of the 150 reviewed, we have found none that violated the specific written guidelines established for hanger red lines after the NRC Audit.
- With respect to your specific concern, we have verified that all activities done by Eechtel relative to that FSK had been performed in accordance with existing procedures.

In listening to your concerns the past days, we believe that part of your concerns can be attributed to the fact that you were only at Midland a short time and did not have a full understanding of the procedures used at the site. Secondly, we believe that, since you were unaware that the NRC did not stop small pipe hanger installation at the site, this could have led you to feel that we were not

Page 2 Mr. Dennis Saunders June 29, 1981

complying with the NRC's Immediate Action Letter. This was, in fact, not the case.

Attachment #3 is a press clipping that I believe best explains the thoughts I discussed with you on the phone.

We thank you for bringing your concerns to our attention. It is very important that employees identify any problems that they feel are not being addressed. We believe we have thoroughly investigated your concerns. To the best of our knowledge, and because of the hours we spent reviewing your concerns, we are confident that all small pipe and supports design and redesign are being performed in accordance with the intent of the NRC Immediate Action Letter and in accordance with present Bechtel Power procedures and specifications.

We are also forwarding your concerns and the results of our investigation to the NRC since our compliance with their May 22, 1981 Immediate Action Letter was in question.

Please find Attachment #4 which is the official close-out of the allegation evaluation.

Site Manager

CC: JWCook, P-26-336B WRBird, P-14-418A

ATTACHMENT #1



PROJECTS, ENGINEERING
AND CONSTRUCTION OUALITY ASSURANCE DEPARTMEN

1. Allegation Serial No _______

2. Who received the allegation? P. Corcoran 3. When was the allegation received? Sat. Jone 13,198/ 4. How was the allegation received? ie, telephone, face-to-face, by letter? 5. When was the allegation reported to CP Co - QA? Mm. Jone 15,198/ 6. Name of the allegator: Nennis Samders 7. Who is allegator's employer and what is the allegator's position? form.	
3. When was the allegation received? Sat. Jone 13, 1981 4. How was the allegation received? ie, telephone, face-to-face, by letter? 5. When was the allegation reported to CP Co - QA? Mm. Jone 15, 1981 6. Name of the allegator: Name Samders	
4. How was the allegation received? ie, telephone, face-to-face, by letter? 5. When was the allegation reported to CP Co - QA? Mm. J.ne. 15,198/ 6. Name of the allegator: Name: Samders	
6. Name of the allegator: Name's Samders	
6. Name of the allegator: Nennis Samders 7. Who is allegator's employer and what is the allegator's position? forms	
7. Who is allegator's employer and what is the allegator's position? form.	
	wy
employed by AP Engineering	
8. Where can the allegator be contacted? PO Box 2101 Midland	48640
9. When will the allegator make next contact? NA	
10. Can the allegator's name be used in investigation of allegation? yes	
(If Yes, will allegator provide signature to this page Yes)
11. Will the allegator permit his name to be used in reports to the NRC? V	<u>es</u>
12. Will the allegator provide details of his allegation to the NRC? waknow 662-6669 office	
STANDARD INFORMATION CHECKLIST Telecomp	WithDs. leted By
1. Notify the allegator of the procedure for investigating allegations. RE	Whithe
2. Explain that if the allegation is validated, an NCR will be issued	
and the allegator will be provided with a copy of the NCR, subsequent	0. 0
documentation and the closed NCR.	White
3. Explain that if required by 10CFR50.55(e) or 10CFR Part 21,	
the nonconformance will be reported to the NRC.	Whiteken
4. Explain that if investigation does not substantiate the allegation	
of if the allegation is not safety related, it will be dropped by	
QA at that time and he will be so notified.	eltku
5. Explain that the allegator will be provided a copy of the final	Withen
report.	Withe
Signature of the allegator indicating (i) permission to release his name in in	ternal
investigation of the allegation (ii) permission to release his name in reports	
if investigation determines that condition is reportable (iii) that Items 1, 2	
4, 5 in the checklist above have been explained and understood.	
Dated: Signature:	



13. Evaluation Completed By/Date:

ALLEGATION EVALUATION

PROJECTS, ENGINEERING
AND CONSTRUCTION QUALITY ASSURANCE DEPARTME

1. Allegation Serial No 3

14. Evaluation Reviewed by Manager,

MPQA or Section Head, QAE&I/Date:

Yes X No
If "No" to 2, above, forward to Midland Project Management Organization
or GPMD, as applicable, for further investigation.
Does alleged condition actually exist? Yes No What was found?
If "No" to 4, above, terminate investigation, enter NA in Blocks 5 through 12, significantly to 4, above, terminate investigation, enter NA in Blocks 5 through 12, significantly to 4, above, terminate investigation, enter NA in Blocks 5 through 12, significantly to 4, above, terminate investigation, enter NA in Blocks 5 through 12, significantly to 4, above, terminate investigation, enter NA in Blocks 5 through 12, significantly to 4, above, terminate investigation, enter NA in Blocks 5 through 12, significantly through 12, signific
Blocks 13 and 14 and distribute.
Has the alleged condition previously been documented on a nonconformance-type
report?
Yes No _X
If "Yes" to 6, above, enter nonconformance-type report identification:
If "Yes" to 6, above, does nonconformance-type report adequately describe
If "Yes" to 6, above, does nonconformance-type report adequately describe alleged condition, is corrective action adequate to resolve the alleged
If "Yes" to 6, above, does nonconformance-type report adequately describe alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately?
alleged condition, is corrective action adequate to resolve the alleged
alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately?
alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately? Yes No
alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately? Yes No
alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately? Yes No
alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately? Yes No Describe any actions taken to resolve inadequacies found in 8, above:
alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately? Yes No Describe any actions taken to resolve inadequacies found in 8, above: If "Yes" to 8, above, enter NA in Blocks 11 and 12, sign Blocks 13 and 14 and
alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately? Yes No Describe any actions taken to resolve inadequacies found in 8, above: If "Yes" to 8, above, enter NA in Blocks 11 and 12, sign Blocks 13 and 14 and distribute.
alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately? Yes No Describe any actions taken to resolve inadequacies found in 8, above: If "Yes" to 8, above, enter NA in Blocks 11 and 12, sign Blocks 13 and 14 and distribute. Does the alleged condition constitute a nonconforming condition which has not



PROJECTS, ENGINEERING AND CONSTRUCTION -QUALITY ASSURANCE DEPARTMENT

1. Allegation Serial No 3

what is the alleged condition? See attached page 4
What is the alleged condition? See allached page 7
What is the location of alleged condition? No specific plant location
because it is a design question.
What systems, components, items are affected by alleged condition? <u>not</u> know at this time
For how long has the alleged condition existed? Since the NRC inspection which ended May 22,1981
What requirement was violated by alleged condition? NRC Immediate Action Letter dated May 22, 1981
To whom has this condition been previously reported? An attempt was made to discuss it with F. Young, T. Supplee, or
P. Corcoron the week of June 8-12, 1981
When was the condition previously reported? See item 7
What actions have been taken to resolve alleged condition and by whom have the actics seen taken? Midland Project Quality Assurance is reviewing
Pedline Logs, Drowing Transmittals and the actual redlined drawin
or the May 20 to June 18, 1981 time period to determine was redlined or revised during that time and how it was handled. Is alleged condition covered by an existing nonconformance report?
No
Prepared By/Date:

Allaged condition

- 1. That Pravin Patel and maybe others had approved red lines of hanger drawings for systems that had only preliminary calculations rather than committed preliminary design calculations as required by the verbal instructions from Becht. Resident Engineering.
- 2. That Pravin Patel revised hanger drawings an they were possibly issued having only prelimin calculations, not committed preliminary design calculations to support the system design.

RE White 6/18/81 +



FROJECTS, ENGINEERING
AND CONSTRUCTION OUALITY ASSURANCE DEPARTMENT

1. Allegation Serial No _

2.	Who received the allegation? Pat Corcoran. Tom Supplee, and Jim Reinsch
3.	When was the allegation received? May 26, 1981
4.	How was the allegation received? ie, telephone, face-to-face by letter?
5.	When was the allegation reported to CP Co - QA? Monday June 15, 1981
6.	Name of the allegator: D. P. Saunders
7.	Who is allegator's employer and what is the allegator's position? Consultant
	DPS Enterprises
8.	Where can the allegator be contacted? P. O. Box 2101 Midland, Michigan 48640
9.	When will the allegator make next contact? June 25, 1981
10.	Can the allegator's name be used in investigation of allegation?
	(If Yes, will allegator provide signature to this page)
11.	Will the allegator permit his name to be used in reports to the NRC?
12.	Will the allegator provide details of his allegation to the NRC? Yes, if necessary
	STANDARD INFORMATION CHECKLIST
	Completed By
1.	Notify the allegator of the procedure for investigating allegations.
2.	Explain that if the allegation is validated, an NCR will be issued
	and the allegator will be provided with a copy of the NCR, subsequent
	documentation and the closed NCR.
3.	Explain that if required by 10CFR50.55(e) or 10CFR Part 21,
	the nonconformance will be reported to the NRC.
4.	Explain that if investigation does not substantiate the allegation
	of if the allegation is not safety related, it will be dropped by
	QA at that time and he will be so notified.
5.	Explain that the allegator will be provided a copy of the final
	report.
Sign	ature of the allegator indicating (i) permission to release his name in internal
inve	stigation of the allegation (ii) permission to release his name in reports to NRC
if i	nvestigation determines that condition is reportable (iii) that Items 1, 2, 3,
4, 5	in the checklist above have been explained and understood.
Date	d: June 25, 1981 Signature: Mennis le Samueles



PROJECTS, ENGINEERING
AND CONSTRUCTION QUALITY ASSURANCE DEPARTMENT

1. Allegation Serial No ____

2.	Does alleged condition affect a Q-listed system/component/item?
	Yes X No
	If "No" to 2, above, forward to Midland Project Management Organization or GPMD, as applicable, for further investigation. Does alleged condition actually exist? Yes X No What was found?
5.	If "No" to 4, above, terminate investigation, enter NA in Blocks 5 through 12, sign Blocks 13 and 14 and distribute.
6.	Has the alleged condition previously been documented on a nonconformance-type report?
7.	Yes No _X If "Yes" to 6, above, enter nonconformance-type report identification:
	If "Yes" to 6, above, does nonconformance-type report adequately describe alleged condition, is corrective action adequate to resolve the alleged condition, and is corrective action progressing adequately? Yes No Describe any actions taken to resolve inadequacies found in 8, above:
0.	If "Yes" to 8, above, enter NA in Blocks 11 and 12, sign Blocks 13 and 14 and distribute. Does the alleged condition constitute a nonconforming condition which has not been previously documented? Yes No If "Yes" to 11, above, prepare an NCR and enter the NCR No. NCR No
3.	Evaluation Completed By/Date: 14. Evaluation Reviewed by Manager, MPQA or Section Head, QAE&I/Date:



PROJECTS, ENGINEERING
AND CONSTRUCTION QUALITY ASSURANCE DEPARTMENT

1. Allegation Serial No.

	What is the alleged condition? See attached page 4
	What is the location of alleged condition? No specific plant location because it is a design question.
	What systems, components, items are affected by alleged condition? Not Known at this time.
	For how long has the alleged condition existed? Since the NRC inspection which ended May 22, 1981.
	What requirement was violated by alleged condition? NRC Immediate Action Letter dated May 22, 1981.
	To whom has this condition been previously reported? An attempt was made to
1	discuss it with P. Corcoran. T. Supplee, and J. Reinsch on May 26, 19
	When was the condition previously reported? See Item 7
	What actions have been taken to resolve alleged condition and by whom have the
	actions been taken? Midland Pr ject Quality Assurance is reviewing the Release. Drawing Transmittals and the actual redline drawings for the M
13401	o June 18. 1981 time period to determine what was redlined or revise uring the total time covered by the wasting nonconformance report?
	No

DP SAUNDERS ENTERPRISES
P. 0. Box 2101
Midland, Michigan 48640
Phone: (517) 662-6669

Alleged Condition

- 1. That Pravin Patel and maybe others had approved redlines of hanger drawings for systems; that had only preliminary calculations rather than committed preliminary design calculations as required by the verbal instructions from Bechtel Resident Engineering.
- 2. That Pravin Patel revised hanger drawings and they were possibly issued having only preliminary calculations, not committed preliminary design calculations to support the system design.

CLIPPING SHEET

CLIPPED FROM_	Midland Daily	News
CLIPPED BY	PAPuffer '	
DATE OF ISSUE	5-28-81	CITY_Midland



Pipe work at n-plant permitted

Daily News staff writer

Installation of backlogged small-hore pipe can continue at the Midland nuclear plant without prior audits of design criteria, officials clarified and confirmed Tuesday.

The Daily News said Saturday, based on an interview with in-plant-Nuclear Regulatory Commission, inspector Ronald J. Cook, that such work had been halted by the NRC pending the audits.

The NRC's Region 3 Office of Inspection and Enforcement at Glen Ellyn, Ill., said Cook may have "misunderstood" the intent of an immediate action letter issued to Consumers Power Co. Friday after a week-long inspec-

The inspection found that calculation summaries were missing from some pipe design packages. The NRC letter asked Consumers to stop issuing new design packages which are incomplete, and to "periodically" audit packages already processed to make sure the correct calculations were used.

But the letter did not require Consumers to audit hacklogged design packages first before the small nipe could be installed, as Cook had interpreted, according to NRC's Region 1 and Consumers.

"The audit does not have to be performed before the backlog work can be installed. It has to be performed before, new work can be released (for installation)," nuclear plant spokesman Norman Saari said.

He said the plant received numerous calls over the Memorial Day weekend from some of the project's 700 pipefiters who had read Saturday's article and wondered if there would be work for them Tuesday.

"Work can continue on previously issued fabrication drawings," said Jan. Strasma, NRC Region 3 spokesman.

He said Cook was not directly involved in all aspects of last week's inspection. "Perhaps he misunderstood," Strasma said.

Cook said. "I guess we didn't say, 'Completely stop what you are doing.' If Consumers is sensitive to the words 'stop work,' I guess it (the immediate action letter) didn't really say stop work."

He said his interpretation of when the audits were to be performed was "based on words we had during the week" with Consumers.

Cook said it will be satisfactory if the backlogged design packages are "ultimately audited," but said that procedure could lead to problems if the design calculations are later found to be incorrect.

"If they have to go back and tear out the work, that does not make sense to me," Cook said.

After the NRC identified the calculation problem, plant site manager Donald Miller said, 70 stress engineers worked over the holiday weekend to check design packages for errors.

"We found nothing technically wrong with any of the piping we've put in or its design," Miller said.

Miller and Saari said the exit interview with the NRC which completed last week's inspection was "extremely upbeat and very positive."

Miller said Region 3 Director James Keppler told the utility he was reserving final comment on the Midland inspection until later, but that Keppler had said "Consumers should be very satisfied to have this team come in here and give the plant, a passing grade."



ATTACHMENT #4



PROJECTS, ENGINEERING
AND CONSTRUCTION QUALITY ASSURANCE DEPARTMENT

2.	Who received the allegation? P. Corcoran
3.	When was the allegation received? Sat. June 13, 1981
4.	How was the allegation received? ie, telephone, face-to-face, by letter?
5.	When was the allegation reported to CP Co - QA? Mm. Jmc 15;1981
6.	Name of the allegator: Dennis Samders
7.	who is allegator's employer and what is the allegator's position? formarly employed by AP Engineering
8.	Where can the allegator be contacted? PO Box 2101 Midland 48640
9.	When will the allegator make next contact?
10.	Can the allegator's name be used in investigation of allegation? yes
	(If Yes, will allegator provide signature to this page)
11.	Will the allegator permit his name to be used in reports to the NRC? yes
12.	Will the allegator provide details of his allegation to the NRC? waknown now 662-6669 office
	STANDARD INFORMATION CHECKLIST
	Completed By
1.	Notify the allegator of the procedure for investigating allegations. REWalthi
2.	Explain that if the allegation is validated, an NCR will be issued
	and the allegator will be provided with a copy of the NCR, subsequent
	documentation and the closed NCR. Reculation
3.	Explain that if required by 10CFR50.55(e) or 10CFR Part 21, the nonconformance will be reported to the NRC. REWRITER
	the nonconformance will be reported to the NRC.
4.	Explain that if investigation does not substantiate the allegation
	of if the allegation is not safety related, it will be dropped by
	QA at that time and he will be so notified.
5.	QA at that time and he will be so notified. Explain that the allegator will be provided a copy of the final report. REWRITELE REWRITELE
· · ·	sature of the allegator indicating (i) permission to release his name in internal
	estigation of the allegation (ii) permission to release his name in reports to NRC
	investigation determines that condition is reportable (iii) that Items 1, 2, 3,
4, 5	in the checklist above have been explained and understood. See Attachment #2 for
Date	d: Signature: signature of Dennis P Sanders

Consumers Power Company QA66-0

ALLEGATION EVALUATION

PROJECTS, ENGINEERING AND CONSTRUCTION -QUALITY ASSURANCE DEPARTMENT

1. Allegation Serial No

	Does alleged condition affect a Q-listed system/component/item?
	Yes _X No
	If "No" to 2, above, forward to Midland Project Management Organization or GPMD, as applicable, for further investigation.
	Does alleged condition actually exist? Yes No _X
	What was found? If "No" to 4, above, terminate investigation, enter NA in Blocks 5 through 12, sig Blocks 13 and 14 and distribute.
	Has the alleged condition previously been documented on a nonconformance-type report?
	Yes NoX
	If "Yes" to 6, above, enter nonconformance-type report identification:
	NA
	If "Yes" to 6, above, does nonconformance-type report adequately describe
	alleged condition, is corrective action adequate to resolve the alleged
	condition, and is corrective action progressing adequately?
	Yes No NA
	Describe any actions taken to resolve inadequacies found in 8, above:
	If "Yes" to 8, above, enter NA in Blocks 11 and 12, sign Blocks 13 and 14 and
	distribute. WA
	Does the alleged condition constitute a nonconforming condition which has not
	been previously documented? Yes No NA
	If "Yes" to 11, above, prepare an NCR and enter the NCR No.
	마다 하기 보다 한 경기 때문에 가게 되었다. 그 아이는 그 아이는 그 아이는 그 아이는 것이 없는 것이 없다.
	NCR No NA
	Evaluation Completed By/Date: 14. Evaluation Reviewed by Manager, MPQA or Section Head, QAE&I/Date:
1	CEWlither 6/26/81 UNBINE 6/24/51

Consumers Power Company QA67-0

ALLEGATION EVALUATION QUALITY ASSURANCE DEPARTMENT

PROJECTS, ENGINEERING

1. Allegation Serial No 3

3. W	That is the elleged condition? See attached page 4 That is the location of elleged condition? No specific plant location because it is a design question.
3. W	that is the location of alleged condition? No specific plant location because it is a design question.
	That systems, components, items are affected by alleged condition? not known at this time
	For how long has the alleged condition existed? Since the NRC
	inspection which ended may 22, 1981
	Action Letter dated May 22, 1981
-	made to-discuss -it with F. Young, T. Supplee , or
8. 4	P. Corcoron - the week of - June 8-12, 1981 Then was the condition previously reported? See item -7
	what actions have been taken to resolve alleged condition and by whom have the actions been taken? Midland Project Quality Assurance is reviewing the
K	Pedline Logs, Oroming Transmittals and the actual redlined drawings for the May 20 to June 18, 1981 time period to determine what
0.	No No
11.	Prepared By/Date: RE Whith 6/18/81

	·A11.	laged condition	page 4 of
	77110		
	1	That Pravin Patel and maybe others had redlines of hanger drawings for systems	approved
i b.		had only preliminary calculations rathe	r than
		_committed preliminary design calculations required by the verbal instructions from Resident Engineering.	m_Bechtel
	_2	That Pravin Patel revised hanger dra.	uings and
		they were possibly issued having onlycalculations, not committed preliminary	design
		calculations to support the system des	rign.
-			
		RE White	6/18/81.
344.5			
	-		
1			

The transfer of the control of the c



NUCLEAR REGULATORY COMMISSION

REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137 YELLOW COPY

May 22, 1981

Docket No. 50-329 Docket No. 50-330

Consumers Power Company
ATTN: Mr. James W. Cook
Vice President
Midland Project
1945 West Parnall Road
Jackson, MI 49201

Gentlemen:

Based on Discussions between Mr. J. W. Cook and Mr. R. C. Knop on May 22, 1981, we understand that you will not issue fabrication and construction drawings for the installation of the safety related small bore pipe and piping suspension systems until steps one through four below have been completed and audited.

- MED 4.37-0 will be revised to include requirements that the specific revision number of the specification or procedure, of which the calculation was based on, is identified in the calculation package. (Note: This action was completed on 5/21/81 by issuance of Revision 16 of MED 4.37-0).
- Conduct document control review to ensure that all the applicable up-to-date specifications and procedures are in place in the work locations.
- 3. Conduct training on MED 4.37-1 (Design Calculations), the importance of following QA procedures in general, and use of specification M 343 for all personnel within the small bore piping design group performing stress analysis for safety-related piping.
- 4. Establish plans and schedules to review all small bore piping isometrics that have been issued without supporting calculations properly packaged to the revised MED 4.37-1 requirements.
- Perform the reviews identified in Item 4, above, to accomplish the following:
 - a. Bring the calculation documentation up to the level required by MED 4.37-0, Rev. 16.
 - b. Ensure that the calculations are technically adequate.

In conducting those reviews, the highest priority shall be given to

YELLOW COPY

MONEDIATE NOTICH LETTER

8146030389

-2- YELLOW COPY

piping isometric drawings issued for construction but not yet installed, in the order of installation.

- 6. During the conduct of the reviews, identified in items 4 and 5, you will document all discrepancies and will notify cognizant NRC Region III staff of any significant discrepancy. (An example of a significant discrepancy is if the reviewed calculation indicates that stresses in the pipe that is depicted on an isometric drawing issued for construction exceed code allowables).
- 7. Audits will be conducted at completion of steps one through four, and periodically during steps five and six, to ensure adequacy of the program.

Please inform us immediately if your understanding of these items is different from that stated above.

Sincerely,

9 Bert Da James G. Keppler Director

cc: Central Files Reproduction Unit NRC 20b Local PDR NSIC TIC Ronald Callen, Michigan Public Service Commission Myron M. Cherry, Chicago

Hayes 40

RIII

RIII



NUCLEAR REGULATORY COMMISSION

REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

October 28, 1983

MEMORANDUM FOR: D. G. Eisenhut, Director, Division of Licensing, NRR

FROM:

R. F. Warnick, Director, Office of Special Cases

SUBJECT:

CONCERNS OF DENNIS SAUNDERS

The attached memorandum dated October 20, 1983, documents the concerns of Dennis Saunders recently made to a member of my staff. This memorandum is forwarded for your review and any actions you deem to be necessary, as his concerns appear to be within the area under your purview.

Should you have any questions regarding this matter, please contact J. J. Harrison (388-5635) of my staff.

RFWarrick

R. F. Warnick, Director Office of Special Cases

Attachment: As stated

Profit the tr

The same

NUCLEAR REGULATORY COMMIS IN REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

001 2 0 1993

MEMORANDUM FOR: Region III Files

FROM: J. J. Harrison, Chief, Section 2, Midland

SUBJECT: TELEPHONE CONTACT WITH DENNIS SAUNDERS

On October 17, 1983, I was requested by the Regional Administrator to contact Mr. Saunders, as Mr. Keppler was involved in a conference.

At approximately 4:00 p.m. (CDT), I telephoned Mr. Saunders. Mr. F. Hawkins of Region III staff was present to assist in the call.

Mr. Saunders (telephone number (301) 565-3955) made the following statements concerning the Midland Nuclear Plant:

"Tell Jim he is the one who must sign-off on the plant." "In my opinion it's a serious problem. . .the underpinning of the Diesel Generator Building." I corrected this statement. Underpinning is related to the Auxiliary Building and Service Water Pump Structure.

He further stated that, ". . .loads during an earthquake over the nearby salt cavities were analyzed incorrectly as only a static load."

"Absolutely ridiculous to continue work on the Midland Plant, do not have a fix at one million dollars/day while we don't know what the earthquake loads are because of the salt cavities."

He further suggested, "You should stop work until you find out what the loads are during earthquakes with salt cavities below it."

Mr. Saunders stated he had performed some rough calculations showing the significance of his projected loads.

Mr. Saunders inquired as to the involvement of Jim Foster at Midland. I told him Mr. Foster currently was not associated with the Midland Project. He stated "Foster not involved was good."

He asked if I was an engineer, and if I knew the difference between dynamic and static loads.

He also wanted to know if I knew about the \$25,000 fine and five years in jail and that I had better think about them and be careful. He further stated the NRC had better think about Article 203, and tell Jim, "...not to expect any help from Denton."

Duped - 8406050031

I told Mr. Saunders his concerns would be relayed to Mr. Keppler.

Grignal Signed by G. G. Harrison J. J. Harrison, Chief Section 2, Midland

cc: J. G. Keppler R. F. Warnick G. W. Roy

Harrison/ls 10/20/83