No violations of NRC requirements were identified during the course of this inspection. Based on our observations of the accident scenarios performed by your operating staff on the Persy rimulator, it was evident that the EOPs were understood by the operators and could be accomplished using existing equipment, controls, and instrumentation.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

9112240092 911220 PDR ADDCK 05000440 PDR If you have any quastions concerning this inspection, please contact Peggy R. Rescheske of my staff at (708) 790-5273.

Sincerely,

ORIGINAL SIGNED BY GEOFFREY C. MITTHET

Geoffrey C. Wright, Chief Operations Branch

Enclosure: Inspection Report No. 50-440/91024(DRS)

co w/enclosure:

F. R. Stead, Director, Nuclear

Support Department

R. A. Stratman, General Manager,

Perry Nuclear Power Plant Kevin P. Donovan, Manager,

Licensing and Compliance Section

S. F. Kensicki, Director, Perry Nuclear Engineering Dept.

H. Ray Caldwell, General

Superintendent Nuclear Operations

DCD/DC3 (RIDS)

Licensing Fee and Debt Collection

Branch

Resident Inspector, RIII

Terry J. Lodge, Esq.

James R. Williams, State of Ohio

Robert E. Owen, Ohio

Department of Health

A. Grandjean, State of Ohio, Public Utilities Commission

Clinton SRI

J. Arildsen, NRR

B. Brett, SAIC

RILL Rescheske/cg Wheffelt Whillips 12//7/91

1 IDea 12/7 /51 12//9/91

(377) J Lanksbury 12/19/91

REIL 1860 Wright 12/20/91