



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

DEC 13 1991

DCD/DCB
(R105)

Docket No. 50-454
Docket No. 50-455

License No. NPF-37
License No. NPF-66

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Opus West III
1400 Opus Place
Downers Grove, IL 60515

Dear Mr. Reed:

This refers to the routine safety inspection conducted by Messrs. W. J. Kropp and M. J. Miller of this office from December 4 through December 12, 1991. This inspection included a review of activities at the Byron Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Brent Clayton, Chief
Reactor Projects, Branch 1

7201

DEC 13 1991

Commonwealth Edison Company 2

Enclosure:

Inspection Reports

No. 50-454/91028(DRP);

No. 50-455/91028(DRP)

Distribution

cc w/enclosures:

M. Wallace, Vice President,
PWR Operations

T. Kovach, Nuclear
Licensing Manager

T. Schuster, Nuclear Licensing Administrator

R. Pleniewicz, Station Manager

D. Brindle, Regulatory Assurance Supervisor
DCD/DCB (RIDS)

OC/LFDCB

Resident Inspector, RIII Byron, Zion, Braidwood
Richard Hubbard

J. W. McCaffrey, Chief, Public
Utilities Division

Diane Chavez, DAARE/SAFE

A. Hsia, LPM, NRR

Robert Newmann, Office of Public Counsel,
State of Illinois Center