



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401  
Telephone (612) 330-5500

June 1, 1984

Director  
Office of Nuclear Reactor Regulation  
U S Nuclear Regulatory Commission  
Washington, DC 20555


PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket Nos. 50-282 License Nos. DPR-42  
50-306 DPR-60

Unit 1 Inservice Inspection Summary Report

Attached for your review are four copies of the report, "Inservice Inspection - Examination Summary, Prairie Island Nuclear Generating Plant - Unit 1, March 27, 1984 thru March 30, 1984.

This report summarizes the results of inservice inspection examinations performed in response to the NRC Staff Evaluation meeting documented April 18, 1983. Examinations were performed on circumferential pipe welds in portions of the Safety Injection system that were identified as containing stagnant oxygenated borated water, with selection based on those welds that are considered the most susceptible to trans-granular stress corrosion cracking.

The evaluation of the results from the inservice examinations indicated that the integrity of the system has been maintained.

  
David Musolf  
Manager - Nuclear Support Services

DMM/EFE/bd

- c: Regional Administrator-III, NRC (2 copies of attachment)
- NRR Project Manager, NRC (1 copy of attachment)
- Resident Inspector, NRC (w/o attachment)
- G Charnoff (w/o attachment)
- H Baron, Chief Boiler Ins., State of MN (1 copy of attachment)
- S Tack Hartford Ins. (1 copy of attachment)

Attachment

8406050520 840601  
PDR ADOCK 05000282  
G PDR

A047  
1/4