

982

RELATED CORRESPONDENCE

LAW OFFICES OF
BISHOP, LIBERMAN, COOK, PURCELL & REYNOLDS

1200 SEVENTEENTH STREET, N. W.
WASHINGTON, D. C. 20036
(202) 857-9800
TELEX 440574 INTLAW U1

DOCKETED
USNRC

'84 JUN -5 A10:47

IN NEW YORK
BISHOP, LIBERMAN & COOK
26 BROADWAY
NEW YORK NEW YORK 10004
(212) 248-6900
TELEX 222767

DOCKETING & SERVICE
BRANCH

June 2, 1984

Peter B. Bloch, Esquire
Atomic Safety and
Licensing Board
U.S. Nuclear Regulatory
Commission
Washington, D.C. 20555

Dr. Walter H. Jordan
881 West Outer Drive
Oak Ridge, Tennessee 37830

Dr. Kenneth A. McCollom, Dean
Division of Engineering,
Architecture & Technology
Oklahoma State University
Stillwater, Oklahoma 74078

Subj: Texas Utilities Electric Company, et al.
(Comanche Peak Steam Electric Station,
Units 1 and 2; Docket Nos. 50-445 and 50-446

Gentlemen:

Attached hereto are the following:

(1) notarized signature page of Mr. R.D. Wheaton which is page 45 of "Affidavit of J.C. Finneran, R.C. Iotti and R.D. Wheaton Regarding Safety Factors," attached to "Applicants' Motion for Summary Disposition of CASE's Allegations Regarding Safety Factors" filed in this proceeding on May 20, 1984. (Applicants had previously stated that this signature page would be filed under separate cover.)

(2) a correction sheet reflecting several minor corrections to this motion.

Sincerely,

William A. Horin
Counsel for Applicants

8406060089 840602
PDR ADDCK 05000445
PDR

cc: Board and Parties - Overnight Delivery
Remainder of Service List - First Class Mail

DSOS



R. D. Wheaton

Sworn to before me this 22 day of May, 1984.


Notary Public

Corrections to
"Applicants' Motion for Summary Disposition
of CASE's Allegations Regarding Safety Factors"

A. Motion for Summary Disposition

1. Page 4, line 12: change "46" to "40"

B. Attachment 1: Affidavit

1. Page 39, lines 7-9: delete "Applicants have considered the SSE as an emergency load (level C), and that this in itself introduces an additional margin which will be discussed in 4 below."
2. Page 40, lines 16-17: delete "For instance, the SSE is normally considered an emergency load rather than a faulted load."

Page 40, line 17: change "Further" to "For instance"

3. Page 43, Table 2, Cumulative Margin under Item A: change "5.1" to "4.32"
4. Page 43, Table 2, Item D: change "46-47" to "40"

C. Attachment 2: Statement of Material Facts

1. Page 1, Item 2: change "46" to "40"
2. Page 2, Item 2: change "1.8" to "1.18"