0 6/92 (0/2)

Docket No. 50-282 Docket No. 50-306

Northern States Power Company ATTN: Mr. L. R. Eliason Vice President, Nuclear Generation 414 Nicollet Mall Minneapolis, MN 55401

Dear Mr. Eliason:

This refers to the routine safety inspection conducted by P. L. Hartmann, Esquire, Mr. D. C. Kosloff, and others of this office from October 30 through December 23, 1991, of activities at the Prairie Island Nuclear Generating Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-42 and No. DPR-60, and to the discussion of our findings with Mr. M. B. Sellman and other members of your staff at the conclusion of the inspection. This also refers to a routine management meeting conducted at the Region III office on December 19, 1991.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a) of the Commission's regulations, a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

9201160009 920109 PDR ADDCK 05000282

W. D. Shafer, Chief Reactor Projects Branch 2

Enclosure: Inspection Reports No. 50-282/91024(DRP); No. 50-306/91024(DRP)

See Attached Distribution

FORBYWATER JOSES

RIII East Bostorgensen RIII RWD shafer, 1/9/92 GEO!

Distribution

cc w/enclosure:
E. L. Watzl, Site Manager,
Prairie Island Site
M. Sellman, Plant Manager
DCD/DCB (RIDS)
OC/LFDCB
Resident Inspector, RIII Prairie
Island
Resident Inspector, RIII Monticello
John W. Ferman, Ph.D.,
Nuclear Engineer, MPCA
State Liaison Officer, State
of Minnesota
Prairie Island, LPM, NRR
Robert M. Thompson, Administrator
Wisconsin Division of Emergency
Government



NUCLEAR REGULATORY COMMISSION REGION III 759 ROOL CELT ROAD

799 ROOL ELT ROAD GLEN ELLYN, ILLINGIS 60137

JAN 0 9 382

Docket No. 50-282 Docket No. 50-306

Northern States Power Company ATTN: Mr. L. R. Eliason Vice President, Nuclear Generation 414 Nicollet Mall Minneapolis, MN 55401

Dear Mr. Eliason:

This refers to the routine safety inspection conducted by P. L. Hartmann, Esquire, Mr. D. C. Kosloff, and others of this office from October 30 through December 23, 1991, of activities at the Prairie Island Nuclear Generating Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-42 and No. DPR-60, and to the discussion of our findings with Mr. M. B. Sellman and other members of your staff at the conclusion of the inspection. This also refers to a routine management meeting conducted at the Region III office on December 16, 1991.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a) of the Commission's regulations, a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Low W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosure: Inspection Reports

No. 50-282/91024(DRP); No. 50-306/91024(DRP)

See Attached Distribution

Distribution

cc w/enclosure: E. L. Watzl, Site Manager, Prairie Island Site M. Sellman, Plant Manager DCD/DCB (RIDS) OC/LFDCB Resident Inspector, RIII Prairie Island Resident Inspector, RIII Monticello John W. Ferman, Ph.D., Nuclear Engineer, MPCA State Liaison Officer, State of Minnesota Prairie Island, LPM, NRR Robert M. Thompson, Administrator Wisconsin Division of Emergency Government