

Appendix A

NOTICE OF VIOLATION

Union Electric Company

Docket No. 50-483

Based on the investigation conducted April 24-25, 1978, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. This item is a deficiency.

Contrary to 10 CFR 50, Appendix B, Criteria XV, and the Callaway PSAR, Section 17.1.15 and procedure WP-115, an embedment was repaired using heat without proper procedural control of the heat applied.

OFFICE						
SURNAME						
DATE						

NRC Form 318B (R III) (1-78) NRCM 0240

U. S. GOVERNMENT PRINTING OFFICE: 1978-259817

B406070160 B40424
PDR FOIA
GARDEB4-187 PDR