

Reasons for Supporting the PETITION:

(a) To the U.S. Nuclear Regulatory Commission

Contrary to popular belief, the entire nuclear fuel cycle--from mining of uranium to transportation of nuclear materials, to manufacture of nuclear weapons/projectiles/so-called "depleted uranium" armor piercing munitions, to nuclear power plant and nuclear research reactors--~~Do~~^{Do} emit DEADLY RADIOACTIVE CONTAMINANTS TO AIR, SOIL, VEGETATION AND WATER. Further, under "ALARA" principles, one is allowed to release radioactive contaminants to the environment as long as the releases are kept As Low As Reasonably Achievable, i.e., ALARA, depending upon what one wants to spend on containing releases, what available equipment one has and such. In other words, ALARA puts economics above concern for health and the environment. Due to the nature of radiation, such releases under ALARA permit illness, contamination and deaths. The only way to avoid these deaths--which medical nuclear expert Dr. John Gofman calls "planned deaths"--is to have ZERO releases.

THERE IS NO "SAFE" LEVEL OF RADIATION, whether naturally occurring or human made. The so-called "permissible" and "allowable" doses/limits/guidelines/standards are hogwash. They grew out of recommendations made in 1950 by the International Commission on Radiological Protection (ICRP). The ICRP itself had accepted standards agreed upon by nuclear physicists from the Manhattan Project (WWII atomic bomb project) even those these physicists had NO health credentials. Although the ICRP has issued some updates, it persists in the basic views/recommendations "to allow reasonable latitude for the expansion of atomic energy programs"--not to protect health.

Even the NRC admitted in 1978 that there is NO safe level of exposure, a fact that had been known for years. The effects of radiation are cumulative. Any exposure constitutes a threat as ionizing radiation seriously disrupts the chemistry of the cell, leading to later events we may see as lymphoma, leukemia, breast or lung cancer, asthma, spontaneous abortion, heart problems, deformed offspring, sterility, ovarian/reproductive problems, thyroid problems, or death.

Workers in nuclear industries are allowed to be exposed to even higher levels of radiation than the current appalling levels allowed for the general public. Furthermore, as soon as they enter the workplace, such workers are not considered to be "members of the public" anymore by the NRC and industry, so less protection is given.

The deadly effects of Cobalt-60 and Cesium-137 are well known. Cobalt-60's effects on DNA at low exposure are horrendous, let alone the fact that exposure to Co-60 and Ce-137 can kill outright.

Radiation cannot be rendered harmless. It has to decay to its stable state which may take millions of years. Even though many people think that when a radioactive substance has reached its half-life, everything is fine, the term "half-life" is a useless

phrase when it comes to safety. It takes 10 to 20 half-lives, on the average, for something to go through the various stages of radioactive decay to become stable/harmless. A pound of Cesium-137 (with a half-life of approximately 30 years), for example, would only decay to 1/2 pound at the end of 30 years; at the end of 30 more years, 1/4 pound; at the end of yet another 30 years, 1/8 pound, etc.

When radioactive contaminants are dumped to sewers, they wind up often eventually wind up in drinking water, having contaminated sewer lines, treatment plants, sewage sludges and creeks/streams en route to drinking water intake plants. The result is a major public health problem in which people are exposed daily to yet another cumulative dose of radiation.

(b) To the Agency for Toxic Substances and Disease Registry (ATSDR)

As guardian of the public's health, ATSDR MUST INTERVENE and insure that the requests in this petition to NRC are honored and implemented.

While not much can be done about naturally occurring background radiation to which we are all exposed and which in turn causes health problems, aging, etc., ZERO exposure to radiation from all man-made/induced activities is a must. The latter source of exposure can be eliminated to a great extent.

(c) In General

U.S. nuclear guidelines are generally adopted/followed worldwide. Stupidity on this issue has already spread because the press and public generally bought into all the hogwash, believed they were being protected and asked few questions. Above and below ground (with vents) nuclear testing by the U.S., Russia, China, Britain, France and others have saturated much of this earth with fallout, causing approximately 6 million cancer deaths worldwide by 1963 (when above ground tests stopped). These cancer deaths would not have otherwise occurred according to former Soviet dissident/nuclear scientist Andrei Sakharov. Millions more have died since.

We do not need any additional exposure. Remember, radiation is unsafe at any level. (Suggested reading: No Immediate Danger: Prognosis for a Radioactive Earth by Dr. Rosalie Bertell.)

.

Thank you for your support of this petition. Please distribute unsigned copies of it to friends (by mail, fax, on Internet) and then make three copies of your completed petition (all 3 pages) and mail to:

- (1) The Executive Director, U.S. Nuclear Regulatory Commission, Washington, D.C. 20555-0001
- (2) Petitioned Health Assessment Co-ordinator, John Steward, Agency for Toxic Substances and Disease Registry, 1600 Clifton Rd., N.E. (E-28), Atlanta, Georgia 30333
- (3) Pamela Blockey-O'Brien, I.F.O.R., c/o D23 Golden Valley, Douglasville, Georgia 30134.