



84 MAY 29 AIO: 46 Carolina Power & Light Company

P. O. Box 101, New Hill, N. C. 27562
May 22, 1984

Mr. James P. O'Reilly
United States Nuclear Regulatory Commission
Region II
101 Marietta Street, Northwest (Suite 2900)
Atlanta, Georgia 30303

NRC-218

CAROLINA POWER & LIGHT COMPANY
SHEARON HARRIS NUCLEAR POWER PLANT
1986 - 900,000 KW - UNIT 1
**WELDING DEFICIENCIES ON CLASS IE 6.9 KV
CIRCUIT BREAKERS - ITEM II7**

Dear Mr. O'Reilly:

Attached is Addendum No. 1 to the Final 10CFR50.55(e) and 10CFR, Part 21 Report issued to the NRC on March 29, 1984 for the above subject deficiency. This addendum clarifies our corrective action concerning site QA inspections.

If you have any questions regarding this matter, please contact me.

Yours very truly,

R. M. Parsons
Project General Manager
Shearon Harris Nuclear Power Plant

RMP/sh

Attachment

cc: Messrs. G. Maxwell/R. Prevatte (NRC-SHNPP)
Mr. R. C. DeYoung (NRC)

8406110211 840522
PDR ADOCK 05000400
S PDR

OFFICIAL COPY

IE 27

**SHEARON HARRIS NUCLEAR POWER PLANT
UNIT 1**

**WELDING DEFICIENCIES ON CLASS 1E
6.9 KV CIRCUIT BREAKERS**

**ADDENDUM NO. 1 TO FINAL REPORT - ITEM II7
ISSUED MARCH 29, 1984**

MAY 17, 1984

Under **Corrective Action**, paragraph 1, the second sentence should be changed to read as follows:

Items received on site will be inspected by Site QA with the exception of those supplied by vendors which have established a high confidence level as to adherence to procurement documents.