

DMB

JUN 07 1984

Docket No. 50-315
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

Enclosed for your review, prior to our scheduled meeting of June 21, 1984, is the SALP Board Report for the D. C. Cook Nuclear Plant, covering the period April 1, 1983 through March 31, 1984.

In considering your performance during this period the SALP Board took under consideration the negative impact that moving your corporate headquarters had on your efforts to improve your performance since the last SALP period. This was demonstrated by your inability to implement the Regulatory Performance Improvement Program until January 1984 when aggressive corporate and site action was observed in most areas. In arriving at the results of this SALP assessment, more weight was placed on the improvements observed in this latter period.

Overall, during this period, your performance was found to be acceptable and generally showed an improving trend. It was noted that many past problems could be attributed to poor followup on identified deficiencies and failure to meet commitments. In most cases, your recent actions on resolution of past problems has been responsive and comprehensive.

Performance in the area of Quality Programs and Administrative Controls, while displaying an improving trend, has not appreciably improved since the last two SALP periods, and additional effort should be devoted to these areas.

While you will have sufficient opportunity to present your comments at the meeting on June 21, 1984, we also solicit written comments within 30 days after the meeting to enable us to thoroughly evaluate your comments and provide you with our conclusions relative to them.

In accordance with Section 2.790 of NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the SALP Report will be placed in the NRC's Public Document Room.

8406120108 840607
PDR ADDCK 05000315
G PDR

1E0111

American Electric Power Service
Corporation

2

JUN 07 1984

No reply to this letter is required at this time; however, should you have any questions concerning the SALP report, we would be pleased to discuss them with you.

Sincerely,

"Original Signed by James G. Keppler"

James G. Keppler
Regional Administrator

Enclosure: SALP Report
No. 50-315/84-08; 50-316/84-09

cc w/encl:
W. G. Smith, Jr., Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
R. C. DeYoung, IE
H. R. Denton, NRR
INPO
Regional Administrators
RI, RII, RIV, RV

RIII

Shaffer/ld
05/04/84

RIII

Tambling
6/6/84

RIII

Norellus

RIII

Spessard
6/6

RIII

Hind
6/6/84

RIII

Davis

RIII

Keppler
6/6/84