

JAN 24 1992

DOCUMENT CONTAINS  
SAFEGUARDS INFORMATION

Docket Nos. 50-445  
50-446  
License No. NPF-87  
Construction Permit No. CPPR-127

TU Electric  
ATTN: W. J. Cahill, Jr., Executive  
Vice President, Nuclear  
Skyway Tower  
400 North Olive Street, L.B. 81  
Dallas, Texas 75201

DOCUMENT CONTAINS  
SAFEGUARDS INFORMATION

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-445/91-68, 50-446/91-68

This refers to the inspection conducted by Mr. B. Earnest of this office on December 9-12, 1991. The inspection included a review of activities authorized for your Comanche Peak Steam Electric Station. At the conclusion of the inspection, the findings were discussed with Mr. Kelley and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. These areas included selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, one of your activities appeared to be in violation of NRC requirements. This violation is discussed in paragraph 4 of the enclosed inspection report. In accordance with the criteria in Section V.G.1. of NRC's Enforcement Policy, a citation will not be issued for the violation because of the minor significance and several mitigating factors.

We are concerned about the significant increase in security infractions identified during the 1991 refueling outage. Your staff had identified the increase in security infractions as a concern prior to the inspection and indicated that they are currently devising means to reduce the number of infractions prior to the next refueling outage.

We have also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 2 of the enclosed report.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR Part 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will not be placed in the Public Document Room.

RIV:FIPS C:FIPS  
\*BEarnest:nh \*BMurray  
/ /92 / /92  
\*Previously concurred.

D:DRSS  
LJCallan  
1/14/92

D:DRP  
ABBeach  
1/24/92

ZE-04

DOCUMENT CONTAINS  
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION  
UPON SEPARATION THIS  
PAGE IS DECONTROLLED

000012  
9201310015 920124  
PDR ADDOCK 05000445  
Q PDR

JAN 24 1992

Docket Nos. 50-445  
50-446  
License No. NPF-87  
Construction Permit No. CPPR-127

DOCUMENT CONTAINS  
SAFEGUARDS INFORMATION

TU Electric  
ATTN: W. J. Cahill, Jr., Executive  
Vice President, Nuclear  
Skyway Tower  
400 North Olive Street, L.B. 81  
Dallas, Texas 75201

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-445/91-68, 50-446/91-68

This refers to the inspection conducted by Mr. B. Earnest of this office on December 9-12, 1991. The inspection included a review of activities authorized for your Comanche Peak Steam Electric Station. At the conclusion of the inspection, the findings were discussed with Mr. Kelley and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. These areas included selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, one of your activities appeared to be in violation of NRC requirements. This violation is discussed in paragraph 4 of the enclosed inspection report. In accordance with the criteria in Section V.G.1. of NRC's Enforcement Policy, a citation will not be issued for the violation because of the minor significance and several mitigating factors.

We are concerned about the significant increase in security infractions identified during the 1991 refueling outage. Your staff had identified the increase in security infractions as a concern prior to the inspection and is currently devising means to reduce the number of infractions prior to the next refueling outage.

We have also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 2 of the enclosed report.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR Part 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will not be placed in the Public Document Room

RI:FIPS  
\*BEarnest:nh  
/ /92

C:FIPS  
\*BMurray  
/ /92

D:DRSS  
LJCallan  
/ /92

D:DRP  
ABBeach  
/ /92

\*Previously concurred.

**PREVIOUS CONCURRENCE PAGE**

DOCUMENT CONTAINS  
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION  
UPON SEPARATION THIS  
PAGE IS DECONTROLLED

JAN 24 1992

Docket Nos. 50-445  
50-446  
License No. NPF-87  
Construction Permit No. CPPR-127

DOCUMENT CONTAINS  
SAFEGUARDS INFORMATION

TU Electric  
ATTN: W. J. Cahill, Jr. Executive  
Vice President, Nuclear  
Skyway Tower  
400 North Olive Street, L.B. 81  
Dallas, Texas 75201

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-445/91-68, 50-446/91-68

This refers to the inspection conducted by Mr. B. Earnest of this office on December 9-12, 1991. The inspection included a review of activities authorized for your Comanche Peak Steam Electric Station. At the conclusion of the inspection, the findings were discussed with Mr. Kelley and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. These areas included selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, one of your activities appeared to be in violation of NRC requirements. This violation is discussed in paragraph 4 of the enclosed inspection report. In accordance with the criteria in Section V.G.1. of NRC's Enforcement Policy, a citation will not be issued for the violation because of the minor significance and several mitigating factors.

We are concerned about the significant increase in security infractions identified during the 1991 refueling outage. Your staff had identified the increase in security infractions as a concern prior to the inspection and are currently devising means to reduce the number of infractions prior to the next refueling outage.

We have also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 2 of the enclosed report.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR Part 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will not be placed in the Public Document Room.

RIV:FIPS  
BEarnest:nh  
1/17/92

C:FIPS  
BMurray  
1/17/92

D:DRSS  
LJCallan  
1/17/91

D:DRP  
ABBeach  
1/17/91

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION  
UPON SEPARATION THIS  
PAGE IS DECONTROLLED

DOCUMENT CONTAINS  
SAFEGUARDS INFORMATION

PREVIOUS CONCURRENCE PAGE

JAN 24 1992

DOCUMENT CONTAINS  
SAFEGUARDS INFORMATION

Docket Nos. 50-445  
50-446  
License No. NPF-87  
Construction Permit No. CPPR-127

TU Electric  
ATTN: W. J. Cahill, Jr., Executive  
Vice President, Nuclear  
Skyway Tower  
400 North Olive Street, L.S. 81  
Dallas, Texas 75201

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-445/91-68, 50-446/91-68

This refers to the inspection conducted by Mr. B. Earnest of this office on December 9-12, 1991. The inspection included a review of activities authorized for your Comanche Peak Steam Electric Station. At the conclusion of the inspection, the findings were discussed with Mr. Kelley and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. These included selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

Based on the results of this inspection, one of your activities appeared to be in violation of NRC requirements. This violation is discussed in paragraph 4 of the enclosed inspection report. In accordance with the criteria in Section V.A. of NRC's Enforcement Policy a citation will not be issued for the violation because of the minor significance and several mitigating factors.

We are concerned about the significant increase in security infractions identified during the 1991 refueling outage. Your staff had identified the increase in security infractions as a concern prior to the inspection and are currently devising means to reduce the number of infractions prior to the next refueling outage.

We have also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 2 of the enclosed report.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR Part 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will not be placed in the Public Document Room.

RIV: [Signature]  
BE: [Signature]  
12/31/91

C:FIPS  
BMurray  
/ /91

D:DRSS  
LJCallan  
/ /91

D:DRP  
ABBeach  
/ /91

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION  
UPON SEPARATION THIS  
PAGE IS DECONTAMINATED

DOCUMENT CONTAINS  
SAFEGUARDS INFORMATION

PREVIOUS CONCURRENCE PAGE



TU Electric

-2-

JAN 24 1992

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original signed by

A. Bill Beach, Director  
Division of Reactor Projects

Enclosure: w/summary page only  
Appendix - NRC Inspection Report  
50-445/91-68  
50-446/91-68

cc w/enclosure:  
TU Electric  
ATTN: Roger D. Walker, Manager  
Nuclear Licensing  
Skyway Tower  
400 North Olive Street, L.B. 81  
Dallas, Texas 75201

Juanita Ellis  
President - CASE  
1426 South Polk Street  
Dallas, Texas 75224

GDS Associates, Inc.  
Suite 720  
1850 Parkway Place  
Marietta, Georgia 30067-8237

TU Electric  
Bethesda Licensing  
3 Metro Center, Suite 610  
Bethesda, Maryland 20814

Jorden, Schulte, and Burchette  
ATTN: William A. Burchette, Esq.  
Counsel for Tex-La Electric  
Cooperative of Texas  
1025 Thomas Jefferson St., N.W.  
Washington, D.C. 20007

JAN 24 1992

Newman & Holtzinger, P.C.  
ATTN: Jack R. Newman, Esq.  
1615 L. Street, N.W.  
Suite 1000  
Washington, D.C. 20036

Texas Department of Labor & Standards  
ATTN: G. R. Bynog, Program Manager/  
Chief Inspector  
Boiler Division  
P.O. Box 12157, Capitol Station  
Austin, Texas 78711

Honorable Dale McPherson  
County Judge  
P.O. Box 851  
Glen Rose, Texas 76043

Texas Radiation Control Program Director  
1100 West 49th Street  
Austin, Texas 78756

Owen L. Thero, President  
Quality Technology Company  
Lakeview Mobile Home Park, Lot 35  
4793 E. Loop 820 South  
Fort Worth, Texas 76119

bcc copy of entire report:  
RIV Security File  
Elaine Koup, RSGB/NRR (9D24)  
R. D. Martin, RA  
B. Murray, FIPS  
Resident Inspector  
Security File  
G. F. Sanborn, EO

bcc copy of letter and inspection summary only:  
DMB IE-04                      DRS  
DRP                              Lisa Shea (4503)  
Project Engineer, DRP/B        RIV File  
MIS                              RSTS Operator  
Division Director, DRP M. Fields, NRR Project Manager  
J. Wilson, NRR Project Manager