NRC Form (9-83)	9-83)														APPR	APPROVED OMB NO. 3150-0104 EXPIRES 8/31/85					
FACILITY	ACILITY NAME (1)														DOCK	DOCKET NUMBER (2) PAGE					
Sequoyah, Unit 1															0 15 10 10				1 0	F 0 1 2	
TITLE 14		,	-				-		-									1	1		
Re	acto	r T	rii	,																	
EVENT DATE (6) LER NUMBER (6)										REPORT DATE (7) OTHE					R FACILITIES INVOLVED (8)						
MONTH	ONTH DAY		AR	YEAR	R I		ENTIAL REVISION			MONTH	DAY	YEAR	FACILITY NAMES				DO	DOCKET NUMBER(S)			
		-	+		-	1 70	MBCH	NUMBER	MBER		-					0	0 5 0 0 0 1 1				
																	+				
0 5	1 1	8	4	8 4	4 -	0	3 3	- 0	0	0 6	0 5	8 4					0	151010	101	1.1	
OPE	RATING			THIS	REPORT	r IS SL	BMITTE	D PURSU	ANT	TO THE R	EQUIREN	ENTS OF 1	0 CFR & /	Check one or more	of the	fallowing)	_			•	
MODE (9)					20.402(b)				T	20.406	e)		X 50.73(a)(2)(iv)			T	73.71(b)				
POWER					20.405(a)(1)(i)					60.38(c)(1)				50.73(a)(2)(v)				73.71(c)			
(10) 012 II					20.405(a)(1)(ii)					50.36(c)	(2)			50.73(a)(2)(vii) OTHER (Specify in Abstract below and in Text. NRC Fo					betract		
			20.406(a)(1)(iii)					60.73(a)(2)(i)				50.73(e)(2)(viii)(A)				366A)					
		[20.405(a)(1)(iv)						80.73(a)	(2)(ii)		80.73(a)(2)(viii)(B)									
				20.408(a)(1)(v)					50.73(a)	(2)(iii)		50.73(a)(2)(x)									
									L	ICENSEE	CONTACT	FUR THIS	LER (12)								
NAME															TELEPHONE NUMBER						
0.1		0	Dr. d. s	-1-	0					- V1					A	REA COD					
Glenn B. Kirk, Compliance Section									110	n Engineer						6,1,5 8,7,0,-,6,1,4,6					
		_				CON	APLETE	ONE LIN	E FOR	EACH CO	MPONEN	T FAILURE	DESCRIBE	D IN THIS REPO	RT (13	1					
CAUSE	SYSTEM	СОМРО		ONENT		MANUFAC TURER		REPORTABLE TO NPRDS					SYSTEM	COMPONENT		MANUFAC- TURER		REPORTABLE TO NPRDS			
												-	-		-			TO MENUS			
X	S _I B	F	Cı	Vı.	- 0	161	3 1 5	Y													
			_		-	-			-				-		+		-				
	1		1	-1		1 1							1	111		1 1					
			_			SU	PPLEME	NTAL RI	PORT	EXPECTE	D (14)				+-			MONT	H DAY	YEAR	
													EXPECTED SUBMISSION								
YE	S Iff yes, c	omple	to EX	PECT	ED SUB	MISSIC	N DATE	1		X	NO					DATE (16)			1	1	
ASSTRAC	T (Limit	to 140	10 spe	000, 1.0	**********	ximatel	y fifteen	single spe	ce type	ewritten lin	es/ (16)				-		-				

During a normal startup on 05/11/84 at 1400 CST, unit 1 experienced an automatic reactor trip on low-low level in the number 2 steam generator following a turbine trip. Just prior to the event, unit 1 was in mode 1 (554 degrees F, 2235 psig) at 21% reactor power.

1622 1/1

During a normal reactor startup following a reactor trip on 05/10/84 (see SQRO-50-327/84032), unit 1 experienced another reactor trip. Just prior to the event which occurred at 1400 CST on 05/11/84, unit 1 was in mode 1 (554 degrees F, 2235 psig) at

21% reactor power with steam generator level controls in manual.

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Steam dump valve 1-FCV-1-107 spuriously opened resulting in swell of steam generator levels. This action resulted in a high-high level in the number 3 steam generator which caused a turbine trip and main feedwater isolation to all four steam generators. The transient then resulted in shrink of steam generator levels causing a reactor trip on low-low level in steam generator number 2. All equipment and personnel responded as expected and the unit stabilized at 547 degrees F.

Inspection revealed a broken repositioning linkage on steam dump valve 1-FCV-1-107 allowing the valve to cycle erratically. The repositioning linkage was replaced and the valve was returned to service.

There was no effect on public health or safety. For 1984, this was the sixth automatic reactor trip on low-low steam generator level and the second event initiated by the opening of a steam dump valve.

TENNESSEE VALLEY AUTHORITY

Sequoyah Nuclear Plant Post Office Box 2000 Soddy Daisy, Tennessee 37379

June 5, 1984

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE REPORT SQRO-50-327/84033

The enclosed licensee event report provides details concerning a reactor trip from 21% reactor power. This event is reported in accordance with 10 CFR 50.73, paragraph a.2.iv.

Very truly yours,

O.R. Walla

TENNESSEE VALLEY AUTHORITY

✓C. C. Mason

Power Plant Superintendent

Enclosure cc (Enclosure):

> James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Suite 2900 101 Marietta Street, NW Atlanta, Georgia 30303

Records Center Institute of Nuclear Power Operations Suite 1500 1100 Circle 75 Parkway Atlanta, Georgia 30339

NRC Inspector, NUC PR, Sequoyah