



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION I
475 ALLENDALE ROAD
KING OF PRUSSIA, PENNSYLVANIA 19406-1415

NOV 06 1991

Docket Number: 50-336

Northeast Nuclear Energy Company
ATTN: Mr. John F. Opeka
Executive Vice President - Nuclear
Engineering and Operations Group


P.O. Box 270
Hartford, Connecticut 06141-0270

Dear Mr. Opeka:

Thank you for informing us of the results of your reviews of the concerns listed in the enclosed table. We have performed verification inspections on selected issues, find your responses generally acceptable, and plan no further actions on these issues at this time. This is not to say that further independent reviews of these issues will not take place in the future. You will be kept informed of such verification inspections and independent reviews by the normal inspection report process.

A copy of this letter as well as the referenced correspondence is being placed in the Public Document Rooms and sent to the State of Connecticut. We appreciate your cooperation in these matters.

Sincerely,


Edward Wenzinger, Chief
Reactor Projects Branch-4

Enclosure: Table of NU's Response:

cc w/encl:

Public Document Room (PDR)
Local Public Document Room (LPDR)
State of Connecticut

9202040081 911106
PDR ADOCK 05000336
P FDR

4005 1/1

ENCLOSURE

NRC NUMBER	NU RESPONSE	RESPONSE DATE	SUBJECT OF ISSUE
91-070-1 91-070-3B	A09805	09/27/91	NO PLANT INCIDENT REPORT FOR "D" CIRCULATION PUMP TRIP MOTOR HEATER, WERE NOT ENERGIZED ON SPARE BORIC ACID PUMP
91-079	A09768	09/27/91	GAMMA METRICS PROCEDURES
91-113N & 91-136 91-114-1 91-114-2 91-116 91-122 91-128 91-129 91-130	A05699	09/13/91	ABNORMAL STACK RADIATION MONITOR INDICATION REPETITIVE FAILURES OF VENT STACK HIGH RANGE MONITOR ACCUMULATOR TANK LEVEL CALIBRATION ERROR INADEQUATE RWP/HP CONTROLS CLEAN LIQUID RADIATION MONITOR TAGGING ERROR OUT OF SERVICE STACK MONITOR IMPROPER ASSIGNMENT OF ON-CALL I&C TECHNICIAN VOLUME CONTROL TANK LEVEL EVOLUTION WRONG PART FOR LOCAL PRESSURE GAGE
91-162	A09698	09/09/91	UNCALIBRATED/UNLABELED EXHAUST VENTILATION DUCT MANOMETER
91-163	A09819	09/27/91	WIDE RANGE NUCLEAR INSTRUMENT UNDOCUMENTED SWITCHES
91-165-1 91-165-2	A09703	09/09/91	UNLABELED CRYOGENIC LIQUID NITROGEN CONVERTER VALVES PERMANENTLY CONNECTED - NOT DEPICTED PUMP
91-166	A09701	09/13/91	RECOVERY BORIC ACID TANK PUMP ISOLATED SWITCH

91-170-1	A09807	10/03/91	CALIBRATION OF WIDE RANGE NUCLEAR INSTRUMENT PROCEDURE PROBLEM
91-170-2			WIDE RANGE INSTRUMENT CALIBRATIONS NOT DONE
91-171	A09806	10/03/91	MAIN EXHAUST FAN PM
91-172	A09755	09/13/91	ENERGIZED AIR EJECTOR FAN AUXILIARY CONTACTS
91-173			ALLEGED INADEQUATE STATOR COOLING PUMP ELECTRICAL BOUNDARIES
91-183-5	A09803	09/30/91	ALLEGED INADEQUATE PORC REVIEWS
91-183-7			DISABLED WASTE NEUTRALIZER RADIATION MONITOR
91-210-1	A09829	09/30/91	UNLABELED TURBINE SAMPLING VALVES
91-210-2			NO MODIFICATION PACKAGE FOR MAIN GENERATOR HYDROGEN MONITOR CHANGES
91-229	A09850	10/03/91	GROUND PROTECTION FOR "B" SERVICE WATER PUMP