

James A. FitzPatrick  
Nuclear Power Plant  
P.O. Box 41  
Lycoming, New York 13093  
315 342 3840



**New York Power  
Authority**

Harry P. Salmon, Jr.  
Site Executive Officer

August 29, 1995  
JAFP-95-0390

United States Nuclear Regulatory Commission  
Document Control Desk  
Mail Station P1-137  
Washington, D.C. 20555


SUBJECT: DOCKET NO. 50-333  
LICENSEE EVENT REPORT: LER-95-006-01:  
  
Reactor Safety Relief Valve Setpoint Drift

Dear Sir:

This report is submitted in accordance with 10CFR50.73  
(a)(2)(i).

This supplement provides the results of an analysis performed on the as-found actuation pressures of eleven safety relief valves removed and tested during the 1994/1995 refueling outage. The analysis was performed to determine the margin to the reactor vessel pressure safety limit based on these as-found actuation pressures. Questions concerning this report may be addressed to Mr. Gordon Brownell at (315) 349-6360.

Very truly yours,

  
HARRY P. SALMON, JR.

HPS:GJB:tlc

Enclosure

cc: USNRC, Region I  
USNRC Resident Inspector  
INPO Records Center

66007  
9509070222 950829  
PDR ADOCK 05000333  
S PDR

IE22  
11