

PCST OFFICE BOX 2351 + BEAUMONT, TEXAS 77704

AREA CODE 713 838 6631

June 4, 1984 RBG- 17987 File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator U. S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011



Dear Mr. Collins:

River Bend Station Unit 1 Docket No. 50-458 Interim Report/DR-174

An interim or final status report concerning skewed angle joint fillet welds supplied by Reactor Controls, Incorporated will be provided by August 30, 1984.

Sincerely,

L. G. England for

J. E. Booker Manager-Engineering, Nuclear Fuels & Licensing

JEB/2D/df

cc: Director of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D.C. 20555

NRC Resident Inspector - Site

8406180222 840604 PDR ADDCK 05000450 S PLA 12-271/0