



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 9023, 1994
ARLINGTON, TEXAS 76011-8064

MEMORANDUM FOR: Distribution

FROM: Samuel J. Collins, South Texas Project (STP)
Restart Panel Chairman

SUBJECT: STP RESTART PANEL MEETING NOTES

Attached are the Meeting Notes for the STP Restart Panel Meeting conducted on February 14, 1994, at the South Texas Project site.

Original Signed By:
/s/

Samuel J. Collins
Panel Chairman

cc (E-Mail):

J. Callan	J. Montgomery
P. Gwynn	A. Howell
D. Chamberlain	W. Johnson
D. Loveless	S. Black
L. Kokajko	B. Beach
C. Hackney	J. Gilliland
G. Sanborn	R. Wise
M. Satorius	

cc:
C. Sudman

RIV:C:DRP/A
WDJohnson;df
2/ /94

ADD:DRP
ATHowell
2/ /94

RPC
SJCollins
2/ /94

STP REVIEW PANEL

MEETING NOTES - FEBRUARY 14, 1994

ATTENDEES

- J. Callan, Regional Administrator
- # S. Collins, Panel Chairman
- # S. Black, Director, Project Directorate IV-2, NRR
- # L. Kokajko, Senior Project Manager, NRR
- # A. Howell, Deputy Director, DRP
- # W. Johnson, Chief, Project Section A
- # D. Loveless, Senior Resident Inspector

Panel Members

PANEL SUBJECTS

- NRC Restart Approval Process, Concurrences, and Notifications

This was a brief meeting held at the site following the licensee's presentation on the resolution status of the restart issues listed in the Confirmatory Action Letter of February 5, 1993, and its two supplements. The panel members agreed that, pending the successful completion of main feedwater isolation valve bypass valve testing and verification of completion of the worker and supervisor briefings on management expectations regarding work practices, the licensee had resolved the restart issues. The Panel recommended that the Regional Administrator concur in the restart of Unit 1 after the licensee completes these two items.

- Review Status of Panel Action Items

Items from past meetings:

- DRP will prepare four inspection reports to assign tracking numbers to DET items which are not considered to be restart issues. Reports 9348 through 9351, one for each DET functional inspection area, will list DET findings which are not restart issues. They are under preparation.
- Perform an internal audit of the RIV STP Restart File - Panel
- D. Loveless will verify licensee completion of ORAT commitments as listed in the quick look letter. On 2/14, the only item remaining is the management expectation briefings of workers and supervisors regarding work practices.
- D. Loveless will monitor licensee completion of internal commitments for standby diesel generators.

- (Closed) B. Johnson will set up a conference call with the licensee to discuss clearance order, test coordination, and heat exchanger leakage problems and the potential impact on the plant's readiness for startup.

New Item:

- D. Loveless will verify completion of MFIV bypass valve postmodification testing.



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

February 23, 1994

MEMORANDUM FOR: Distribution

FROM: Samuel J. Collins, South Texas Project (STP)
Restart Panel Chairman

SUBJECT: STP RESTART PANEL MEETING NOTES

Attached are the Meeting Notes for the STP Restart Panel Meeting conducted on February 15, 1994, in the NRC RIV office.

Original Signed By:
/s/

Samuel J. Collins
Panel Chairman

cc (E-Mail):

J. Callan	J. Montgomery
P. Gwynn	A. Howell
D. Chamberlain	W. Johnson
D. Loveless	S. Black
L. Kokajko	B. Beach
C. Hackney	J. Gilliland
G. Sanborn	R. Wise
M. Satorius	

cc:
C. Sudman

RIV:C:DRP/A
WDJohnson;df
2/ /94

ADD:DRP
ATHowell
2/ /94

RPC
SJCollins
2/ /94

STP REVIEW PANEL

MEETING NOTES - FEBRUARY 15, 1994

ATTENDEES

- # S. Collins, Panel Chairman
- # A. Howell, Deputy Director, DRP
- #* W. Johnson, Chief, Project Branch A
 - M. Satorius, Project Engineer
 - C. Hackney, Regional State Liaison Officer
 - J. Gilliland, Public Affairs Officer

- # Panel Members
- * Participated by telecon

PANEL SUBJECTS

- NRC Restart Approval Process, Concurrences, and Notifications

The panel reviewed the open items requiring confirmation following the public meeting on February 14, 1994. Both the valve testing and the worker training items had been completed. The Panel reviewed a draft memo to the Regional Administrator and a draft CAL closure letter. The panel members agreed that the licensee had satisfactorily resolved the restart issues for Unit 1. The Panel reviewed the Restart Action Plan. The Panel Chairman provided a marked-up Revision 3 which will be used for Revision 4.

- Review Status of Panel Action Items

items from past meetings:

- DRP will prepare four inspection reports to assign tracking numbers to DET items which are not considered to be restart issues. Reports 9348 through 9351, one for each DET functional inspection area, will list DET findings which are not restart issues. They are under preparation.
- Perform an internal audit of the RIV STP Restart File - Panel
- (Closed) D. Loveless will verify licensee completion of ORAT commitments as listed in the quick look letter. On 2/14, the only item remaining is the management expectation briefings of workers and supervisors regarding work practices.
- D. Loveless will monitor licensee completion of internal commitments for standby diesel generators.
- (Closed) D. Loveless will verify completion of MFIV bypass valve postmodification testing.

New Items:

- DRP will revise the augmented restart coverage plan to include discussion of an NRC staff assessment of licensee performance at about the 50 percent and 100 percent plateaus.