

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

June 18, 1984
BECO 84-085

Mr. Domenic B. Vassallo, Chief
Operating Reactors Branch #2
Division of Licensing
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

License No. DPR-35
Docket No. 50-293

1984 Core Spray Sparger Visual Examination

Dear Sir:

As required by NRC IE Bulletin 80-13 and our letter to yourself dated August 4, 1983, we have performed a visual examination of the core spray spargers and associated piping inside the reactor pressure vessel at the Pilgrim Nuclear Power Station during the current refueling outage. The examination revealed no apparent change in the conditions reported during the 1981 examinations and no other areas of concern were identified. The attached final report of this visual examination is provided for your review.

Very truly yours,

W.D. Harrington

DMV/kmc

Attachment: 1984 Remote Visual Examination of the Core Spray Sparger System of Pilgrim Nuclear Power Station, Unit 1, Final Report, dated May 1984

cc: Regional Administrator, Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Director
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

*Abol
1/1*

8406210318 840618
PDR ADDCK 05000293
Q PDR