



GE Nuclear Energy

DRF A12-00061

# GENERAL ELECTRIC COMPANY PROPRIETARY INFORMATION

Commonwealth Edison Company  
Dresden Nuclear Power Station, Units 2 & 3

## Primary Structure Seismic Models

December 1994

Prepared By: D.K. Henrie  
D.K. Henrie, Project Manager  
Quad Cities 1 & 2, Seismic Model Generation

Verified By: J.A. Muse Sr  
J.A. Muse, Engineer  
Engineering and Licensing Consulting Services

Approved By: S. Ranganath  
S. Ranganath, Projects Manager  
Engineering and Licensing Consulting Services

Dresden Units 2 and 3 - Primary Structure Seismic Models



# GENERAL ELECTRIC COMPANY PROPRIETARY INFORMATION

## PROPRIETARY INFORMATION NOTICE

*This document contains proprietary information of the General Electric Company (GE) and is furnished to Commonwealth Edison Company, in confidence solely for the purpose or purposes stated in the purchase order between Commonwealth Edison Company and GE. Commonwealth Edison Company shall not publish or otherwise disclose this document or the information to others without the written consent of GE except as provided in such purchase order and shall return this document at the request of GE.*

### IMPORTANT NOTICE REGARDING CONTENTS OF THIS REPORT

Please Read Carefully

*The only undertaking of the General Electric Company (GE) respecting information in this document are contained in the purchase order between Commonwealth Edison Company and GE, and nothing contained in this document shall be construed as changing the purchase order. The use of this information by anyone other than Commonwealth Edison Company, or for any purpose other than that for which it is intended under such purchase order is not authorized; and with respect to any unauthorized use, GE makes no representation or warranty, and assumes no liability as to the completeness, accuracy, or usefulness of the information contained in this document, or that its use may not infringe privately owned rights.*



Table of Contents

<u>Section</u>	<u>Page No.</u>
1.0 Introduction	1
2.0 Purpose and Scope	2
3.0 Seismic Models	2
4.0 Baseline Model Analysis & Results	4
5.0 References	6
Appendix A - Figures	A1
Appendix B - Tables	B1
Appendix C - SAPG07 Input Geometry Listings for N-S and E-W Seismic Models	C1

**GENERAL ELECTRIC COMPANY  
PROPRIETARY INFORMATION**



## 1.0 INTRODUCTION

The licensing basis seismic design adequacy evaluations for the Dresden Nuclear Power Station, Units 2 and 3 primary structures were completed in the late nineteen sixties and early nineteen seventies. The primary structure seismic models utilized in the original evaluations are referred to as the "benchmark" seismic models in this report and are discussed in Section 3.0 below. The seismic models reconstructed for this report, from the benchmark models, are referred to as "regenerated baseline" seismic models in this report.

In recent years, both the NRC staff and the nuclear industry have identified as a technical issue of concern the Intergranular Stress Corrosion Cracking (IGSCC) of Boiling Water Reactor (BWR) internal components, Reference 5.7. The core shroud has been found to be prominent among the internal components susceptible to IGSCC. Subsequent inspections at Quad Cities Unit 1 and Dresden Unit 3 revealed significant cracking at the core shroud circumferential welds. Due to the 360° extent of the cracking, and at lower elevations where extensive cracking had not been previously observed, the inspections and related analyses (References 5.8 and 5.9) performed in the Spring of 1994 for Dresden Unit 3 and Quad Cities Unit 1 were especially noteworthy.

The analytical evaluations corresponding to References 5.8 and 5.9 were conducted to demonstrate that, without any shroud repair, the fuel control rods could be readily inserted and the reactor brought to a safe shut-down condition regardless of the extent of the cracking at the core shroud circumferential welds. This allowed continue operation of the reactor until the next planned fuel outage, at which time appropriate shroud repairs could be most favorably implemented.

Conceptually, the shroud repair to be implemented at Dresden corresponds to the installation of a shroud-to-vessel stabilizer assembly. The shroud stabilizer assembly is comprised of: (i) two sets of linearly elastic, lateral, stabilizer springs between the shroud and the vessel (the first set is located at the top guide elevation and the second set at the core support plate elevation) in conjunction with (ii) a set of vertical tie rods between the upper shroud flange and the lower shroud support plate which structurally connects the shroud to the RPV.

In order to generate loads for the design adequacy evaluation of the shroud repair hardware, it is necessary to reconstruct the primary structure seismic models used in the licensing basis seismic design adequacy evaluation for Dresden Units 2 and 3. Furthermore, the introduction of the shroud-to-vessel stabilizer assembly and the extent of cracking at the shroud circumferential welds will significantly change the eigen (dynamic)

Enclosure 16

GENE Letter, M. D. Potter - GE Shroud Project Engineer to Kenneth Hutko -  
ComEd Shroud Project Engineer,  
Performance impact of shroud repair leakage for Dresden Units 2 & 3, dated  
May 18, 1995 (B13-01749, MDP-9536)



May 18, 1995

General Electric Company  
175 Curtner Avenue, San Jose, CA 95125

cc: R. Svarney  
E. R. Mohtashemi  
B13-01749  
MDP-9536

To: Kenneth Hutko  
ComEd Shroud Project Engineer

From: M. D. Potter *M. D. Potter*  
GE Shroud Project Engineer

SUBJECT: PERFORMANCE IMPACT OF SHROUD REPAIR LEAKAGE FOR DRESDEN  
UNITS 2 AND 3

Reference: DRF No. B13-01749.

## 1. Introduction

The hardware designed to repair the shroud with identified cracks for Dresden Units 2 and 3 requires the machining of eight holes through the shroud support plate. Each of these holes will have some clearance, which will allow leakage flow to bypass the steam separation system. In addition, potential leakage through the weld cracks (H1 through H8) and the replacement access hole cover is also considered. This letter reports the leakage flow for 100% rated power and core flow.

## 2. Evaluation

### 2.1 Leakage Flow Evaluation

The most restrictive flow area for leakage through the holes in the shroud support plate is based on a conservative gap between the adjacent surfaces of the shroud support plate and the lower support bracket. In addition, there are a total of eight circumferential shroud welds (H1 - H8) that are considered as potential leakage paths - two above the top guide support ring, three on the upper shroud between the core support ring and the top guide support ring, and three on the lower shroud below the core support ring. It is conservatively assumed that each of these welds develops a complete circumferential crack that opens to 0.001 inches.

The leakage flows for 100% rated power and core flow are summarized in Table 1. These leakage flows are based on applicable loss coefficients and reactor internal pressure differences (RIPD's) across the applicable shroud components. The replacement access hole cover leakage is based on information in the referenced DRF. Leakage from the weld cracks above the top guide support ring is assumed to be two-phase fluid at the core exit quality. Leakage from the remaining paths below the top guide support ring is considered single-phase liquid. All of the leakage flows bypass the steam separators and dryers. The leakage flows below the shroud support ring also bypass the core. The results show that the leakage flows from the repair holes, weld cracks and the access hole cover result in a combined leakage of about 0.23% of core flow.

**Table 1. Summary of Leakage Flows at Rated Power and Flow**

Leakage flow (gpm)	
Shroud head flange pockets	1600
Weld cracks	140
Repair holes in support plate	325
Access hole covers	180
Leakage-to-core Mass flow (%)	
Shroud head flange pockets	0.21
Weld cracks	0.04
Repair holes in support plate	0.12
Access hole covers	0.07

The steam portion of the leakage flows will contribute to increasing the total carryunder from the steam separators. The impacts of the total leakage on the steam separation system performance, jet pump performance, core monitoring, fuel thermal margin, emergency core cooling system (ECCS) performance and fuel cycle length are evaluated as summarized in the following subsections.

## 2.2 Steam Separation System

The leakage flow through weld cracks H1 and H2 occurs above the top guide support ring and includes steam flow, which effectively increases the total carryunder in the downcomer by about 0.03% at rated conditions. The carryunder from the separators is based on the applicable separator test data at the lower limit of the operating water level range. The combined effective carryunder from the separators and the shroud head leakage is about 0.18% and is bounded by the design value.

## 2.3 Jet Pumps

The increased total carryunder will decrease the subcooling of the flow in the downcomer. This in turn reduces the margin to jet pump cavitation. However, because the total carryunder meets the design-condition carryunder value, there is no impact on jet pump performance compared with the design condition.

## 2.4 Core Monitoring

The impact of the leakage results in an overprediction of core flow by about 0.21% of core flow. This overprediction is small compared with the core flow measurement uncertainty of 2.5% for jet pump plants used in the MCPR Safety Limit evaluations. Additionally, the decrease in core flow resulting from the overprediction results in only a 0.1% decrease in calculated MCPR. Therefore, it is concluded that the impact is not significant.

## 2.5 Anticipated Abnormal Transients

The code used to evaluate performance under anticipated abnormal transients and determine fuel thermal margin includes carryunder as one of the inputs. The effect of the increased carryunder due to leakage results in greater compressibility of the downcomer region and, hence, a reduced maximum vessel pressure. Since this is a favorable effect, the thermal limits are not impacted.

## 2.6 Emergency Core Cooling System

Leakage through weld cracks H1 and H2 results in slightly increased carryunder that causes the initial core inlet enthalpy to increase slightly, with a corresponding decrease in the core inlet subcooling. However, because the total downcomer carryunder still meets the design value, there is no impact on the emergency core cooling system (ECCS) performance from this effect compared with the design conditions. Another effect of the leakage flows from the repair holes and the weld cracks is to decrease the time to core uncover slightly and, also to increase the time that the core is uncovered. The combined effect has been assessed to increase the peak cladding temperature (PCT) for the limiting LOCA event by less than 30°F. The current analysis basis yields a LOCA PCT of about 2045°F for the design basis LOCA with LPCI injection failure. The 10CFR50.46 regulatory limit PCT is 2200°F. Because the maximum potential effect on the design basis LOCA PCT is very small, there is no adverse effect on the margin of safety. This impact is sufficiently small to be judged insignificant, and hence, the licensing basis PCT for the normal condition with no shroud leakage is applicable. The sequence of events remains essentially unchanged for the LOCA events with the shroud head leakage.

## 2.7 Fuel Cycle Length

The increased carryunder due to leakage flow above the top guide support ring results in a slight increase in the core inlet enthalpy, compared with the no-leakage condition. The combined impact of the reduced core inlet subcooling and the reduced core flow due to the leakage results in a minor effect (-0.8 days) on fuel cycle length and is considered negligible.

## 3. Conclusions

The impact of the leakage flows through the shroud repair holes and the potential weld cracks in the shroud have been evaluated. The results show that at rated power and core flow, the leakage flows from the repair holes and the weld cracks are predicted equal to a combined leakage of about 0.44% of core flow (including potential replacement access hole cover leakage). These leakage flows are sufficiently small so that the steam separation system performance, jet pump performance, core monitoring, fuel thermal margin and fuel cycle length remain adequate. Also, the impact on ECCS performance is sufficiently small to be judged insignificant, and hence, the licensing basis PCT for the normal condition with no shroud leakage is applicable.

M. D. Potter