

ENCLOSURE 1

NOTICE OF VIOLATION

Florida Power and Light Company  
Turkey Point

Docket Nos. 50-250 and 50-251  
License Nos. DPPR-31 and DPPR-41

The following violations were identified during an inspection conducted on March 19-23, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

1. Technical Specification 6.3.1 requires that each member of the facility staff meet or exceed the minimum qualifications of ANSI N18.1-1971 for comparable positions. Paragraph 4 of ANSI N18.1-1971 states, in part, that technicians in responsible positions shall have a minimum of two years of working experience in their specialty.

Contrary to the above, chemistry technicians with less than two years of working experience in their speciality were serving in responsible positions.

This is a Severity Level IV Violation (Supplement IV).

2. Technical Specification 6.8 requires that written procedures and administrative policies be established, implemented and maintained that meet or exceed the requirements and recommendations of Section 5.1. and 5.3 of ANSI N18.7-1972, and Appendix A of Regulatory Guide 1.33, and that each procedure and change thereto be reviewed by the PNCS and approved by the Nuclear Plant Superintendent prior to implementation.

Contrary to the above, the requirements of the Technical Specification were not met, in that:

- (a) Between December 27, 1983 and March 22, 1984, Shipments of radioactive waste were made using a draft procedure which had not been reviewed by the PNCS or approved by the Plant Manager-Nuclear, and
- (b) Laboratory qualification guides were not used to document the qualifications of the chemistry technicians as required by Nuclear Chemistry Procedure NC-120.

This is a Severity Level V Violation (Supplement IV).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

8406210531 840608  
PDR ADOCK 05000250  
G PDR

Florida Power and Light Company  
Turkey Point

2 Docket Nos. 50-250 and 50-251  
License Nos. DPPR-31 and DPPR-41

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: APR 20 1984