

Mr. T. C. McMeekin
Vice President, McGuire Site
Duke Power Company
12700 Hagers Ferry Road
Huntersville, NC 28078-8985

September 7, 1995

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION GENERIC LETTER 95-03

Dear Mr. McMeekin:

On April 28, 1995, the U.S. Nuclear Regulatory Commission issued Generic Letter (GL) 95-03 "Circumferential Cracking of Steam Generator Tubes" which requested addressees to evaluate recent operating experience related to circumferential cracking, justify continued operation until the next scheduled steam generator tube inspections, and to develop plans for the next steam generator tube inspections. The staff has reviewed your response for McGuire Nuclear Station, Units 1 and 2. As a result of the review of your response, the staff has identified areas for which additional information and/or clarification is needed. The enclosure to this letter contains the information needed for the staff to complete its review of your response to GL 95-03. Please provide your response within 30 days of receipt of this letter.

The information requested by this letter is within the scope of the overall burden estimated in Generic Letter 95-03 of 350 hours. This request is covered by the Office of Management and Budget clearance number 3150-001, which expires July 31, 1997.

Sincerely,

Original signed by:

Victor Nerses, Senior Project Manager
Project Directorate II-2
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Docket Nos. 50-369 and 50-370

Enclosure: Request for
Additional Information

cc w/encl: See next page

DISTRIBUTION

Docket File
PUBLIC
PD22 Reading File
S. Varga
J. Zwolinski
OGC
ACRS (4)
K. Karwoski
E. Merschoff, RII
R. Crlenjak, RII

DOCUMENT NAME: G:\MCGUIRE\RAI

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

OFFICE	LA:PD22:DRPE	E	PM:PD22:DRPE	E	D:PD22:D&RS	N			
NAME	LBerry		VNerses		HBerkow				
DATE	9/7/95		9/7/95		9/7/95				

OFFICIAL RECORD COPY

9509140136 950907
PDR ADOCK 05000369
P PDR

NRC FILE CENTER COPY
Dfoi



UNITED STATES
NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20565-0001

September 7, 1995

Mr. T. C. McMeekin
Vice President, McGuire Site
Duke Power Company
12700 Hagers Ferry Road
Huntersville, NC 28078-8985

SUBJECT: REQUEST FOR ADDITIONAL INFORMATION GENERIC LETTER 95-03

Dear Mr. McMeekin:

On April 28, 1995, the U.S. Nuclear Regulatory Commission issued Generic Letter (GL) 95-03 "Circumferential Cracking of Steam Generator Tubes" which requested addressees to evaluate recent operating experience related to circumferential cracking, justify continued operation until the next scheduled steam generator tube inspections, and to develop plans for the next steam generator tube inspections. The staff has reviewed your response for McGuire Nuclear Station, Units 1 and 2. As a result of the review of your response, the staff has identified areas for which additional information and/or clarification is needed. The enclosure to this letter contains the information needed for the staff to complete its review of your response to GL 95-03. Please provide your response within 30 days of receipt of this letter.

The information requested by this letter is within the scope of the overall burden estimated in Generic Letter 95-03 of 350 hours. This request is covered by the Office of Management and Budget clearance number 3150-001, which expires July 31, 1997.

Sincerely,

A handwritten signature in cursive script, appearing to read "Victor Nerses".

Victor Nerses, Senior Project Manager
Project Directorate II-2
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

Docket Nos. 50-369 and 50-370

Enclosure: Request for
Additional Information

cc w/encl: See next page

Mr. T. C. McMeekin
Duke Power Company

McGuire Nuclear Station

cc:

A. V. Carr, Esquire
Duke Power Company
422 South Church Street
Charlotte, North Carolina 28242-0001

County Manager of Mecklenburg County
720 East Fourth Street
Charlotte, North Carolina 28202

Mr. J. E. Snyder
Regulatory Compliance Manager
Duke Power Company
McGuire Nuclear Site
12700 Hagers Ferry Road
Huntersville, North Carolina 28078

J. Michael McGarry, III, Esquire
Winston and Strawn
1400 L Street, NW.
Washington, DC 20005

Senior Resident Inspector
c/o U. S. Nuclear Regulatory
Commission
12700 Hagers Ferry Road
Huntersville, North Carolina 28078

Mr. T. Richard Puryear
Nuclear Technical Services Manager
Westinghouse Electric Corporation
Carolinas District
2709 Water Ridge Parkway, Suite 430
Charlotte, North Carolina 28217

Dr. John M. Barry
Mecklenburg County
Department of Environmental
Protection
700 N. Tryon Street
Charlotte, North Carolina 28202

Mr. Dayne H. Brown, Director
Department of Environmental,
Health and Natural Resources
Division of Radiation Protection
P. O. Box 27687
Raleigh, North Carolina 27611-7687

Ms. Karen E. Long
Assistant Attorney General
North Carolina Department of
Justice
P. O. Box 629
Raleigh, North Carolina 27602

Mr. G. A. Copp
Licensing - EC050
Duke Power Company
526 South Church Street
Charlotte, North Carolina 28242

Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta Street, NW. Suite 2900
Atlanta, Georgia 30323

Elaine Wathen, Lead REP Planner
Division of Emergency Management
116 West Jones Street
Raleigh, North Carolina 27603-1335

REQUEST FOR ADDITIONAL INFORMATION

McGuire Units 1 and 2

1. Please clarify the outage during which the rotating pancake coil (RPC) examination of the U-bend portion of the tubes in Rows 1, 2, and 3 at McGuire Units 1 and 2 were performed.
2. In your response to Generic Letter (GL) 95-03, you indicated that dents greater than 4.0 volts had been inspected with a technique capable of detecting circumferential cracking. Provide the procedures used for sizing the dents (i.e., 4.0 volts on 4-20% through-wall ASME holes at 550/130 mix). If the procedure is identical to the procedure for the voltage-based repair criteria, a detailed description is not necessary.

ENCLOSURE