

January 29, 1992

PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-11-92-05

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the Region II staff on this date.

FACILITY: Florida Power & Light  
Turkey Point Unit 4  
Docket No. 50-251  
Florida City, Florida

Licensee Emergency Classification:  
\_\_\_\_ Notification of Unusual Event  
\_\_\_\_ Alert  
\_\_\_\_ Site Area Emergency  
\_\_\_\_ General Emergency  
X Not Applicable

SUBJECT: UNIT SHUTDOWN IN EXCESS OF THREE DAYS

Turkey Point Unit 4 was taken off line at 10:41 p.m. on January 28, 1992, to repair a small steam leak inside the Containment Building. The steam leak is in an elbow in a three-fourth inch line to main steam flow transmitter FT495, and is not isolable from the 4C steam generator. The licensee is taking the unit to cold shutdown to accomplish weld repairs, and expects to have the unit back on line at about midnight this Saturday, February 1, 1992.

The State of Florida was informed by the Licensee.

The NRC Resident Inspector received initial notification of this shutdown from the Licensee at 7:55 p.m. (EDT) on January 28, 1992.

This information is current as of 9:00 a.m. on January 29, 1992.

CONTACT: R. Schin - 841-5561

DISTRIBUTION:

One White	M'land Nat'l	Regions	MAIL TO:	DCS	(Original	IE	34)	
Flint North	Bank Bldg	Region I		DOT	(Transportation		Only)	11:14
Chairman Selin	IRM	Region			II			
Comm. Rogers	OIG	Region III		FAX TO:	Chairman		Selin	11:10
Comm. Curtiss	AEOD	Region IV			OIG			11:12
Comm. Remick	NRC Ops Ctr				INPO			11:16
Comm. de Planque	Region V				LICENSEE	(Corporate)		11:21
OGC					and	site		
OCA	Nicholson Lane	Phillips Bldg			RII	Resident		11:19
GPA/SLITP/PA	RES	ACRS			PM,	NRR		
EDO								
NRR	L Street	EW						
NMSS	PDR	ASLAP						
OE								

5520: 01/29/92 @ 10:45 a.m. TO REGIONS AND HQ

\*\*\*\*\*

*DW*

9202140105 920129  
PDR I&E  
PNO-11-92-005 PDR

110  
IE34