

ENCLOSURE 1

NOTICE OF VIOLATION

Carolina Power and Light Company  
Shearon Harris Unit 1

Docket No. 50-400  
License No. CPPR-158

The following violations were identified during an inspection conducted on February 20 - March 23, 1984. The Severity Levels were assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50.55(f)(1) requires CP&L to implement the quality assurance program described or referenced in the Preliminary Safety Analysis Report. Section 1.8.5.5 of the CP&L Quality Assurance Program requires that activities affecting quality be accomplished in accordance with documented instructions, procedures and drawings.

Contrary to the above, CP&L failed to insure that the current craft certifications records for electrical terminators and painters be filed in the QA vault. This item was identified by the resident inspectors on March 16, 1984.

This is a Severity Level V Violation (Supplement II).

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: APR 06 1984

B406220049 B40608  
PDR ADOCK 05000400  
G PDR