Duke Power Company Catawba Nuclear Generation Department 4800 Concord Road York, SC 29745



DUKE POWER

September 8, 1995

Document Control Desk U. S. Nuclear Regulatory Commission Washington, D.C. 20555

Subject: Catawba Nuclear Station Docket No. 50-413 LER 413/95-003, Revision 1

Gentlemen:

Attached is Licensee Event Report 413/95-003, Revision 1, concerning FAILURE TO PERFORM TECHNICAL SPECIFICATION SURVEILLANCES DUE TO UNANTICIPATED INTERACTION OF SYSTEMS. This revision is being submitted with additional information that had not initially been considered as well as the final Safety Analysis.

This event was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

W. R. McCollum

xc: Mr. S. D. Ebneter
 Regional Administrator, Region II
 U. S. Nuclear Regulatory Commission
 101 Marietta Street, NW, Suite 2900
 Atlanta, GA 30323

Mr. R. E. Martin U. S. Nuclear Regulatory Commission Office of Nuclear Reactor Regulation Washington, D.C. 20555

9509150061

Mr. R. J. Freudenberger NRC Resident Inspector Catawba Nuclear Station

Printed on recycled pape

Marsh & McLennan Nuclear 1166 Avenue of the Americas New York, NY 10036-2774

INPO Records Center 700 Galleria Place Atlanta, GA 30339

IE22

WILLIAM R. MCCOLLUM, JR. Vice President (803)831-3200 Office (803)831-3426 Fax U. S. Nuclear Regulatory Commission September 8, 1995 Page Two

bxc:

M. S. Tuckman B. L. Walsh C. A. Paton A. V. Carr B. J. Horsley T. E. Mooney NSRB Staff NC MPA-1 NCEMC PMPA SREC EC07H
EC11C
PB02L
PB05E
EC12T
EC090
EC05N

J. W. Glenn (PIP File) K. E. Nicholson (Reg. Compl.) SRG Electronic Library Master File - CN05SR (with Enclosures)

- CN01RC (with Enclosures)

- CN05SR (with Enclosures)

- EC050 (with Enclosures)

- CN02DC CN-815.04 (with Enclosures)