

06/12/80

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PDR

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IR-77-01	IE BULLETIN	C	R210	C		PNEUMATIC TIME DELAY SET POINT DRIFT
	IR-77-02	IE BULLETIN	C	R210	C		POT FAILURE MECHANISM IN CERTAIN W AR RELAYS W/LATCH ATTACHMENTS
	IR-77-03	IE BULLETIN	C	R329	C		ONLINE TESTING OF W SOLID STATE PROTECTION SYSTEM
	IR-77-04	IE BULLETIN	C	R210	C		CALC ERROR-DESIGN PERFORMANCE SYS CONTRLS PH CONT BUMP WATER FOL LOCA
	IR-77-05	IE BULLETIN	C	R210	C		ELECTRIC CONNECTOR ASSEMBLIES-SUPPLEMENT A
	IR-77-07	IE BULLETIN	C	R210	C		CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IR-77-08	IE BULLETIN	C	R210	C		SAFEGUARDS LOCKING SYSTEM
	IR-78-01	IE BULLETIN	C	R210	C		FLAMMABLE CONTACT-ARM RETAIN GE CR120A RELAYS
	IR-78-02	IE BULLETIN	C	R210	C		TERMINAL BLOCK QUALIFICATION
	IR-78-04	IE BULLETIN	C	R210	C		ENVIRONMENTAL QUALIF CERTAIN STEM MOUNTED LIMIT SWITCH INSIDE REACTOR CONTAINMENT
	IR-78-05	IE BULLETIN	C	R210	C		MAFUNCTION CIRCUIT BRKR AUX CONTACT MECHANISM-GENERAL MODEL CR105X

8406230210 840612
 PDR ADDCK 05000528
 PDR
 Q

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 2

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IR-78-04	IE BULLETIN	C	8210	C		DEFECTIVE CUTLER-HAMER TYPE M RELAYS WITH DC COILS
	IR-78-10	IE BULLETIN	C	8210	C		BERGEN-PATTERSON HYDRAULIC SHOCK SUPPRESSOR ACCUMULATOR SPRING COILS
	IR-78-12	IE BULLETIN	C	8210	C		ALSO 78-12A AND 78-12B ATYPICAL WELD MATERIAL IN RV-SPLMTS A & B
	IR-79-01	IE BULLETIN	C	8329	C		ENVIRONMENTAL QUALIFICATION OF CLASS IE EQUIP-SPLMTS A & B
	IR-79-02	IE BULLETIN	C	8231	C		PIPE SUP BASE PLY DGGN USING CONCRETE EXP ANCHOR BOLTS LATEST EFFECTIVE REV: 2/SUP: 1
	IR-79-03	IE BULLETIN	C	8231	C		LONGITUDINAL WELD DEFECTS IN ASME SA-312 TYPE 304 STAINLESS STEEL PIPE-AND REV. A
	IR-79-04	IE BULLETIN	C	8231	C		INCORRECT WEIGHTS FOR SWING CHECK VALVES MANUFACTURED BY VELAN ENG.
	IR-79-07	IE BULLETIN	C	8231	C		SEISMIC STRESS ANALYSIS OF SAFETY RELATED PIPING
	IR-79-09	IE BULLETIN	C	8231	O		FAILURES OF GE TYPE AK-2 CIRCUIT BREAKER IN SAFETY RELATED SYSTEMS
	IR-79-11	IE BULLETIN	C	8231	C		FAULTY OVERCURRENT TRIP DEVICE IN CIRCUIT BREAKERS IN ENG SAFETY SYSTEM
	IR-79-14	IE BULLETIN	C	8231	O		SEISMIC ANAL OF AS-BUILT SAFETY RELATED PIPING SYSTEM - LATEST EFFECTIVE REV: 1/SUP: 2

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IR-79-15	IE BULLETIN	C	R231	C		MATE DEFS IN INGER-RAND PUMPS USED FOR HI/LO PRESS COPE SPRAY & RHR PP
	IR-79-21	IE BULLETIN	C	R308	O		TEMPERATURE EFFECTS ON LEVEL MEASUREMENTS
	IR-79-23	IE BULLETIN	C	R308	C		POTENTIAL FAILURE OF EMERG DIESEL GEN FIELD EXCITER TRANSFORMER
	IR-79-24	IE BULLETIN	C	R311	C		FROZEN LINES SAFETY RELATED
	IR-79-25	IE BULLETIN	C	R308	C		FAILURES OF WESTINGHOUSE RFD RELAYS IN SAFETY RELATED SYSTEMS
	IR-79-28	IE BULLETIN	C	R308	C		POSS MALF CN OF NAMCO MODEL FA180 LIMIT SWITCHES AT ELEVATED TEMPS
	IR-80-03	IE BULLETIN	M	R021	C		LOSS OF CHARCOAL FROM TRAY ABSORBER CELLS-RESPOND BY MAR 31, 1980
	IR-80-05	IE BULLETIN	C	R311	C		VACUUM COND RESULTING IN DAMAGE TO HOLDUP TANKS RESPOND BY JUN 28, 1980
	IR-80-06	IE BULLETIN	C		O		ESF RESET CONTROLS - OL'S RESPOND BY JUL 1, 1980 - CP'S FOR INFO ONLY
	IR-80-08	IE BULLETIN	C		O		EXAM OF CONTAINMENT LINER PENETRATION WELDS - RESPOND BY JUL 16, 1980
	IR-80-09	IE BULLETIN	C		O		HYDRAMOTOR ACTUATOR DEFICIENCIES RESPOND BY JUL 6, 1980

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	18-80-11	IE BULLETIN	C	8311	C		MASONARY BLOCK WALLS
	18-80-12	IE BULLETIN	C	8121	0		DECAY HEAT REMOVAL SYS OPERABILITY
	18-80-16	IE BULLETIN	C	8121	0		POTENTIAL MISAPPLICATION OF ROSEMT 1151 & 1152 PRESSURE TRANSMITTERS-REP BY 9-5-80
		IE BULLETIN	C	8308	0		
	18-80-18	IE BULLETIN	C		0		MAINT OF ADEQUATE FLOW THRU CCP'S AFTER SECONDARY BREAK-NO REPLY REQD
	18-80-19	IE BULLETIN	C	8308	C		FAILURE OF MERCURY WETTED RELAYS IN RPS-REPLY BY 11-05-80
	18-80-20	IE BULLETIN	C	8308	C		WESTINGHOUSE TYPE W-2 CONTROL SWITCH-REPLY BY 9-21-80
	18-80-21	IE BULLETIN	C	8308	C		VALVE YOKES SUPPLIED BY MALCOM FOUNDRY CO, CRACK FAILURE
	18-80-23	IE BULLETIN	C	8308	C		FAILURE OF SOLENOID VALVES MFG BY VALCOR ENG CORP
	18-81-01	IE BULLETIN	C		0		SURVEILLANCE OF MECHANICAL SNIPPERS-INSPECT ACCESSABLE WITHIN 30 DAYS
	18-81-02	IE BULLETIN	C	8234	0		PRV ISULATION OR BLOCK VALVE FAILURES AGAINST DIFF PRESSURE 90 DAYS FOR CONST

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 5

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IR-81-02	IE BULLETIN	C	R305	0		
	IR-81-03	IE BULLETIN	C		0		CLAM INFESTATIONS OF WATER SYSTEMS & RESULTANT FOULING-90 DAY RPT FOR CONST.
	IR-82-01	IE BULLETIN	C		0		ALTERATION OF RADIOGRAPHS OF WELD IN PIPING SUBASSEMBLIES
	IR-82-02	IE BULLETIN	C		0		DEGRADATION OF THREADED FASTENERS IN PRIMARY PRESSURE BOUNDARIES
	IR-82-03	IE BULLETIN	C		0		STRESS CORROSION CRACKING IN THICKWALL LARGE-DIAMETER STAINLESS RECIP
	IR-82-04	IE BULLETIN	C		0		DEFICIENCIES IN PRIMARY CONTAINMENT ELECTRICAL PENETRATION ASSEMBLIES
	IR-83-01	IE BULLETIN	0		0		FAILURE OF REACTOR TRIP BREAKERS TO OPEN ON AUTO TRIP SIGNAL
	IR-83-02	IE BULLETIN	C		0		STRESS CORROSION CRACKING IN LARGE DIAMETER STAINLESS STEEL RECIP
	IR-83-03	IE BULLETIN	C		0		CHECK VALVE FAILURES IN RAW WATER SYS OF DIESEL GENERATORS
	IR-83-04	IE BULLETIN	C		0		FAILURE OF UNDERVOLTAGE TRIP FUNCTION OF REACTOR TRIP BREAKER
	IR-83-05	IE BULLETIN	C		0		PUMPS & PARTS BY WAYWARD TYLER

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 6

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IR-83-06	IE BULLETIN	C		0		NO MATERIALS SUPPLIED BY TUBE-LINE CORP OF LONG ISLD CITY HOUSTON
	IR-83-07	IE BULLETIN	C		0		APPARENTLY FRAUDLENT PRODUCTS SOLD BY RAY MILLER, INC
	IR-83-08	IE BULLETIN	C		0		CKT BKRS WITH UV TRIP IN SAFETY RELATED USE OTHER THAN REACTOR TRIP
	IR-84-02	IE BULLETIN	C		0		FAILURE OF GE TYPE HFA RELAYS USED IN CLASS IE SAFETY SYSTEMS

06/12/80

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 7

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	IC-76-01	IE CIRCULAR	C	8210	C		CIRCUIT MODS ON CRANE HOIST CONTROLS
	IC-76-02	IE CIRCULAR	C	8210	C		RELAY FAILURES-W/BF(AC) & RFD(DC) RELAYS
	IC-76-05	IE CIRCULAR	C	8210	C		HYDRAULIC SHOCK & SWAY SUPPRESSORS MFG BY ITT-GRINNELL
	IC-77-01	IE CIRCULAR	C	8210	C		MAJFUNCTIONS OF LIMITORQUE VALVE OPERATORS
	IC-77-03	IE CIRCULAR	C	8210	C		FIRE INSIDE A MOTOR CONTROL CENTER
	IC-77-05	IE CIRCULAR	C	8210	C		LIQUID ENTRAPMENT IN VALVE BONNETS
	IC-77-06	IE CIRCULAR	C	8210	C		EFFECTS OF HYDRAULIC FLUID ON ELECTRICAL CABLE
	IC-77-14	IE CIRCULAR	C	7807	C		SEPARATION CONTAMINATED WATER SYS FROM NONCONTAMINATED PLANT SYSTEM
	IC-78-02	IE CIRCULAR	C	8210	C		PROPER LUBRICATING OIL FOR TERRY TURBINES
	IC-78-04	IE CIRCULAR	C	8210	C		INSTALLATION ERROR THAT COULD PREVENT CLOSING OF FIRE DOORS
	IC-78-05	IE CIRCULAR	C	8210	C		INADVERTENT SAFETY INJECTION DURING COOLDOWN

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 8

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IC-78-06	IE CIRCULAR	C	8210	C		PUT COMMON MODE FLOODING OF ECCS EQUIP RMS AT BWR FACILITIES
	IC-78-07	IE CIRCULAR	C	8210	C		DAMAGED COMPONENTS OF BERGEN-PATTERSON 25000 HYDRAULIC TEST STAND
	IC-78-08	IE CIRCULAR	C	8210	C		ARCING OF GE CO SIZE 2 CONTRACTORS
	IC-78-13	IE CIRCULAR	C	8210	C		INOPERABILITY OF MULT SERVICE WATER PUMPS
	IC-78-15	IE CIRCULAR	C	8210	C		CHECKVALVES FAIL TO CLOSE IN VERT POSITION
	IC-78-16	IE CIRCULAR	C	8210	C		LIMITORQUE VALVE ACTUATORS
	IC-78-18	IE CIRCULAR	C	8210	C		UL FIRE TEST
	IC-78-19	IE CIRCULAR	C	8210	C		MANUAL OVERRIDE OF SAFETY SYS ACTUATOR SIGNALS
	IC-79-02	IE CIRCULAR	C	8231	C		FAILURE OF 120 VOLT VITAL AC POWER SUPPLIES
	IC-79-04	IE CIRCULAR	C	8231	C		LOOSE LOCKING NUT ON LIMITORQUE VALVE OPERATORS
	IC-79-05	IE CIRCULAR	C	8231	C		MOISTURE LEAKAGE IN STRANDED WIRE CONNECTORS

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 9

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IC-79-08	IE CIRCULAR	C	8231	C		NO DESCRIPTIVE TITLE
	IC-79-10	IE CIRCULAR	C	8231	C		NO DESCRIPTIVE TITLE
	IC-79-11	IE CIRCULAR	C	8231	C		DESIGN/CONSTR PROB-MISORIENTED RX VESSELS OR THEIR SUPPORTS
	IC-79-12	IE CIRCULAR	C	8231	C		NO DESCRIPTIVE TITLE
	IC-79-13	IE CIRCULAR	C	8231	C		REPLACEMENT OF DIESEL FIRE PUMP STARTING CONTACTORS
	IC-79-17	IE CIRCULAR	C	8231	O		CONTACT PROBLEM IN SR-12 SWITCHES ON GE METALCLAD CIRCUIT BREAKERS
	IC-79-18	IE CIRCULAR	C	8231	C		PROPER INSTALLATION OF TARGET ROCK SAFETY-RELIEF VALVES
	IC-79-19	IE CIRCULAR	C	8231	C		LOOSE IMPELLAR LOCKING DEVICES ON INGERSOLL-RAND PUMPS
	IC-79-20	IE CIRCULAR	C	8231	C		FAILURE OF GTE SYLVANIA RELAYS
	IC-79-21	IE CIRCULAR	M	8021	C		PREVENTION OF UNPLANNED RELEASES OF RADIOACTIVITY
		IE CIRCULAR	C	8231	O		

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 10

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IC-79-22	IE CIRCULAR	C	A231	C		STROKE TIMES FOR POWER OPERATED RELIEF VALVES (PORV'S)
	IC-79-23	IE CIRCULAR	C	A231	C		MOTOR STARTERS AND CONTACTORS FAILED TO OPERATE
	IC-79-25	IE CIRCULAR	C	A231	C		SHOCK ARRESTOR STRUT ASSEMBLY INTERFERENCE; LATEST EFFECTIVE IS SUP A
	IC-80-01	IE CIRCULAR	C	8308	0		GE INDUCTION RELAYS
	IC-80-03	IE CIRCULAR	C	8308	C		TOXIC GAS
	IC-80-04	IE CIRCULAR	C	8308	C		SECURING OF THREADED LOCKING DEVICES ON SAFETY-RELATED EQUIPMENT
	IC-80-05	IE CIRCULAR	C	8308	0		EMERG DIESEL GEN LUBE OIL ADDITION AND ONSITE SUPPLY
	IC-80-07	IE CIRCULAR	C	8308	C		TURBINE OIL PROBLEMS
	IC-80-09	IE CIRCULAR	C		0		PROBLEMS WITH PLANT INTERNAL COMMUNICATIONS SYSTEMS
		IE CIRCULAR	C	8308	0		TRANSFER TO OPS PER PJ/PN DISCUSSION 3/21/83
	IC-80-10	IE CIRCULAR	C	8308	0		FAILURE TO MAINTAIN ENVIRONMENTAL QUALIFICATION OF EQUIPMENT

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IC-80-11	IE CIRCULAR	C	8308	C		EMERGENCY DIESEL GENERATOR LUBE OIL COOLER FAILURES
	IC-80-12	IE CIRCULAR	C	8308	C		BETTIS/PRATT VALVE ACTUATOR SHAFT KEY ORIENTATION
	IC-80-14	IE CIRCULAR	C	8021	O		RADIOACTIVE CONTAMINATION OF PLANT DEMIN. WATER SYSTEM
		IE CIRCULAR	C	8311	O		CONTAMINATION OF DEMINERALIZED WATER (REOPENED BY NARRUT FOR OPERATIONS)
	IC-80-14	IE CIRCULAR	C	8311	O		DEFICIENCIES IN ROSEMOUNT 510DU TRIP UNITS & 1152 PRESS XMTS
	IC-80-17	IE CIRCULAR	C	8311	C		FUEL PIN DAMAGE FROM WATER JET BARREL PLATE CORNER
	IC-80-18	IE CIRCULAR	M	8021	C		50,59 SAFETY EVALUATIONS FOR CHANGES TO RAWASTE SYSTEMS
	IC-80-22	IE CIRCULAR	C	8311	C		CONFIRMATION OF EMPLOYEE QUALIFICATIONS PROGRAM
	IC-80-23	IE CIRCULAR	C	8311	C		DEFECTS IN BELDIT POWER SYSTEMS EMERGENCY GENERATORS COUPLED TO DIESELS
	IC-81-01	IE CIRCULAR	C	8319	C		MECHANICAL MALFUNCTION OF HONEYWELL PB INDICATING SWITCHES AT SAN ONOFRE
	IC-81-02	IE CIRCULAR	O		O		PERFORMANCE OF NRC LICENSED INDIVIDUALS WHILE ON DUTY

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IC-81-03	IE CIRCULAR	O		O		INOP SEISMIC INSTRUMENTATION
	IC-81-04	IE CIRCULAR	O		O		ROLE OF STA'S & IMPORTANCE OF LER'S
	IC-81-05	IE CIRCULAR	C	8311	C		SELF-ALIGNING ROD END BUSHINGS FOR PIPE SUPPORTS
	IC-81-06	IE CIRCULAR	C	8311	C		ENVIRONMENTAL DUAL FAILURE OF FOXBORO 10-50 MA XMITTERS
	IC-81-07	IE CIRCULAR	M	8224	C		CONTROL OF RADIOACTIVELY CONTAMINATED MATERIAL
	IC-81-08	IE CIRCULAR	C	8311	C		INSUFFICIENT COMPACTION OF BACKFILL MATERIALS DURING CONSTRUCTION
	IC-81-09	IE CIRCULAR	C	8311	C		UNMONITORED CONTAINMENT EFFLUENT BYPASS
	IC-81-10	IE CIRCULAR	O		O		STEAM VOIDING IN RCS DURING COOLDOWN
	IC-81-12	IE CIRCULAR	O		O		INADEQUATE PERIODIC BREAKER TEST PROCEDURES
	IC-81-13	IE CIRCULAR	C	8311	C		TORQUE SWITCH ELECTRICAL BYPASS-CKT MISSING ON SAFEGUARD VALVE MOTORS
	IC-81-14	IE CIRCULAR	C	8311	O		EVALUATE MSIV PROGRAMS & PROPOSE CHANGES TO MINIMIZE PROBLEMS

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 13

DOCKET ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT-NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-15-01 INSP RPT (DEV)	0	0	0		DELAY IN ISSUING REVISED 70AC-07Z02
83-34-09	INSP RPT (DEV)	C	8406	0		ACCEPTANCE CRITERIA FOR VISUAL INSPECTION OF WELDING
83-41-01	INSP RPT (DEV)	M		0		FUEL BLDG-MONITOR NOT ISOKINETIC
83-01-02	INSP RPT (DEV)	M		0		RG 1.68 TEST PGM DEFICIENCY FOR TEST OF RMS-SAMPLE SYSTEM & PLATOUT

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 14

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	78-08-03	INSP RPT (ENF)	C	7809	C		MAKING OF REINFORCING BAR CALDWELDING PERFORMED AFTER PLACING SLEEVE
		INSP RPT (ENF)	C	7901	C		
	79-01-04	INSP RPT (ENF)	C	7904	C		DRAWING CONTROL
	79-02-04	INSP RPT (ENF)	C	8008	C		THE SHIPMENT, RECEIPT, STORAGE, AND REPAIR OF THE DIESEL GENERATORS
	79-04-02	INSP RPT (ENF)	C	7905	C		PIPE SUPPORTS HAD UNDERSIZED, INCOMPLETE, AND MISSING WELDS
		INSP RPT (ENF)	C	8112	C		
	79-05-XY	INSP RPT (ENF)	C	8112	C		PIPE HANGER-SUPPORT WELDS IN DESIGN DRAWINGS-STRUCTURAL STEEL
	79-07-09	INSP RPT (ENF)	C	8112	C		SUPPORT ASSEMBLIES OF THE LPSI AND CS RUMPS HAD UNDERSIZED WELDS
	80-01-01	INSP RPT (ENF)	C	8012	C		DOCUMENT CONTROL OF SUPERSEDED DRAWINGS AND FCR/DCN REVISIONS
	80-01-06	INSP RPT (ENF)	C		C		CONTROL OF WELD FILLER MATERIAL
		INSP RPT (ENF)	C	8008	C		NEED TO PERFORM FURTHER INSPECTIONS CONCERNING WELD ROD CONTROL

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 15

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	80-01-06	INSP RPT (ENF)	C	8012	C		
	80-02-01	INSP RPT (ENF)	C	8009	C		FAILURE TO PROPERLY STORE AND IDENTIFY NUCLEAR SYSTEM COMPONENTS
	80-06-01	INSP RPT (ENF)	C	8112	C		REPORTING OF 50,55E ITEM
	80-17-01	INSP RPT (ENF)	C	8022	C		FAIL TO PROVIDE MAINTENANCE ON MOTOR OPERATED MN STEAM & FDWR ISO VALVE
	81-12-01	INSP RPT (ENF)	C	8202	C		HOUSEKEEPING FOR FUEL POOL AREA
	82-02-01	INSP RPT (ENF)	C	8229	C		MISSING WELDS ON COLUMNS
	82-09-01	INSP RPT (ENF)	R		C		NONCOMPLIANCE WITH PART 50 APPENDIX B, PART II, HOUSEKEEPING
		INSP RPT (ENF)	R		C		NONCOMPLIANCE WITH PART 50 APPENDIX B-FAIL TO FOLLOW PROCEDURE
		INSP RPT (ENF)	R		C		SIS PUMP PERFORMANCE VERIFICATION
		INSP RPT (ENF)	R	8221	C		NONCOMPLIANCE W/PART 50 APPENDIX B PART II-HOUSEKEEPING
	82-09-02	INSP RPT (ENF)	R	8222	C		FAILURE TO FOLLOW PROCEDURE

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 16

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	82-09-04	INSP RPT (ENF)	R	NA	C		HCC PHASE SHORT EVALUATION FOR REPORTABILITY
	82-25-01	INSP RPT (ENF)	C	8329	C		CONTROL ROOM PANELS NOT WELDED IAW DRAWINGS
	82-30-01	INSP RPT (ENF)	F		0		NONCOMPLIANCE STEAM GENERATOR CHEMICAL
	83-02-01	INSP RPT (ENF)	C	8317	C		UNDOCUMENTED UNAUTHORIZED WELD IN RD SYSTEM
		INSP RPT (ENF)	C	8329	C		
	83-02-04	INSP RPT (ENF)	C	8317	0		PIPE SUPPORTS NOT PROVIDED BY ENGINEERING RD SYSTEM
		INSP RPT (ENF)	C	8329	0		
	83-10-01	INSP RPT (ENF)	C		0		TERMINATION CARDS INACCURATE
	83-18-01	INSP RPT (ENF)	C	8346	C		CON SPRAY MOTORS UNITS 1&2 INSUFF SUPPORT/NOY GROUNDED/ NO EESSR DOGS
	83-19-01	INSP RPT (ENF)	R	8408	C		HOUSEKEEPING IN THE FEEDWATER PUMP ROOM NONCOMPLIANCE
	83-31-01	INSP RPT (ENF)	R	8344	C		NONCOMPLIANCE LETDOWN LINE LEAK

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 17

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-34-01	INSP RPT (ENF)	C		0		QC PERSONNEL ACCEPTING DISCONTINUITIES
	83-34-02	INSP RPT (ENF)	C		0		QC PERSONNEL ACCEPTING
	83-34-03	INSP RPT (ENF)	C		0		FAILURE TO PROVIDE CONTROL OVER QUALITY ACTIVITIES
	83-34-04	INSP RPT (ENF)	C		0		FAILURE OF MFG QC TO IDENTIFY DEFECT
	83-34-05	INSP RPT (ENF)	C		0		FAILURE TO PROVIDE CONTROL OVER QUALITY ACTIVITIES
	83-34-06	INSP RPT (ENF)	C		0		FAILURE OF STUD NUTS TO MEET TORQUE REQUIREMENTS
	83-34-07	INSP RPT (ENF)	C		0		VPI POSITION INCORRECT
	83-34-08	INSP RPT (ENF)	C		0		UNSATISFACTORY BOLTING ACCEPTED BY QC
	83-34-10	INSP RPT (ENF)	C		0		ACCEPTANCE OF UNSATISFACTORY BOLTING BY QC
	83-34-11	INSP RPT (ENF)	C		0		NO PERMANENT ID ON CABLE TRAY
	83-34-12	INSP RPT (ENF)	C		0		JUNCTION BOX SEPARATION ABOUT ONE INCH

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 18

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-34-13	INSP RPT (ENF)	C		0		NON-SAFETY RELATED CONDUIT BOX IN CONTACT WITH SAFETY-RELATED CONDUIT
	83-34-14	INSP RPT (ENF)	C		0		NO RED ID ON GROUP 1 CABLE TRAY
	83-34-15	INSP RPT (ENF)	C		0		NO MARKINGS ON GROUP 1 CONDUITS
	83-34-16	INSP RPT (ENF)	C		0		NO BLUE ID ON CHANNEL D CONDUIT
	83-34-17	INSP RPT (ENF)	C		0		CABLE TRAY CONNECTIONS DISCONNECTED
	83-34-18	INSP RPT (ENF)	C		0		HANGER WELDS NOT IAW DRAWING
	83-34-19	INSP RPT (ENF)	C		0		WELD OVERLAP ON INSTRUMENT RACK SUPPORT
	83-34-20	INSP RPT (ENF)	C		0		LUMBER IN CHANNEL C ELECTRICAL RACEWAY
	83-34-21	INSP RPT (ENF)	C		0		CABLES IN CONTACT WITH FIRE PROTECTION RIG
	83-34-22	INSP RPT (ENF)	C		0		CONTAINMENT PRESSURE SENSING LINE CARPED
	83-34-23	INSP RPT (ENF)	C		0		87 BOLTS MISSING FROM BASE OF MCC

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO-VERDE UNIT 1

PAGE 19

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-34-24	INSP RPT (ENF)	C		0		ABOUT 1 INCH SEPARATION OF ELECTRICAL WIRING
	83-34-25	INSP RPT (ENF)	C		0		ABOUT 1 INCH SEPARATION OF ELECTRICAL WIRING
	83-40-01	INSP RPT (ENF)	R		0		FAILURE TO FOLLOW PROCEDURES
		INSP RPT (ENF)	R	8408	C		QC WITNESS OF HOLD POINTS MISSED
	83-40-02	INSP RPT (ENF)	R		0		FAILURE TO MAINTAIN PROPER ENVIRONMENT
		INSP RPT (ENF)	R	8408	C		EXCESSIVE VALVE LEAKAGE & DAMAGE TO PIPE SUPPORTS=NONCOMPLIANCE
	83-44-01	INSP RPT (ENF)	R		0		NONCOMPLIANCE FAILURE TO IMPLEMENT A PROPER VALVE ALIGNMENT CAUSED STEAM LINES TO FILL WITH WATER
	84-10-03	INSP RPT (ENF)	C		0		UNQUALIFIED QC

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 20

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	78-03-03	INSP RPT (FOLLOWUP)	C	8006	C		SEISMIC QUALIFICATION OF UNIT-STRUT ELECTRICAL TRAY SUPPORTS
		INSP RPT (FOLLOWUP)	C	8329	C		
		INSP RPT (FOLLOWUP)	C	8404	C		
	78-03-06	INSP RPT (FOLLOWUP)	C	8006	C		VISUAL INSPECTION OF COMPLETED WELDS
	78-06-05	INSP RPT (FOLLOWUP)	C	8006	C		INSTRUCTIONS TO CRAFT ON THE HANDLING OF REWORK ITEMS
	78-08-01	INSP RPT (FOLLOWUP)	C	8329	C		SITE STORAGE PRACTICES (HOT LEG PIPE SPOOL)
	78-09-01	INSP RPT (FOLLOWUP)	C	7902	C		VOIDS IN CONST JOINTS WHERE EXPANDED METAL SHEATHING USED FOR FORM WORK
		INSP RPT (FOLLOWUP)	C	7903	C		
	78-09-02	INSP RPT (FOLLOWUP)	C	7903	C		CONCRETE REPLACEMENT-SPECIFIC CRITERIA NOT PROVIDED BY OCE
	78-09-04	INSP RPT (FOLLOWUP)	C	7902	C		REJECT CRITERIA=QC INSP OF BOLT TORQUE-ADEQUACY ELEC RACEWAY INSTALL
	78-09-05	INSP RPT (FOLLOWUP)	C	7901	C		QUESTION-SEGREGATION CONTROL OF DISCREPANT ELEC CABLE IN STORAGE

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 21

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	79-01-01	INSP RPT (FOLLOWUP)	C	8228	C		CHLORIDE CONTENT IN CONCRETE
	79-01-03	INSP RPT (FOLLOWUP)	C	8006	C		SIGN OFF ON MAINTENANCE RECORDS
	79-01-05	INSP RPT (FOLLOWUP)	C	7903	C		RCPB PIPING HEAT TREATMENT TEMPERATURE
	79-02-01	INSP RPT (FOLLOWUP)	C	8008	C		QC INSPECTORS PROHIBITED FROM MAKING DETAIL CHECKS OF ITEMS
	79-02-02	INSP RPT (FOLLOWUP)	C	8006	C		INTERPRETATION OF THE REQUIREMENTS OF QPP 10.7 QUALITY TREND ANALYSIS
	79-02-03	INSP RPT (FOLLOWUP)	C	8006	C		QUESTION CONCERNING THE INTERCHANGEABILITY OF CLASS 1E CIRCUIT BREAKERS
	79-04-01	INSP RPT (FOLLOWUP)	C	7905	C		DG FOUNDATION MATERIAL CERT MISSING FOR A449 BOLTS
	79-04-03	INSP RPT (FOLLOWUP)	C	7905	C		LIQUID PENETRATION TEST RECORDS UNSATISFACTORY
	79-07-01	INSP RPT (FOLLOWUP)	C		C		JOB SITE SUPERVISOR'S RESPON FOR INSPECTION OF HEAT TRANSIENT
		INSP RPT (FOLLOWUP)	C	7909	C		
	79-07-02	INSP RPT (FOLLOWUP)	C	7909	C		NO REQUIREMENT TO EVALUATE IF HEAT TREAT CALIBR IS UNSAT

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 22

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT-NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	79-07-02	INSP RPT (FOLLOWUP)	C	8003	C		
	79-07-03	INSP RPT (FOLLOWUP)	C	7909	C		NO DIRECT QC FOR PIPING TACK WELDS
	79-07-04	INSP RPT (FOLLOWUP)	C	7909	C		NO CLEANLINESS CONTROL BETWEEN PIP FITUP AND ROOT WELDINGS
		INSP RPT (FOLLOWUP)	C	8003	C		
	79-07-05	INSP RPT (FOLLOWUP)	C	7909	C		HEAT TREAT TRAVELER ITEM 11 WRONG CODE ENTERED
	79-07-06	INSP RPT (FOLLOWUP)	C	7909	C		PT OF REMOVED THERMOCOUPLE NOT REQUIRED FOR HEAT TREAT
	79-07-07	INSP RPT (FOLLOWUP)	C	7909	C		GRINDING WHEELS NOT MARKED W/RED FOR STAINLESS
	79-07-08	INSP RPT (FOLLOWUP)	C	7909	C		MAXIMUM DEPRESSION IN CLADDING NOT SPECIFIED FOR QC INSPECTION
		INSP RPT (FOLLOWUP)	C	8003	C		
	79-09-01	INSP RPT (FOLLOWUP)	C	8003	C		FIELD CHECK OF CLEARANCE BETWEEN PIPE & STRUCTURE NOT REQUIRED
	79-11-01	INSP RPT (FOLLOWUP)	C	8115	C		UNIT 1 STEAM GENERATORS SWIM MOVEMENT

06/12/80

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 23

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	80-01-02	INSP RPT (FOLLOWUP)	C	8112	C		DEVELOP PROCEDURE FOR REVIEW OF POTENTIAL 50,55E ITEMS FOR REPORTABILITY
	80-01-03	INSP RPT (FOLLOWUP)	C	8003	C		REMOVAL OF EXCESS LIQUID PENETRANT MATERIALS FROM PIPE WELDMENTS
	80-01-05	INSP RPT (FOLLOWUP)	C	8003	C		PROGRAM FOR ARC STRIKE REPAIRS ON PIPING
	80-02-02	INSP RPT (FOLLOWUP)	C	8115	C		CONTAINMENT DOME SEGMENT DISTORTED EDGE CURVATURES
	80-05-01	INSP RPT (FOLLOWUP)	C	8228	C		CONCRETE THICKNESS OVER RESTEEL UNSATISFACTORY FOR M866
		INSP RPT (FOLLOWUP)	C	8318	C		
	80-08-01	INSP RPT (FOLLOWUP)	C	8112	C		RUSKIN FIRE DAMPER DEFORMATION PROBLEM
	80-12-01	INSP RPT (FOLLOWUP)	C	8015	C		TENSION CALCULATIONS FOR POWER ASSISTED CABLE PULLS
	80-12-02	INSP RPT (FOLLOWUP)	C	8015	C		CALIBRATION OF MEASURING AND TEST EQUIPMENT
		INSP RPT (FOLLOWUP)	C	8020	C		
	81-02-01	INSP RPT (FOLLOWUP)	C	8112	C		MATERIAL CALLOUT INCONSISTENCY FOR SOCKOLETS

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 24

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-02-02	INSP RPT (FOLLOWUP)	C	8112	C		RECEIPT INSPECTORS SPEC CHECKLIST DOES NOT CONTAIN ITEM FOR HT TREAT DOCUMENTATION
	81-02-03	INSP RPT (FOLLOWUP)	C	8112	C		FITUP & FINAL WELD CONE NOT SPECIFIED F/FULL PEN, PIPE BRANCH CONNECTION CORNER WELDS
	81-02-04	INSP RPT (FOLLOWUP)	C	8311	0		MAINTENANCE PROGRAM AND REQUIREMENTS
		INSP RPT (FOLLOWUP)	C	8317	0		
		INSP RPT (FOLLOWUP)	C	8329	0		
	81-02-05	INSP RPT (FOLLOWUP)	C	8112	C		INCOMPLETE 50,55E SURMITTAL
	81-02-06	INSP RPT (FOLLOWUP)	C	8112	C		IMPROPER IDENT. OF CLASS IE CONDUIT AND CABLE
	81-02-07	INSP RPT (FOLLOWUP)	C	8112	C		USE OF FLEXIBLE CONDUIT AS MEANS OF PROVIDING SEPARATION
	81-02-08	INSP RPT (FOLLOWUP)	C	8112	C		INCONSISTENCY BETWEEN PS&R AND IEEE-384 REQUIREMENTS
	81-04-01	INSP RPT (FOLLOWUP)	C	8322	0		TENDON DATA RECORD DISCREPANCIES
		INSP RPT (FOLLOWUP)	C	8329	0		

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 25

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-04-04	INSP RPT (FOLLOWUP)	C	8210	C		EDGE PROTECTORS ON CABLE TRAYS
	81-08-01	INSP RPT (FOLLOWUP)	C	8141	C		ASTM A354 BD PIPE RESTRAINT BOLT FAILURES
	81-09-01	INSP RPT (FOLLOWUP)	C	8317	C		HAZARDS WALKDOWN PROCEDURE NOT INITIATED-SEISMIC SUPPORT OVER BATTERY
		INSP RPT (FOLLOWUP)	C	8329	C		
		INSP RPT (FOLLOWUP)	C	8410	C		
	81-09-02	INSP RPT (FOLLOWUP)	C	8229	C		MAIN FEED PUMP PRESSURE TAP
	81-10-02	INSP RPT (FOLLOWUP)	0	8209	C		IDENTIFICATION OF PERSONS RECORDING TEST DATA
	81-10-04	INSP RPT (FOLLOWUP)	0	8209	C		CONTROL OF TEMPORARY FILTERS AND BLANK FLANGES
	81-10-05	INSP RPT (FOLLOWUP)	0	8209	C		REVERIFICATION OF TEST CONDITIONS FOLLOWING TEST INTERRUPTION
	81-10-06	INSP RPT (FOLLOWUP)	0	8213	C		TEST BRIEFING FOLLOWING SHIFT CHANGE
	81-10-07	INSP RPT (FOLLOWUP)	0	8209	C		QUALIFICATION PROGRAM FOR TEST PERSONNEL

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 26

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-12-02	INSP RPT (FOLLOWUP)	C	8229	C		VERIFICATION OF PROPER THREAD ENGAGEMENT ON SPRING HANGERS
	81-15-01	INSP RPT (FOLLOWUP)	C	8208	C		CONTAINMENT ELECTRICAL PENETRATIONS PRESSURIZATION PROVISIONS=ALL UNITS
	81-24-01	INSP RPT (FOLLOWUP)	C	8226	C		LEAK IN UNDERGROUND TEMPORARY FIRE LINE=DISTURBED BACKFILL
	81-24-02	INSP RPT (FOLLOWUP)	C	8318	C		ALL UNITS=EMERGENCY LIGHTING SYSTEM NOT AS DESCRIBED IN F8AR
	82-04-01	INSP RPT (FOLLOWUP)	O	8209	C		POSSIBLY OBSOLETE SPECS USED FOR INSTRUMENT CALIBRATION
	82-05-01	INSP RPT (FOLLOWUP)	M	8211	C		REVIEW QUALIFICATIONS OF RECENTLY WIRED RAD PROTECTION PERSONNEL
	82-06-01	INSP RPT (FOLLOWUP)	O		O		EXAMINE QUALIFICATIONS OF STATION WELDERS
	82-06-02	INSP RPT (FOLLOWUP)	O		O		EXAMINE QUALIFICATIONS OF NUCLEAR OPERATORS
	82-06-03	INSP RPT (FOLLOWUP)	M		C		EXAMINE QUALIFICATIONS OF RADIATION PROTECTION SUPERVISOR
		INSP RPT (FOLLOWUP)	M	8211	C		CLOSED BY PARA 3
	82-06-04	INSP RPT (FOLLOWUP)	O	8236	C		COMMENTS ON PROCEDURE 70AC-02Z02 (REVIEW OF STATION PROCEDURES)

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	82-06-05	INSP RPT (FOLLOWUP)	0		0		DEFINE SCOPE OF AUDIT PROGRAM TO BE DONE FOR STARTUP AND OPS QA
		INSP RPT (FOLLOWUP)	0	8306	0	0583	COMPLETED FOR QUALITY SYSTEMS TO BE DONE FOR STARTUP & OPS QA
		INSP RPT (FOLLOWUP)	0	8315	0		COMPLETED BY STARTUP QA OPEN UNTIL COMPLETED BY OPS QA
	82-06-06	INSP RPT (FOLLOWUP)	0		0		CLARIFY METHODS FOR EVALUATING ADEQUACY OF QA PROGRAM
		INSP RPT (FOLLOWUP)	0	8306	0		TO INCLUDE EVALUATION OF ADEQUACY OF STARTUP QA PROGRAM
	82-06-07	INSP RPT (FOLLOWUP)	0		0		DEFINE AUDIT INTERFACES AND METHODS OF DOCUMENTING FINDINGS
	82-06-08	INSP RPT (FOLLOWUP)	0	8306	0		COMMENTS ON SAC CHARTER
	82-06-09	INSP RPT (FOLLOWUP)	0		0		PROVIDE SAC EXPERTISE IN METALLURGY & RADIOCHEMISTRY
	82-06-10	INSP RPT (FOLLOWUP)	0	8306	C		COMMENTS ON PRB CHARTER
		INSP RPT (FOLLOWUP)	0	8315	C		
	82-06-11	INSP RPT (FOLLOWUP)	0	8236	C		CONTROL OF OUT-OF-SESSION PRB REVIEWS

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 28

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	82-06-12	INSP RPT (FOLLOWUP)	O	8236	C		REVIEW PRACTICES-REINCORPORATION OF PRB PROCEDURE-REVIEW COMMENTS
	82-08-01	INSP RPT (FOLLOWUP)	C	8318	C		CONCRETE EXPANSION ANCHORS
	82-11-01	INSP RPT (FOLLOWUP)	M	8335	C		ATTEND SITE ACCESS TRAINING ON RADIATION PROTECTION
	82-11-02	INSP RPT (FOLLOWUP)	M		C		SUPPLIES AND EQUIPMENT SEE PARA 8
		INSP RPT (FOLLOWUP)	M	8312	C		SEE REPORT PARA 8
	82-11-03	INSP RPT (FOLLOWUP)	M		C		ATTEND RWP TRAINING-OBSERVE RESPIRATORY PROTECTION TRAINING
		INSP RPT (FOLLOWUP)	M	8224	C		ATTEND 2ND DAY RWP TRAINING
		INSP RPT (FOLLOWUP)	M	8335	C		
	82-14-01	INSP RPT (FOLLOWUP)	C	8228	C		ELECTRICAL REDUNDANCY OF AUXILIARY FEEDWATER VALVES
	82-15-01	INSP RPT (FOLLOWUP)	O	8236	C		COMMENTS ON PROCEDURE 70AC-02202 (REVIEW OF STATION PROCEDURES)
	82-18-01	INSP RPT (FOLLOWUP)	O	8315	C		ALL TECH SPEC REVIEW REQUIREMENTS NOT INCLUDED IN PRB CHARTER

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 29

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	82-18-02	INSP RPT (FOLLOWUP)	0	8306	C		INDOCTRINATION OF SAC MEMBERS
	82-18-03	INSP RPT (FOLLOWUP)	0		0		SAC AUDIT RESPONSIBILITIES NOT DEFINED IN CHARTER OR PROCEDURES
	82-18-04	INSP RPT (FOLLOWUP)	0	8236	C		COMMENTS ON PROCEDURE 70AC-07Z02 (REVIEW OF STATION PROCEDURES)
	82-24-01	INSP RPT (FOLLOWUP)	M	8339	C		VERIFY GAS RAHWASTE SYSTEM COMPONENTS ARE AS DESCRIBED IN FSAR TBL 11.3
	82-25-02	INSP RPT (FOLLOWUP)	C	8329	C		SEISMIC CALCULATIONS MIGHT NOT REFLECT AS-BUILT CONDITIONS FOR MCRP(8)
	82-36-01	INSP RPT (FOLLOWUP)	0		0		INDOCTRINATION OF PRB & PRG MEMBERS RE PROCEDURE REVIEWS
	82-36-02	INSP RPT (FOLLOWUP)	0		0		CLARIFY MEANING AND USE OF "SAFETY RELATED" WRT PROCEDURES
	82-36-03	INSP RPT (FOLLOWUP)	0	8315	C		REVIEW AND APPROVAL REQUIREMENTS FOR PROCEDURE CANCELLATION
	82-36-04	INSP RPT (FOLLOWUP)	0	8326	C		DOCUMENT PRB REVIEW ON PROCEDURE COVER SHEET
	82-36-05	INSP RPT (FOLLOWUP)	0	8315	C		COMMENTS REGARDING USE OF PCN18
	82-36-06	INSP RPT (FOLLOWUP)	0	8315	C		COMMENTS ON PROCEDURE 70AC-07Z02 (PROCEDURE REVIEW AND APPROVAL)

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 30

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	82-36-07	INSP RPT (FOLLOWUP)	0	8306	C	0383	PREPARE, VERIFY & PROVIDE LISTING OF PLANT PROCEDURES
	83-01-01	INSP RPT (FOLLOWUP)	0	8306	C		EXAMINE DOCUMENT CONTROL FOR STARTUP MAINTENANCE AND QA/QC
	83-01-02	INSP RPT (FOLLOWUP)	0		0		EXAMINE TRAINING REQUIREMENTS FOR DUTY MANAGERS
	83-01-04	INSP RPT (FOLLOWUP)	0	8306	C		PRB MEMBERS AND ALTERNATES TO COMPLETE TRAINING BY 2/1/83
	83-02-02	INSP RPT (FOLLOWUP)	C	8311	C		SITING CONCERNS BY ALLEGER REQUIRE NRR RESPONSE
	83-02-03	INSP RPT (FOLLOWUP)	C	8317	0		COLD SPRINGING OF ECM PIPE REQUIRES APS ACTION
	83-03-01	INSP RPT (FOLLOWUP)	M		0		RAD PROT ORGANIZATION AND STAFFING CHANGES FOLLOWUP
		INSP RPT (FOLLOWUP)	M	8405	0		ORGANIZATION NOT FINALIZED
	83-03-02	INSP RPT (FOLLOWUP)	I	8312	C		REVIEW REPORT AND DOC IN REPORT CLOSE 803308 FOR ALL 3 DOCKETS
	83-03-03	INSP RPT (FOLLOWUP)	M	8405	C		SAMPLE POINT FOR PURGE MONITOR NOT AS SHOWN IN DRAWINGS
	83-03-04	INSP RPT (FOLLOWUP)	M	8339	C		RU-37 & 18 POWER ACCESS PURGE MONITORS LOCATION

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 31

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-03-05	INSP RPT (FOLLOWUP)	H		0		FUEL PLDR EXHAUST MONITOR RU-145 8146 SAMPLE POINT LESS THAN 5 DUCT-DIAM
	83-04-03	INSP RPT (FOLLOWUP)	C		0		PRACTICE OF ALLOWING REWORK WITHOUT NER
	83-06-01	INSP RPT (FOLLOWUP)	0	8315	C	0583	ISSUE INSTRUCTIONS ON DISPOSITION OF STARTUP QA/QC RECORDS
	83-06-02	INSP RPT (FOLLOWUP)	0	8315	C		ADDITIONAL COMMENTS ON PRB CHARTER
	83-06-03	INSP RPT (FOLLOWUP)	0		0		ADDITIONAL COMMENTS ON SAC CHARTER
	83-06-04	INSP RPT (FOLLOWUP)	0	8315	C		INDICATE STANDING OF SUGAH WRT DOACH AND FSAR 17.2
	83-06-05	INSP RPT (FOLLOWUP)	0		0		ISSUE POLICY STATEMENT/ENDORSEMENT OF STARTUP QA MANUAL
	83-06-06	INSP RPT (FOLLOWUP)	0		0		PROVIDE INTRODUCTORY STATEMENT FOR QA DEPT PROCEDURES MANUAL
	83-06-07	INSP RPT (FOLLOWUP)	0	8315	C	0583	UPDATE PROCEDURES LIST IN PLANT DOCUMENT REGISTER BY APRIL 29
	83-06-08	INSP RPT (FOLLOWUP)	0	8315	0		REISSUE PROCEDURE 70AC-02202 BY APRIL 15-SUBMIT PTR CHANGES
	83-09-01	INSP RPT (FOLLOWUP)	C	8322	C		UNAUTHORIZED CHANGING OF BRACKETS

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 32

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-09-02	INSP RPT (FOLLOWUP)	C	R317	C		QC DID NOT REVIEW WORK BUT SIGNED CARDS
	83-10-02	INSP PPT (FOLLOWUP)	C	R317	C		NCR ALLOWED CARLE SPLICING
	83-10-03	INSP RPT (FOLLOWUP)	C	R317	C		SCOTCHFILL 2200 USED ON 4160V TERMINATIONS
	83-10-04	INSP RPT (FOLLOWUP)	C	R317	C		ELECTRICAL QC INSPECTOR KNOWLEDGE
	83-12-01	INSP RPT (FOLLOWUP)	H		0		FSAR 12.5.2.1.1 ITEM B-HOODS & AIP SUPPLY RESOLUTION ADD OR DELETE
	83-12-02	INSP RPT (FOLLOWUP)	H	R339	C		INSUFFICIENT INSTRUMENTS OF DESCRIED TYPE=FSAR 12.5.2.2.2 ITEM A
	83-12-03	INSP RPT (FOLLOWUP)	H	R339	C		INSUFFICIENT INSTRUMENTS FSAR 12.5.2.2.2 ITEM C
	83-12-04	INSP RPT (FOLLOWUP)	H	R339	C		NO FAST-SLOW NEUTRON COUNTERS FSAR 12.5.2.2.2 ITEM G
	83-12-05	INSP RPT (FOLLOWUP)	H		0		FSAR 12.5.2.2.3 ITEM A-ONLY 26 OUT OF 30 FRISKERS RECEIVED
		INSP RPT (FOLLOWUP)	H	R339	0		28 OUT OF 30 REQUIRED FRISKES ON HAND
	83-12-06	INSP RPT (FOLLOWUP)	H	R339	C		FSAR 12.5.2.2.3 ITEM F-CONTAINERS NOT RECEIVED

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-12-07	INSP RPT (FOLLOWUP)	M	8339	C		FSAR 12.5.2.2.6-REVIEW INSTRUMENTS
	83-12-08	INSP RPT (FOLLOWUP)	M		O		STAND ALONE TLD-REM VERSUS TLD-REM/CRACB INTERFACE PAPA 6
		INSP RPT (FOLLOWUP)	M	8335	O		PERSONNEL TLD SYSTEM READY FOR OPERATIONS EXCEPT FOR THE CRACB/REM
		INSP RPT (FOLLOWUP)	M	8405	O		CRACS TO BE DELIVERED MARCH 1984 STILL NOT OPERATING PROPERLY
	83-12-09	INSP RPT (FOLLOWUP)	M		O		TRACABILITY OF KAMAN FACTORY CALIBRATION TO SEALED SOURCES USED
	83-12-10	INSP RPT (FOLLOWUP)	M	8335	C		PROCEDURE 75RPGZZ58-SOLID RADWASTE ACTIVITY DETN SEE REVISION
	83-12-11	INSP RPT (FOLLOWUP)	M		O		0737 IIF1 SYSTEM STATUS
	83-12-12	INSP RPT (FOLLOWUP)	M	8328	O		0737 IIF1 CALIBRATION RECORDS
		INSP RPT (FOLLOWUP)	M	8330	O		
	83-12-13	INSP RPT (FOLLOWUP)	M		O		0737 IIF1 REVISED GAS MONITOR DETECTORS
	83-12-14	INSP RPT (FOLLOWUP)	M		O		0737 IIF1 VENDOR CALIBRATION DATA

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 34

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-12-15	INSP RPT (FOLLOWUP)	M	8328	0		0737 IIF1 STEAM LINE MONITOR CASE CONSTRUCTION & SHIELDING
		INSP RPT (FOLLOWUP)	M	8330	0		
	83-12-16	INSP RPT (FOLLOWUP)	M		0		0737 IIF1 ATT2 IODINE & PARTICULATE SAMPLING CONSIDERATIONS
	83-12-17	INSP RPT (FOLLOWUP)	M	8328	0		0737 IIF1 ATT2 ISOKINETIC
		INSP RPT (FOLLOWUP)	M	8330	0		
	83-12-18	INSP RPT (FOLLOWUP)	M		0		0737 IIF1 ATT3 HIGH RANGE CONTAINMENT MONITORS
	83-12-19	INSP RPT (FOLLOWUP)	M		0		0737 IIB3 PASS
	83-12-20	INSP RPT (FOLLOWUP)	M		0		0737 IIB3 CLARIFICATION #89 OFFSITE LABORATORY
	83-12-21	INSP RPT (FOLLOWUP)	M		0		FSAR 12,5,2,2,5-NO PORTABLE CAM'S HAVE BEEN PROCURED
		INSP RPT (FOLLOWUP)	M	8405	0		CAM'S NOT ORDERED-LICENSEE TAKING ACTION TO CORRECT
	83-12-22	INSP RPT (FOLLOWUP)	M		0		FSAR 12,5,2,2,5-EXAMINE FIXED & MOVABLE AIR MONITORS

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 35

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-01	INSP RPT (FOLLOWUP)	S	8401	C	FISH	STAFFING OF CORP EP PLANNING GROUP NOT YET FINALIZED
	83-14-02	INSP RPT (FOLLOWUP)	S	8401	C	FISH	STAFFING OF ONSITE EP GROUP NOT YET DETERMINED
	83-14-03	INSP RPT (FOLLOWUP)	S	8401	C	FISH	TRAINING PROGRAM NOT DEVELOPED FOR EP PLANNERS
	83-14-04	INSP RPT (FOLLOWUP)	S	8401	O		EP PLAN & STAFF AUGMENTATION NOT CONSISTENT WITH NUREG-0654
	83-14-05	INSP RPT (FOLLOWUP)	S	8401	C	FISH	HP ASSIGNMENTS GREATER THAN AVAILABLE
	83-14-06	INSP RPT (FOLLOWUP)	S	8401	O		CORP EMER CTR PROCEDURES NOT SUBMITTED FOR REVIEW
	83-14-07	INSP RPT (FOLLOWUP)	S	8401	C	FISH	EQUIP IN CORP EMER CTR NOT COMPLETED
	83-14-08	INSP RPT (FOLLOWUP)	S	8401	C	FISH	EP TRAINING FOR RESPONSE ORGS NOT APPROVED
	83-14-09	INSP RPT (FOLLOWUP)	S	8401	C	FISH	EP TRAINING INSTRUCTOR QUALIFICATIONS NOT ESTABLISHED
	83-14-10	INSP RPT (FOLLOWUP)	S	8401	C	FISH	CORP OFFSITE TRAINING PROGRAM INCOMPLETE
	83-14-11	INSP RPT (FOLLOWUP)	S	8401	O		TRAINING IN USE OF PAB NOT ESTABLISHED

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 36

DOCKET	ITEM-NO	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-12	INSP RPT (FOLLOWUP)	S	8401	C	FISH	HANDS-ON TRAINING NOT INCLUDED IN EP COURSES
	83-14-13	INSP RPT (FOLLOWUP)	S	8401	C	FISH	EP TRAINING NOT YET COMPLETED
	83-14-14	INSP RPT (FOLLOWUP)	S	8401	O		ER, T6C, 08C & EDC NOT COMPLETED
	83-14-15	INSP RPT (FOLLOWUP)	S	8401	O		PAS NOT INSTALLED
	83-14-16	INSP RPT (FOLLOWUP)	S	8401	O		EFFLUENT SAMPLING EQUIP NOT INSTALLED
	83-14-17	INSP RPT (FOLLOWUP)	S	8401	O		BACKUP LAB NOT FULLY EQUIPPED AND LICENSED
	83-14-18	INSP RPT (FOLLOWUP)	S	8401	C	FISH	ASSEMBLY AREAS NOT CLEARLY MARKED
	83-14-19	INSP RPT (FOLLOWUP)	S	8401	C	FISH	DECON AREAS NOT OPERATIONAL
	83-14-20	INSP RPT (FOLLOWUP)	S	8401	C	FISH	EMER KITS NOT STOCKED IN ACCORD WITH EPIP NO. 38
	83-14-21	INSP RPT (FOLLOWUP)	M	8401	O		AREA, PROCESS & EFFLUENT MONITORING SYSTEMS NOT INSTALLED
	83-14-22	INSP RPT (FOLLOWUP)	S	8401	O		NONRADIATION MONITORS NOT INSTALLED

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 37

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-23	INSP RPT (FOLLOWUP)	S	8401	C	FISH	ALTERNATE SOURCE OF MET DATA NOT IDENTIFIED
	83-14-24	INSP RPT (FOLLOWUP)	S	8401	C	FISH	PROVISIONS FOR NOTIFYING CR PERSONNEL OF WEATHER CONDITIONS NEEDED
	83-14-25	INSP RPT (FOLLOWUP)	S	8401	O		ERFDADS NOT INSTALLED
	83-14-26	INSP RPT (FOLLOWUP)	M	8401	C		RESPIRATORY PROGRAM NOT IMPLEMENTED
		INSP RPT (FOLLOWUP)	M	8405	C		
	83-14-27	INSP RPT (FOLLOWUP)	S	8401	C	FISH	PROTECTIVE CLOTHING & CLEANING PROGRAMS NOT COMPLETED
	83-14-28	INSP RPT (FOLLOWUP)	S	8401	C	FISH	DAMAGE CONTROL & EQUIP MAINTENANCE PROGRAMS NOT ESTABLISHED
	83-14-29	INSP RPT (FOLLOWUP)	M	8401	O		PROCEDURES FOR PAS NOT WRITTEN
	83-14-30	INSP RPT (FOLLOWUP)	M	8401	O		PROCEDURES FOR EFFLUENT MONITORS NOT WRITTEN
	83-14-31	INSP RPT (FOLLOWUP)	S	8401	C	FISH	DISTRIBUTION OF EQ PLAN NOT AS STATED IN EPIR'S
	83-14-32	INSP RPT (FOLLOWUP)	S	8401	O		CARD READER SYSTEM NOT OPERATIONAL

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 38

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT-NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-14-33	INSP RPT (FOLLOWUP)	S	8401	C	----	AGREEMENTS WITH OFFSITE AGENCIES NOT COMPLETED
	83-14-34	INSP RPT (FOLLOWUP)	S	8401	C	FISH	DRILLS & PRACTICE EX NOT CONDUCTED
	83-14-35	INSP RPT (FOLLOWUP)	S	8401	C	FISH	INTEGRATED RECORDS SYSTEM NEEDED
	83-14-36	INSP RPT (FOLLOWUP)	S	8401	C	FISH	TRAINING NEEDED WHEN EPIP'S ARE MADE
	83-14-37	INSP RPT (FOLLOWUP)	S	8401	C	FISH	EP TRAINING NOT CONSISTENT WITH EPIP'S
	83-14-38	INSP RPT (FOLLOWUP)	S	8401	C	FISH	INCONSISTENCIES IN EPIP-36 & CORP EP TRAINING
	83-14-39	INSP RPT (FOLLOWUP)	S	8401	C	FISH	TRAINING FOR FIRE TEAM MEMBERS
	83-14-40	INSP RPT (FOLLOWUP)	S	8401	C	FISH	TRAINING FOR CO NURSE
	83-14-41	INSP RPT (FOLLOWUP)	S	8401	C	FISH	SEAL SYSTEM FOR EMER KITS NEEDED
	83-14-42	INSP RPT (FOLLOWUP)	S	8401	C	FISH	DOSIMETRY FOR EMER KITS
	83-14-43	INSP RPT (FOLLOWUP)	S	8401	C	FISH	CONSOLIDATE EQUIPMENT

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 39

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	83-14-44	INSP RPT (FOLLOWUP)	S	R401	C	FISH	INCREASE MET SYSTEM CHECKS
	83-14-45	INSP RPT (FOLLOWUP)	S	R401	O		MAKE CHANGES TO PROCEDURES
	83-14-46	INSP RPT (FOLLOWUP)	S	R401	O		REVIEW EAL-18 TO THE CRITERIA IN NUREG-0654
	83-14-47	INSP RPT (FOLLOWUP)	S	R401	O		REVIEW EPIP-14A FOR PAS DATA IN CALCULATING RELEASE RATES
	83-14-48	INSP RPT (FOLLOWUP)	S	R401	C	FISH	COMPARE CALCULATIONAL RESULTS WITH ENVIRONMENTAL SURVEYS
	83-14-49	INSP RPT (FOLLOWUP)	S	R401	C	FISH	REVIEW CONCERNS OF ARRA
	83-15-02	INSP RPT (FOLLOWUP)	O	R326	C		COMMENTS ON PROCEDURE 70AC-02202
	83-15-03	INSP RPT (FOLLOWUP)	O		O		COMMENTS ON PROCEDURE 40AC-92202
	83-15-04	INSP RPT (FOLLOWUP)	O		O		COMMENTS ON PROCEDURE 70AC-02215
	83-15-05	INSP RPT (FOLLOWUP)	O		O		UPDATE PDR LISTING BY 6/15/83 REVIEW FOR COMPLETENESS
	83-15-06	INSP RPT (FOLLOWUP)	O		O		ISSUE ALL ADMIN CONTROL PROCEDURES BY 7/1/83

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 40

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-15-07	INSP RPT (FOLLOWUP)	0		0		COMMENTS ON PRB CHARTER
	83-17-01	INSP RPT (FOLLOWUP)	C	8322	C		APS TO RESOLVE PSE REQTS FOR CL2 ECCS SYSTEMS
		INSP RPT (FOLLOWUP)	C	8406	C		
	83-17-02	INSP RPT (FOLLOWUP)	C		0		SIT SAFEND TO NOZZLE WELD REQUIRES RT
	83-17-03	INSP RPT (FOLLOWUP)	C		0		FLEX MEMBRANE FORGING MAY REQUIRE REEXAM
	83-20-01	INSP RPT (FOLLOWUP)	H	8409	C		SEND SPIKE CONTAINING SR89, 90, FESS, H3, MIXEC GAMMA & ALPHA FROM RESL
	83-22-01	INSP RPT (FOLLOWUP)	C		0		LOWER CORE SUPPORT WELDS LACK OF PENET & SACKGOUGE-CE
	83-22-02	INSP RPT (FOLLOWUP)	C		0		TRAINING RECORDS NEED ANNOTATIONS WCS
	83-22-03	INSP RPT (FOLLOWUP)	C	8410	C		LIMITORQUE OPERATORS MAY CHAFE MOTOR LEADS
	83-25-01	INSP RPT (FOLLOWUP)	R		0		FOLLOWUP OF RTD THERMOWELL FAILURES
	83-26-01	INSP RPT (FOLLOWUP)	0		0		REVIEW & APPROVAL OF POST-OL STARTUP TEST PROCEDURES

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 41

TICKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-26-02	INSP RPT (FOLLOWUP)	0		0		RG 1,33 ITEMS APPARENTLY NOT COVERED BY PLANT PROCEDURES
	83-30-01	INSP RPT (FOLLOWUP)	M		0		FUEL BLDG ISO PROBE-SAMPLE LINE PARA. 4,A
	83-30-02	INSP RPT (FOLLOWUP)	M		0		REVIEW NOBLE GAS CHAMBER NRG RESP-PARA. 4,C
	83-32-01	INSP RPT (FOLLOWUP)	C	B346	C		THERMAL SLEEVE & THERMOWELL FAILURES IN REACTOR COOLANT SYSTEM
	83-33-01	INSP RPT (FOLLOWUP)	M		0		CRACKS RMS INTERFACE REVIEW
	83-35-01	INSP RPT (FOLLOWUP)	M	A339	C		RAD PROT & CHEM TECH QUALIFICATIONS AS PER ANSI-3,1-1978 PARA 4,5,7
	83-35-02	INSP RPT (FOLLOWUP)	M		0		TRAINING OF ESCORTS CONCERNING RAD PROTECTION RESPONSIBILITIES
	83-38-01	INSP RPT (FOLLOWUP)	R		0		QUALIFICATION OF CONTAINMENT WATER LEVELS
	83-39-01	INSP RPT (FOLLOWUP)	M	A405	C		PROCEDURE CHANGE TO PROVIDE FOR STOP WORK OR EVACUATION ORDERS
	83-39-02	INSP RPT (FOLLOWUP)	M	A405	C		RESPIRATOR & FILTER TEST BENCH NOT OPERABLE
	83-39-03	INSP RPT (FOLLOWUP)	M		0		BREATHING AIR SUPPLY SYSTEM FOR USE WITH AIRLINE-SUPPLIED MASKS & HOODS

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 42

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-39-03	INSP RPT (FOLLOWUP)	M	8405	0		DIESEL POWERED COMPRESSOR BEING CONSIDERED FOR AIR SUPPLY BACKUP
	83-39-04	INSP RPT (FOLLOWUP)	M		0		VERIFY RADWASTE TANK VOLUMES
	83-41-03	INSP RPT (FOLLOWUP)	M		0		CONTROL ROOM RMS ANNUNCIATOR CAPABILITIES & PROCEDURES FOR ALARM RES
	83-41-04	INSP RPT (FOLLOWUP)	M		0		REVIEW UNMONITORED EFFLUENT RELEASE PATHWAYS SUCH AS TURBINE BUILDING
	84-01-01	INSP RPT (FOLLOWUP)	S		0		GRAB SAMPLE CROSS REFERENCE TO SAFETY PRECAUTIONS
	84-01-02	INSP RPT (FOLLOWUP)	S		0		EPIP-16 NOTIFICATION OF HIGH RADIATION IN 4.3.1.2
	84-01-03	INSP RPT (FOLLOWUP)	S		0		SURVEY METERS FOR AIRBORNE IODINE CONCENTRATIONS IN EPIP-17
	84-01-04	INSP RPT (FOLLOWUP)	S		0		EVACUATION AT 2 HR/HR PER EPIP-20
	84-01-05	INSP RPT (FOLLOWUP)	S		0		PERSONNEL MONITORING FOR REPAIR PERSONS
	84-01-06	INSP RPT (FOLLOWUP)	S		0		BACKUP DOSE CALCULATIONS CAPABILITY
	84-04-02	INSP RPT (FOLLOWUP)	C		0		EVALUATION OF STANDARD CONDUIT ELLS

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 43

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-04-03	INSP RPT (FOLLOWUP)	C		0		CRAFT AND FE EXCELLENCE
	84-05-01	INSP RPT (FOLLOWUP)	M		0		LI TETRABORATE PANASONIC 809 TLD NEUTRON PERSONNEL MONITORING FOLLOWUP
	84-05-02	INSP RPT (FOLLOWUP)	M		0		REVIEW ALARA PROCEDURES
	84-07-01	INSP RPT (FOLLOWUP)	C		0		REEXAMINE COLD LICENSEE TRAINING RECORDS
	84-09-01	INSP RPT (FOLLOWUP)	M		0		DEVELOP QC PROCEDURES FOR GAMMA SPECTROSCOPY & LLD CRITERIA
	84-09-02	INSP RPT (FOLLOWUP)	M		0		TRAINING & PROFICIENCY OF GAMMA SPECTROSCOPY ANALYSTS (SEE PG 5)
	84-10-02	INSP RPT (FOLLOWUP)	C		0		ACTIONS ON FP LOOSE BEAM CLAMPS AND WELDED STUDS
	84-10-04	INSP RPT (FOLLOWUP)	C		0		HVAC WALKDOWN - ADEQUATE FOR SEISMIC INPUT?

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 44

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IN-81-36	INFO NOTICE	M	8224	C		CLARIFICATION OF PLACEMENT OF PERSONNEL MONITORING DEVICES FOR EXTERNAL USE
	IN-82-05	INFO NOTICE	S		O		DRUG RELATED INCIDENTS
	IN-82-07	INFO NOTICE	S		O		SCREENING OF ONSITE PERSONNEL
	IN-82-31	INFO NOTICE	M	8224	C		OVEREXPOSURE OF DIVER DURING WORK IN FUEL STORAGE POOL
	IN-82-36	INFO NOTICE	M	8224	C		RESPIRATOR USERS WARNING FOR CERTAIN 5-MINUTE EMERGENCY ESCAPE SCBA
	IN-82-49	INFO NOTICE	M	8312	C		CORRECTION FOR SAMPLE CONDITIONS AIR & GAS MONITORS
	IN-82-51	INFO NOTICE	M	8312	C		OVEREXPOSURE IN PWR CAVITIES
	IN-83-10	INFO NOTICE	M	8312	C		INFO NOTICE CLARIFICATION FOR USE OF NRC CERTIFIED TRANSPORT PACKAGES
	IN-83-16	INFO NOTICE	M	8312	C		INFO NOTICE EXOTHERMIC REACTION IN RESINS
	IN-83-17	INFO NOTICE	O		O		DIESEL GENERATOR AUTO-START LOGIC
	IN-83-21	INFO NOTICE	M	8335	C		DEFECTIVE EMERGENCY USE RESPIRATOR BIOPAK 60

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 45

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	IN-83-27	INFO NOTICE	S		0		OPERATIONAL RESPONSE TO EVENTS CONCERNING DELIBERATE ACTS AGAINST PLANT (COR W/S B-0)
	IN-83-28	INFO NOTICE	S	8401	C		CRITERIA FOR GENERAL EMERGENCY PROTECTIVE ACTION RECOMMENDATIONS
	IN-83-33	INFO NOTICE	M	8335	C		SAMPLING OF CONTAMINATED OIL
	IN-83-36	INFO NOTICE	S		0		RECOMMENDED REMOVAL OF CERTAIN SECURITY FEATURES FOR SAFETY ASSURANCE
	IN-83-52	INFO NOTICE	M	8335	C		RADWASTE GAS EVENTS
	IN-84-07	INFO NOTICE	S		0		DESIGN BASIS THREAT AND REVIEW OF VEHICULAR ACCESS CONTROL
	IN-84-15	INFO NOTICE	M		0		INFO NOTICE-REPORTING OF RADIOLOGICAL RELEASES
	IN-84-34	INFO NOTICE	M		0		RESPIRATOR USERS WARNING-SCBA 4500 PSI LUXFER CYLINDERS

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 46

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	FW-06-16	OTHER	M	A224	C		IE NOTICE 82-18-ASSMT. OF INTAKES OF RADMATERIAL BY WORKERS
	FW-11-16	OTHER	M	A312	C		IE NOTICE 82-43-DEFICIENCIES IN VENTILATION SYSTEMS
	PJ-05-09	OTHER	O		O		VERIFY DUTIES AND RESPONSIBILITIES DEFINED FOR STA'S
	PJ-05-10	OTHER	O		O		VERIFY IMPLEMENTATION OF INDEPENDENT VERIFICATION PROGRAM
	PJ-05-11	OTHER	O		O		PROVIDE METHOD OF MARKING OUT-OF-CAL OR INOP INSTRUMENTS
	PJ-08-24	OTHER	F		O		DETERMINE WHETHER DUCOMMUN METAL IS ON APPROVED BIDDER'S LIST
	PJ-09-16	OTHER	O		O	REF	CONDUCT NATL CIRCULATION COOLDOWN TEST PRIOR TO FIRST REFUELING REF VAN BRUNT LTR 1/27/83
	PJ-10-24	OTHER	C		O	0183	DEFINE CRITERIA FOR EVAL OF CONST QA/CDR'S-EISENHUT MEMO 10/13/82
	PJ-10-25	OTHER	C		O	0683	EVALUATE CONST QA PROGRAM/SIGNIF CDR'S-EISENHUT MEMO 10/13/82
	PJ-10-26	OTHER	O		O	0783	PROVIDE SUMMARY REPT ON PREOP TEST PROG-EISENHUT MEMO 10/13/82
	PJ-10-27	OTHER	O		O	0784	PROVIDE REPORT RE REVIEW OF STARTUP PROG-EISENHUT MEMO 10/13/82

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO-VERDE UNIT 1

PAGE 47

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	PJ-82-01	OTHER	R		C		SER SECTION 3.5.2-MISSILE PROTECTION FOR HYDROGEN RECOMBINERS
		OTHER	R	A227	C		
	PJ-82-02	OTHER	R		0		SER SECTION 7.2.3-CPC SOFTWARE PROCEDURES
	PJ-82-03	OTHER	0		0		SER SECTION 7.3.2.1-I&C PROCEDURES AND TESTING (4 ITEMS)
	PJ-82-04	OTHER	0		0		SER SECTION 7.4.3-IE BULLETIN 79-27 PROCEDURES
	PJ-82-05	OTHER	0		0		SER SECTION 9.5.1-FIRE PROTECTION MODIFICATIONS (3 ITEMS)
	PJ-82-06	OTHER	0		0		SER SECTION 9.5.1.7-FIRE PROTECTION ADMIN CONTROLS & PROCEDURES
	PJ-82-07	OTHER	0		0		SER SECTION 13.1.2.3-TRAINING FOR OPS SUPERINTENDENT (ANSI/ANS 3.1)
	PJ-82-08	OTHER	0		0		SER SECTION 13.5.2-TRAINING OF OPERATORS ON OP/MAINT PROCEDURES
	PJ-82-09	OTHER	0		0		SER SECTION 15.3.9-ATWS PROCEDURES
	PJ-82-10	OTHER	0		0		SER APPENDIX C ITEM A-44-STATION BLACKOUT PROCEDURES

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 46

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	TM-IE-11	OTHER	R	8238	C		TMI ITEM II-E-11-AUXILIARY SYSTEM FEEDWATER EVALUATION
	TM-IE-12	OTHER	R	8238	C		TMI ITEM II-E-12-PART 2 AUXILIARY FEEDWATER SYS FLOW RATE INDICATION

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 09

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	TI-00-01	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-15
	TI-00-05	TEMP INSTR (TI)	C		0		INSTRUCTIONS FOR VERIFICATION OF TMI ACTION PLAN=LICENSEE ACTIONS
	TI-12-03	TEMP INSTR (TI)	C	7906	0		VERIFY COMPLIANCE WITH ASME CERTIFICATION SYSTEM REQUIREMENTS
	TI-12-08	TEMP INSTR (TI)	C	8311	C		TI FOR IEB 81-08 SOILS AND BACKFILL
	TI-13-01	TEMP INSTR (TI)	0	GZ	C		TRANSFER OF SRP REVIEW FROM NRR TO IE
	TI-14-01	TEMP INSTR (TI)	0		0		REV 2-TASK I,B,1,2 LEAD RESP CHANGE TO NRR FOR EVAL OF OLIS
	TI-15-27	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESPONSE TO IE BULLETIN 79-02 (ANCHOR BOLTS)
	TI-15-28	TEMP INSTR (TI)	C		0		INSP REQ TO REVIEW LICENSEE RESP TO IEB 7902, REV 1
	TI-15-29	TEMP INSTR (TI)	C		0		INSPECTION REQUIREMENTS FOR IE BULLETIN 79-14
	TI-15-37	TEMP INSTR (TI)	C	8311	C		IE BULLETIN FOLLUP 80-11 MASONARY WALLS IN PROXIMITY TO SAFETY SYSTEMS
	TI-15-44	TEMP INSTR (TI)	C		0		TMI ACTION PLAN INSPECT RQMTS HP & EMERGENCY PLANNING-REV. 2

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 50

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50520	TI-15-53	TEMP INSTR (TI)	C		0		NUREG-0737 INSPECTION RQMTS FOR SYSTEM RQMTS
	TI-15-54	TEMP INSTR (TI)	C		0		I&E RESPONSIBILITY FOR REVIEW OF TMI SERIES
	TI-15-57	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR EMERGENCY PROCEDURES-DUE EARLY 82
	TI-15-59	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 1/82
	TI-15-60	TEMP INSTR (TI)	C		0		0737 INSPECTION LISTING FOR MODS DUE 7/82

06/12/84

REGION 5
OUTSTANDING ITEMS REPORT
OPEN & CLOSED
PALO VERDE UNIT 1

PAGE 51

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	78-08-02	INSP RPT (UNR)	C	7902	C		BEAM DEFLECTION RECORDS-DATA NOT ENTERED
	78-09-03	INSP RPT (UNR)	C	7901	C		CONTROLS FOR NONCONFORMING ITEMS IN STORAGE-TRUMPLATE, ETC.
	79-01-02	INSP RPT (UNR)	C	7903	C		WELDS ON ENDS OF MOTOR CONTROL CENTERS
	79-03-01	INSP RPT (UNR)	C	7904	C		ASSEMBLY TECHNIQUES-INSP CRITERIA CONTAINMENT DOME LINER SYSTEM
	79-06-01	INSP RPT (UNR)	C	7909	C		CONTROL OF COLD SPRINGING OF PIPE FOR FITUP
	80-01-04	INSP RPT (UNR)	C		C		DISPOSITION OF APPARENT NONRELEVANT LP INDICATIONS BY NDE EXAMINERS
		INSP RPT (UNR)	C	8003	C		
	81-04-02	INSP RPT (UNR)	C		O		COMPLIANCE W/AWS STRUCTURAL STEEL PREHEAT & RECORDS REQUIREMENTS
		INSP RPT (UNR)	C	8329	O		
	81-10-01	INSP RPT (UNR)	O		C		REISSUE STARTUP ADMIN PROCEDURES
		INSP RPT (UNR)	O	8230	C		ADMINISTRATIVE CONTROLS

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 52

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-10-03	INSP RPT (UNR)	0	8230	C		POST-MAINTENANCE REVIEW OF WORK REQUESTS FOR IMPACT ON TEST RESULTS
	82-17-01	INSP RPT (UNR)	C	8231	C		ACCEPTANCE OF ARC STRIKES BASED ON VISUAL INSP CRITERIA
	83-01-03	INSP RPT (UNR)	0	8326	C		VERIFY PROPER ORIENTATION OF CHECK VALVES IN DIESEL AIR START SYSTEMS
	83-08-01	INSP RPT (UNR)	C	8311	C		RCP SUPPORT STRESS RELIEF TEMP APPEARS LOW
	83-36-01	INSP RPT (UNR)	C	8404	0		CORROSION OF BURIED PIPE
		INSP RPT (UNR)	C	8410	0		
	84-10-01	INSP RPT (UNR)	C		0		QUESTIONS ON VIKING SEISMIC ANALYSIS OF FP HGRS

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 53

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	79-04-27	50,55E RPT	F	8208	C		50,55E-UNITS 1 & 2 POLAR CRANE SUPPORT-GIRDER WELDING
	80-01-10	50,55E RPT	F	8208	C		50,55E-ASME SEC XI VT PRESERVICE EXAM REVEALING INDICATIONS IN PULLMAN POWER ELBOWS
	80-04-10	50,55E RPT	F	8208	C		50,55E-INSPECTION OF ASME SEC 111, CLASS 3 PIPE WELDS
	80-05-25	50,55E RPT	F	8208	C		50,55E-ERROR IN CALCULATION FOR SEISMIC INSTRUMENT TUBE SUPPORT
	80-05-26	50,55E RPT	F	8208	C		50,55E-SEISMIC CAT INSTRUMENT SUPPORT DESIGN CALCULATIONS SHOW DESIGN TO BE INADEQUATE
	80-05-27	50,55E RPT	F	8208	C		50,55E-UNDERSIZED FILLET WELDS FOR STRUCTURAL STEEL W/RESPECT TO AWS D.1.1 & A.15C
	80-05-28	50,55E RPT	F	8208	C		50,55E-ITT-GRINNELL SWAY STRUTS HAVE UNDERSIZED FILLET WELDS W/RESPECT TO ASME SEC 111
	80-06-03	50,55E RPT	F	8208	C		50,55E-OPERABILITY FAILURE OF VERTICAL FIRE DAMPERS
	80-06-04	50,55E RPT	F	8208	C		50,55E-NAMCO CONTROLS SERIES EA 180 LIMIT SWITCHES
	80-06-06	50,55E RPT	F	8208	C		50,55E-DOWELL REBAR OMISSION DURING CONCRETE PLACEMENT (UNIT 3 AUX BUILDING)
	80-06-12	50,55E RPT	F	8208	C		50,55E-CLOSURE OF COMSHID CONTAINMENT GAS ANALYSIS SYS PUMP VLV

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 54

DOCKET	ITEM=NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	80-06-21	50,55E RPT	F	A208	C		50,55E-INADEQUATE DESIGN OF REBAR IN WALLS OF MAIN STM SUPPORT STRUCTURE F/UNIT 1
	80-07-28	50,55E RPT	F	A208	C		50,55E-REBAR SHOWN IN DRAW MAY NOT ACCURATELY REFLECT ACTUAL DESIGN IN SOME CASES
	80-08-22	50,55E RPT	F	A208	C		50,55E-DOWEL REBAR OMISSION F/UNIT 2 CONTROL BLDG WALL POVR
	80-09-04	50,55E RPT	F	A208	C		50,55E-INADEQUATE CONCRETE STRENGTH ACHIEVED W/PNEUMATICALLY PLACED MORTAR REPAIR
	80-09-16	50,55E RPT	F	A208	C		50,55E-WELD DEFICIENCIES IN MAIN CONTROL PANELS
	80-09-17	50,55E RPT	F	A208	C		50,55E-TEMP DETECTION CONTROLLERS USED ON CT1-NUCLEAR AIR HANDLING & FILTRATION EQUIPMENT
	80-10-02	50,55E RPT	F	A208	C		50,55E-PIT MOTOR SHAFT BREAKAGE IN HYDROGEN MONITORS
	80-11-20	50,55E RPT	F	A208	C		50,55E-LOOSE BUSHINGS IN ITT-GRINNELL SWAY STRUTS
	80-12-12	50,55E RPT	F	A208	C		50,55E-PIPE SPOOLS PULLED TO FACILITATE INSTALLATION OF PIPE SUPPORT WELDS
	80-12-13	50,55E RPT	F	A208	C		50,55E-CLASS I/E CONDUCTORS WITHIN 6" OF NONCLASS I/E CONDUCTORS
	81-01-28	50,55E RPT	F	A208	C		50,55E-INDICATION REVEALED IN SITE RT OF PIPING SPOOLS WHICH WERE PREVIOUSLY ACCEPTED

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 55

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	81-03-20	50,55E RPT	F	8208	C		50,55E-SHIVEL BEARINGS ON RCP HORIZONTAL SUPPORT COLUMNS CANNOT BE ROTATED
	81-07- A	50,55E RPT	F	8208	C	0802	50,55E-FOXBORO RECORDER MOD 226 MAY NOT DRIVE FORWARD & BACKWARD DUE TO POSSIBLE SHORT CIRCUIT (DER 81-19)
	81-08-18	50,55E RPT	F	8208	C	0918	50,55E-AUX FEED PUMPS SEIZE-UP DURING MAINTENANCE-BINGHAM- WILLAMETTE PUMPS (DER 81-25)
	81-10-14	50,55E RPT	F	8208	C	1114	50,55E-FOXBORO DISPLAYS SHIPPED BEFORE QUAL TESTING-SUBSEQUENTLY FAILED TEST (DER 81-37)
	81-12- C	50,55E RPT	F		O	0130	50,55E-DIESEL GEN CONTROL CABINET WIRING-LACK OF REQ SEP BY COOPER ENERGY SERVICES (DER 81-51)
	81-12- D	50,55E RPT	F		O	0130	50,55E-LOOSE ANTI-ROTATION PINS IN CONTAINMENT SPRAY AND LPSI PUMPS (DER 81-52)
	81-12- E	50,55E RPT	F		O	0130	50,55E-MAIN CONTROL PANEL WIRING-LACK OF REQ SEP BY COMSIP CUSTOM LINE (DER 81-53)
	81-12- F	50,55E RPT	F	8208	C	0130	50,55E-STM GEN 2 HAS LINEAR INDICA- TION 1/2" LONG VISIBLE ON INSIDE OF STM OUTLET NOZZLE WELD (DER 81-54)
	83-01-28	50,55E RPT	M		C	0228	50,55E-HVAC TEST PROCED DO NOT MEET ANSI N 510 DER 83-4
		50,55E RPT	M	8312	C		50,55E-FINAL LICENSEE RPT REC REVIEWED ONSITE W/APS DA/OC
	83-04-06	50,55E RPT	O		O	0505	50,55E-APS STARTUP OC NOT QUALIFIED-DER 8320

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 56

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	83-04-07	50.55E RPT	0		0	0505	50.55E=LPSI PUMP OPERATED W/SUCTION VALVE SHUT-DER 8321
	84-01=C	50.55E RPT	C		0		50.55(E): CONTROL OF RETESTING ACTIVITIES DETERMINED NOT TO BE REPORTABLE
	84-02=C	50.55E RPT	C		0		50.55(E): EXCESSIVE RUST SI AND CH VALVES (ALL UNITS) FINAL RPT EXPECTED 6/21/84
	84-03=C	50.55E RPT	C		0		50.55(E): FEEDWATER ISOLATION VALVE STUCK DURING TESTING - FINAL RPT EXPECTED 5/31/84
	84-04=C	50.55E RPT	C		0		50.55(E): FOXBORO ALARM MODULE DEFECTS (ALL UNITS) - FINAL RPT EXPECTED 6/12/84
	84-08=C	50.55E RPT	C		0		50.55(E): BARTON MDL 763 TRANSMITTS DO NOT MEET SPECS (ALL UNITS) FINAL RPT EXPECTED 5/18/84
	84-10=C	50.55E RPT	C		0		50.55(E): FAILURE OF SINGLE ELEMENT RTD'S (ALL UNITS) FINAL REPORT EXPECTED 6/1/84
	84-11=C	50.55E RPT	C		0		50.55(E): PUMP INSTRUMENTATION CONDUIT CONTAMINATED WITH CHLORIDES FINAL RPT EXPECTED 5/29/84
	84-12=C	50.55E RPT	C		0		50.55(E): ZONE III VIOLATION OF RCP 1A AND SG #1 FINAL RPT EXPECTED 6/1/84
	84-13=C	50.55E RPT	C		0		50.55(E): HVAC ACCEPTANCE CRITERIA (ALL UNITS) - FINAL RPT EXPECTED 12/14/84
	84-15=C	50.55E RPT	C		0		50.55(E): UNDERSIZED PIPE RESTRAINT SUPPORT WELDS (ALL UNITS)-FINAL RPT EXP 8/3/84

06/12/84

REGION 5
 OUTSTANDING ITEMS REPORT
 OPEN & CLOSED
 PALO VERDE UNIT 1

PAGE 57

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	84-16-C	50,55E RPT	C		0		50,55(E): UNDERSIZED ESFAS RELAY CABINET BASEPLATS (ALL UNITS) FINAL RPT EXPECTED 6/29/84
	84-17-C	50,55E RPT	C		0		50,55(E): CORE SHROUD ENVELOPE REPORTABLE
	84-18-C	50,55E RPT	C		0		50,55(E): WIRING ERROR ON LP81 B PUMP SWITCH=FINAL RPT EXPECTED 6/12/84
	84-19-C	50,55E RPT	C		0		50,55(E): BLIND FLANGES IMPROPERLY INSTALLED (ALL UNITS)
	84-20-C	50,55E RPT	C		0		50,55(E): CONNECTING LINE TO 81R 380 DAMAGED
	84-21-C	50,55E RPT	C		0		50,55(E): ROSEMONT TRANSMITTERS LOOSE NUTS
	84-22-C	50,55E RPT	C		0		50,55(F): CEA SHROUD CONTAMINATED WITH OIL
	84-23-C	50,55E RPT	C		0		50,55(E): AFW VALVE LOOSE SLEEVE PIN
	84-24-C	50,55E RPT	C		0		50,55(F): LOOSE BOLTS ON BOLTS ON LIMITORQUE OPERATORS (ALL UNITS)
	84-25-C	50,55E RPT	C		0		50,55(E): TITUS AIR SUPPLY AIR SUPPLY REGISTERS BY TITUS HAVE WIPE (ALL UNITS)
	84-33-C	50,55E RPT	C		0		50,55(F): UNIT 1 MISSING WELD ON PIPE SUPPORT ISI070H011