ENCLOSURE 1

NOTICE OF DEVIATION

Florida Power Corporation Crystal River 3 Docket No. 50-302 License No. DPR-72

The following deviations were identified during an inspection conducted on January 31 - February 24, 1984.

Letters to the Nuclear Regulatory Commission from FPC, dated June 16 and July 29, 1983 responded to the violation identified in NRC Inspection Report 50-302/83-09 and stated that the calibration of all IST related instrumentation would be accomplished prior to plant startup for operating cycle 5. This response also stated that an evaluation of all systems subject to Inservice Inspection per Section XI of the ASME Boiler and Pressure Vessel Code would be conducted to determine if such systems were incorrectly determined to be operable through the use of instrumentation that was out of calibration.

Contrary to the above, as of February 24, 1984, calibration of all IST related instrumentation had not been performed nor was an evaluation for system operability with out-of-calibration instrumentation performed.

Please provide, in writing within 30 days of the date of this Notice, a description of corrective actions regarding these deviations, actions taken to avoid further deviations, and the dates when these actions were or will be completed.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by $10 \ \text{CFR} \ 2.790(d)$ or $10 \ \text{CFR} \ 73.21$.

Date: APR 05 1004