

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50528	02-07-84	OTHER	S		0		MALICIOUS MISCHIEF-22 CUT CABLES IN UPPER CABLE SPREADING RM - UNIT 3
	04-26-83	OTHER	S		0		GENERIC LETTER RE: LAW ENFORCEMENT VISITS, DTD 4/28/83
	10-10-83	OTHER	S		0		INITIAL BOMB THREAT ON SITE TARGET-CONTROL ROOM
	11-03-83	OTHER	S		0		73.71(C) RPT #83-001-493 RE: DOOR F-202 FOUND UNLOCKED AND AJAR
	11-04-83	OTHER	S		0		SHERIFF'S DEPT ARRESTS FIVE SUBCONTRACTOR EMPLOYEES FOR MARIJUANA
	12-02-83	OTHER	S		0		DEC 2, 83 APS LTR WITH SGI WAS IMPROPERLY SENT TO HQ, NRC,
	12-23-83	OTHER	S		0		CONSTRUCTION DEFICIENCY (SOLDERING) OF OMNI-SPECTRA MICROWAVE UNITS
	81-08-X1	SPECIAL RPT.	C		0		RY FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
	81-10-21	PART 21	C		0		PART 21-(PARSONS PEERLES) DIESEL GENERATOR SYSTEM DEFECT
	84-02-P	PART 21	C		0		PR 21 BY TERRY/ING-RAND AFW TURBINE VALVES NEED NEW SPRINGS

8406230472 840612
 PDR ADDCK 05000528
 PDR

4 CYS ON SHIF

06/12/84

REGION 5
LICENSEE EVENT REPORT

PAGE 1

DOCKET	ITEM-NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
50529	81-08-X1	SPECIAL RPT.	C		0		RV FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
	81-10-21	PART 21	C		0		PART 21-(PARSONS PEEPLES) DIESEL GENERATOR SYSTEM DEFECT

DOCKET ITEM#NUM	TYPE	FOLLOWUP BRANCH	FOLLOWUP REPORT NO.	STATUS	ACTION DATE	DESCRIPTIVE TITLE
-----------------	------	--------------------	------------------------	--------	-------------	----------------------

50530 81-0A-X1	SPECIAL FRT,	C		0		RV FOLLOWUP-PROBLEMS WITH CRANE TILTING DISC CHECK VALVES
----------------	--------------	---	--	---	--	--

81-10-21	PART 21	C		0		PART 21-(PARSONS PEEBLES) DIESEL GENERATOR SYSTEM DEFECT
----------	---------	---	--	---	--	---