

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

SEP 1 1 1995

Wolf Creek Nuclear Operating Corporation ATTN: Neil S. Carns, President and Chief Executive Officer P.O. Box 411 Burlington, Kansas 66839

SUBJECT: NRC INSPECTION REPORT 50-482/95-17 AND NOTICE OF DEVIATION

This refers to the inspection conducted by Messrs. J. F. Ringwald, R. V. Azua, and Ms. J. L. Dixon-Herrity of this office on July 16 through August 26, 1995, at the Wolf Creek Generating Station facility. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to deviate from your commitments in the Updated Safety Analysis Report, as specified in the enclosed Notice of Deviation (Notice). While this deviation did not appear to result in an operability issue, we are concerned that failure to comply with seismic installation instructions could result in operability concerns. A noncited violation was identified regarding the use of the wrong torque for fasteners. This noncited violation is of concern because we continue to identify examples of weakness in your planning for maintenance and quality control inspection activities. We urge you to improve the thoroughness of your planning for these activities.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure(s), and your response will be placed in the NRC Public Document Room (PDR). To the extent possible, your response should not

9509180292 950911 PDR ADDCK 05000482 Q PDR



UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

SEP 1 1 1995

Wolf Creek Nuclear Operating Corporation ATTN: Neil S. Carns, President and Chief Executive Officer P.O. Box 411 Burlington, Kansas 66839

SUBJECT: NRC INSPECTION REPORT 50-482/95-17 AND NOTICE OF DEVIATION

This refers to the inspection conducted by Messrs. J. F. Ringwald, R. V. Azua, and Ms. J. L. Dixon-Herrity of this office on July 16 through August 26, 1995, at the Wolf Creek Generating Station facility. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to deviate from your commitments in the Updated Safety Analysis Report, as specified in the enclosed Notice of Deviation (Notice). While this deviation did not appear to result in an operability issue, we are concerned that failure to comply with seismic installation instructions could result in operability concerns. A noncited violation was identified regarding the use of the wrong torque for fasteners. This noncited violation is of concern because we continue to identify examples of weakness in your planning for maintenance and quality control inspection activities. We urge you to improve the thoroughness of your planning for these activities.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NAC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure(s), and your response will be placed in the NRC Public Document Room (PDR). To the extent possible, your response should not

include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

J. E. Dyer, Director Division of Reactor Projects

Docket: 50-482 License: NPF-42

Enclosures:

 Notice of Deviation
 NRC Inspection Report 50-482/95-17

cc w/enclosures: Wolf Creek Nuclear Operating Corp. ATTN: Vice President Plant Operations P.O. Box 411 Burlington, Kansas 66839

Shaw, Pittman, Potts & Trowbridge ATTN: Jay Silberg, Esq. 2300 N Street, NW Washington, D.C. 20037

U.S. Nuclear Regulatory Commission ATTN: Regional Administrator, Region III 801 Warrenville Road Lisle, Illinois 60532-4351

Wolf Creek Nuclear Operating Corp. ATTN: Supervisor Licensing P.O. Box 411 Burlington, Kansas 66839 Wolf Creek Nuclear Operating -4-Corporation

E-Mail report to D. Sullivan (DJS)
E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan
Branch Chief (DRP/B)
Section Chief (RIII, DRP/3C)
SRI (Callaway, RIII)
Project Engineer (DRP/B)
Branch Chief (DRP/TSS)

Resident Inspector
DRSS-FIPB
RIV File
MIS System
Leah Tremper (OC/LFDCB, MS: TWFN 9E10)

DOCUMENT NAME: R:\ WC517rp.jfr

To receive copy of document, indicate in box: "C" = Copy without enployures "E" = Copy with enclosures "N" = No copy

RIV:SRI:DRP/B	AC:DRP/B		D:DRSS	
JFRingwald:sa	DFKirsch	JEDyer V	TDEXTER Stelecon	
09/11/95	09/11/95	09/11/95	09/11/95	

OFFICIAL RECORD COPY

Wolf Creek Nuclear Operating Corp. ATTN: Supervisor Regulatory Compliance P.O. Box 411 Burlington, Kansas 66839

Missouri Public Service Commission ATTN: Assistant Manager Energy Department P.O. Box 360 Jefferson City, Missouri 65102

Kansas Corporation Commission ATTN: Chief Engineer Utilities Division 1500 SW Arrowhead Rd. Topeka, Kansas 66604-4027

Office of the Governor State of Kansas Topeka, Kansas 66612

Attorney General Judicial Center 301 S.W. 10th 2nd Floor Topeka, Kansas 66612-1597

County Clerk Coffey County Courthouse Burlington, Kansas 66839-1798

Kansas Department of Health and Environment Bureau of Air & Radiation ATTN: Public Health Physicist Division of Environment Forbes Field Building 283 Topeka, Kansas 66620