05-38-90

DCS No: 03029300900308 Date: March 29, 1990

## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE -- PNO-117-90-02A

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by the IIT on this date.

Facility: Georgia Power Company Yogtia Unit 1 Docket No. 50-424 Waynesboro, GA	Licensee Emergency Classification:  Notification of Unusual Event  Alert  Site Area Emergency General Emergency Not Applicable
No. 1995 The Control of the Control	V (2)

Subject: STATUS REPORT FROM NRC INCIDENT INVESTIGATION TEAM

The Incluent Intestigation Toam (IIT) remains on ofte gathering data, conducting interviews, inspecting equipment, meeting with the licensee, concurring in licensee action plans and analyzing facts. A preliminary sequence of events has been developed by the IIT and is enclosed.

All site interviews should be completed by March 31, 1990. All licensee action plans for further troubleshooting and uncovering remaining event-related information should be finalized on March 31, 1990.

A final status report will be issued prior to the III's departure from the site.

CONTACT:	A. Chaff (404-554	ee -9901)	W. Lazarus (404-554-9902)			
DISTRIBUTION: OWFN Chairman Carr Comm. Roberts Comm. Rogers Comm. Curtiss Comm. Remick		MNBB L- AEOD PD IRM OIG	L-St. PDR	NL RES	Ma:11:	ADM: DMB DOT: Trans only
					NRC Ops Ctr	
CA OGC GPA	EDO NMSS NRR	Phillips ACRS		INPO		
PA C	OE SLITP	Regional	Offices	RI Resident Office  Liceensee: (Reactor Licensees)		
		EWW ASLAP				

# INCIDENT INVESTIGATION TEAM PRELIMINARY SEQUENCE OF EVENTS

#### INITIAL PLANT CONDITIONS:

- Unit 2 operating ut a stoody state power of jone,
- Unit 1 in day 24 of a planned 44-day outage.
- Non-emergency ac power was being supplied by backfeeding through the main transformer to the unit auxiliary transformers.
- Power was being supplied to both emergency 4kV busses from a single transformer (the 14 Meseve auxillary transformer).
- The other 4kV emergency transformer (the 1E reserve auxiliary transformer) was out of service for planned maintenance.
- One of the two unit 1 diesel generators (1B) was out of service for overhaul and inspection.
- The "A" loop of residual heat removal (RHR) was providing core cooling with the reactor coolant system in mid loop at approximately 90 degrees Fahrenheit.
- The reactor coolant system was open at several locations for maintenance.
- The containment equipment hatch was fully open for removal of equipment.
- The 1B RHR injection valve was closed and out of service leaving only the 1A injection valve (which was de-energized open) available for shutdown cooling.
- NOTE: All times are EST. Some provious reports of this incident were reported in CST.

### Time Description of Event

- A lubrication and fuel truck backed into a support post for the 230kV line resulting in loss of power to the 1A reserve dualliary transformer supplying both Unit 1 and one of the Unit 2 emergency 4kV busses. This resulted in a trip of Unit 2, loss of ac power to the Unit 1 emergency busses, and an undervoltage start of the 1A diesel generator.
- 0921 1A diesel generator tripped.
- 0940 Site area emergency declared due to loss of emergency ac power for greater than 15 minutes.
- O941 Diesel generator 1A restarted as expected when the load sequencer was locally reset. Diesel generator 1A tripped again.
- O956 Local emergency start of diesel generator 1A was successful and emergency AC power was restored to the 1A emergency bus.
- 0957 Emergency plan initial notifications of the Site Area Emergency (SAE) commenced.

#### Description of Events Time NRC Operations Center notified of SAE. 0958 RHR was restored. The maximum primary coolant temperature reached 136 1000 degrees Fahrenheit. Completed initial notification of required off-site emergency response 1013 organizations except for Georgia Emergency Management Agency (GEMA) and Burke County Georgia. (The normal Emergency Notification Network (ENN) was out of service in the control room bacause it is powered by vital power which was lost.) The Site Area Emergency was downgraded to an alert. 1015 GEMA is aware of an emergency at Vogtle due to checkout of ENN from the 1016 Technical Support Center, but does not receive the details of the SAE. The plant Technical Support Center (TSC) was activated. 1026 The TSC infurmed GEMA that the SAE existed but had been downgraded to an 1029 alert. Installation of the steam generator primary manways was completed. 1034 GEMA received a facsimile from South Carolina with the details of the initial 1035 notification. Initial formal notification of GEMA was completed by the licensee. 1041 The containment equipment hatch was boilted in place. 1042 The 1B emergency bus was re-energized from its normal transformer (reserve 1140 auxiliary transformer 1E) which had been out of service for maintenance. The pressurizer manway was installed. 1140 RHR was shifted to the B RHR pump (to facilitate later electrical alignment 1238 changes). Emergency terminated. 1347

The 1A diesel generator was shutdown. Both emergency busses were receiving

power from the 1R reserve auxiliary transformer.

1426