

Appendix

NOTICE OF VIOLATION

Union Electric Company

Docket No. 50-483

As a result of the inspection conducted on May 16-18, 1984, and in accordance with the General Policy and Procedures for NRC Enforcement Actions, (10 CFR Part 2, Appendix C), the following violation was identified:

10 CFR 50, Appendix B, Criterion III, as implemented by SNUPPS Quality Assurance Program for Design and Construction, Section 17.1.3, requires that the design basis be correctly translated into specifications, drawings and instructions.


Contrary to the above, the installation of diesel generator control panels KJ121 and KJ122 was not in accordance with the design basis seismic qualification test descriptions and drawing No. 01761414S. Mounting details on the seismic qualification test drawing No. 01761414S shows the configuration of the diesel generator panels mounting to be significantly different from the as-built installation.

This is a Severity Level V violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

JUN 8 1984

\_\_\_\_\_  
Dated

  
\_\_\_\_\_  
R. L. Spessard, Director  
Division of Engineering