SCE&G

South Carplina Electric & Gas Company F O Box 88 Jankinsville, SC 29965 (803) 345-4040 John L. Skolds Vice President Nuclear Operations

February 19, 1992

Mr. S. D. Ebneter Regional Administrator U. S. Nuclear Regulatory Commission Region II, Suite 2900 101 Marietta Street, NW Atlanta, GA 30323

Dear Mr. Ebneter:

SUBJECT: VIRGIL C. SUMMER NUCLEAR STATION DOCKET NO. 50/395 OPERATING LICENSE NO. NPF-12 SPECIAL REPORT (SPR 920001)

This Special Report is being submitted by South Carolina Electric & Gas Company pursuant to the requirements of the Virgil C. Summer Nuclear Station (VCSNS) Station Administrative Procedure (SAP) 131A, Fire Equipment/Systems Operability Requirements.

On January 28, 1992, during an engineering inspection of the Diesel Generator Fire Service Sprinkler System, a piping penetration in a 3-hour rated fire wall separating the "A" and "B" Diesel Generator Rooms was identified as not listed in the required fire barrier Surveillance Test Procedure (STP). The penetration was sealed, but because it was not listed in the applicable STP (728.027), no surveillance had been performed as required by SAP-131A. The penetration was declared inoperable and compensatory action was taken as required by procedure. A Nonconformance Notice (NCN) was initiated documenting the discrepancy. Disposition of the NCN directed that the penetration be inspected, reworked/repair (if required) to the original installation, and the penetration be included in the applicable STP.

Inspection of the penetration found it to be functional as-is, and it was declared operable on January 31, 1992. A procedure change has been made to incorporate the penetration.

The cause of this event was the inadvertent omission of the barrier from the applicable STP. SAP-131A Surveillance Requirement requires a visual inspection of at least 10 percent of each type of sealed penetration be performed at least once each 18 months. In the upcoming STP inspection, a 100 percent inspection of fire barriers will be performed. Each fire barrier will be verified and uniquely identified at this time. Any barrier not listed in the STP will be readily identified by the absence of a label or tag. This action will be completed by January 1994.

9202250118 920219 PDR ADDCK 05000395 40210

. Mr. S. D. Ebneter SPR 920001 Page 2 of 2

Should you have any questions, please call at your convenience.

Very truly yours,

John L. Skolds

## RJB:JLS:1cd

C: O. W. Dixon Jr.
R. R. Mahan
R. J. White
General Managers
G. f. Wunder
S. R. Hunt
NRC Resident Inspector
J. B. Knotts Jr.
Marsh & McLennan
Document Control Desk
INPU Records Center
ANI Library
NSRC
RTS (ONO 920007)
File (818.05 & 818.08)