

RECEIVED
NRC

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

1984 JUN 21 PM 12:35

June 19, 1984
G01-84-0184

REGION V WIRE

50-513

Mr. J. B. Martin
Regional Administration
Nuclear Regulatory Commission
Region V
1450 Maria Lane, Suite 210
Walnut Creek, Calif. 94596

Subject: NUCLEAR PROJECT NO. 4
DOCKET NO. 50-513 REPORTABLE 10CFR50.55(e)
ROCKBESTOS CABLE


- Reference: 1) Telecon ME Rodin, Supply System to PP Narbut, Region V, Nuclear Regulatory Commission, dated 1/26/82
- 2) G01-82-0060, dated 2/26/82, DW Mazur to RH Faulkenberry
 - 3) G01-82-0152, dated 4/21/82, RW Root to RH Faulkenberry
 - 4) G01-82-0413, dated 7/2/82, DW Mazur to RH Faulkenberry
 - 5) G01-83-344, dated 6/29/83, RA De Lorenzo to DM Sternberg

Reference 3) informed your office of a reportable deficiency under 10CFR50.55(e) and transmitted an interim status report on the subject condition.

Reference 4) provided the Supply System's final report on the above caption condition; however, a completion schedule had not yet been established. Since it has been determined that the only cable involved is that used in the Unit 4 penetrations (see reference 4) this letter only refers to Unit 4 and Docket No. 50-513.

During contract closeout activities, it was agreed between the Supply System and Westinghouse that the WNP-4 penetrations would be destroyed or made non-reusable. Therefore, sections of the defective cable were removed and the penetrations have been scrapped.

In view of this action, we consider the activities associated with this 10CFR50.55(e) to be complete and will not submit any further reports.



R. W. Root, Director
WNP-1/4 Program (821)

RWR.GAB:pp

- cc: TA Mangelsdorf, BPC (862)
V Mani, UE&C (897)
EC Haren, UE&C (895)
NRC Doc. Control Desk, DC
FDCC (899)
BDCC (828)
ORM (847)

FILE COPY

8406290280 840619
PDR ADOCK 05000513
S PDR

IE-27 1/0