

DMB

ILLINOIS POWER COMPANY



1605-L
U-10169

CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727

June 21, 1984

Docket No. 50-461

Mr. James G. Keppler
Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Potential 10CFR50.55(e) Deficiency 55-84-02:
Material Traceability

Dear Mr. Keppler:

In Illinois Power Company letter dated February 14, 1984 (Ref: Letter D. P. Hall to J. G. Keppler, U-10124), your office was provided an interim report addressing the status of the subject 10CFR50.55(e) investigation. It was anticipated at the time that an interim report would be provided in approximately ninety (90) days.

Illinois Power Company is presently involved in evaluating the need to expand its investigation associated with the Material Traceability issue. It is anticipated that approximately thirty (30) additional days will be necessary to complete our evaluation and provide an interim report on the issue.

If you have any questions or comments regarding the status of actions taken on this issue, please contact Illinois Power Company.

Sincerely yours,

D. P. Hall
Vice President

8406290298 840621
PDR ADOCK 05000461
S PDR

RLC/cbs

cc: NRC Resident Office
Director - Office of I&E, US NRC, Washington, DC 20555
Illinois Department of Nuclear Safety
INPO Records Center

JUN 25 1984 /10 IE27