-Edoningo ini chimini

JUN 2 2 1984

AFFOLIADDO INFORM

Docket No. 50-305

Wisconsin Public Service Corporation ATTN: Mr. C. W. Giesler Vice President Nuclear Power Post Office Box 1200 Green Bay, WI 54305

Gentlemen:

8406290366 840622 PDR ADDCK 05000305

This refers to the routine safeguards inspection conducted by Messrs. T. J. Madeda and B. W. Stapleton of this office on May 7-11, 1984, of activities at the Kewaunee Nuclear Power Plant authorized by NRC Operating License No. DPR-43 and to the discussion of our findings with Mr. R. Lange and other members of your staff at the conclusion of the inspection.


The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix. With respect to Item 1, the inspection showed that action had been taken to correct the identified noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required and we have no further questions regarding this matter at this time.


Regarding the remaining item, a written response is required.

In addition, we request that you respond in writing within 30 days of the date of this letter to our concerns identified in Sections 15 and 18. Your response should describe your actions taken to address these concerns. The response should be submitted as a separate enclosure to your transmittal letter in the manner prescribed.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 73.21(c)(2) of the NRC's "Rules of Practice," Part 73, Title 10, Code of Federal kegulations. This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, the enclosure to this letter, our report of this inspection, and your response to the noncompliance identified in the enclosure to this letter will not be placed in the Public Document Room. Therefore, your statement of



Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled



Wisconsin Public Service Corporation

JUN 2 2 1984

corrective action regarding the noncompliance identified in the enclosure should be submitted as a separate enclosure to your transmittal letter in the manner prescribed.

2

The responses directed by this letter (and the accompanying Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

RIII

son, Chief

Materials and Safeguards Branch

Fnclosures: 1. Appendix, Notice of Violation Inspection Report 2. No. 50-305/84-06(DRMSP) (UNCLASSIFIED SAFEGUARDS INFORMATION) cc w/encls: D. C. Hintz, Plant Superintendent IE File IE/DQASIP/ORPB IE/ES NMSS/SGPL NRR/DL/SSPB ACRS cc w/encls, w/o UNCLASSIFIED SAFEGUARDS INFORMATION: DMB/Document Control Desk (RIDS) Resident Inspector, RIII John J. Duffy, Chief Boiler Section Ness Flores, Chairperson Wisconsin Public Service Commission RIII Madeda/rr 06/14/84

AXENSO

Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled