



Northern States Power Company

Prairie Island Nuclear Generating Plant

1717 Wakonade Dr. East  
Weich, Minnesota 55089

September 25, 1995

U S Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-306 License No. DPR-60

Unit 2 Inservice Inspection Summary Report  
Refueling Outage No. 17

During the 1995 Prairie Island Unit 2 refueling outage (Refueling Outage No. 17), an inservice inspection (ISI) examination for the third period of the second 10-year interval and for the first period of the third 10-year interval was conducted. Attached for your information are four copies of the ISI examination Summary Report for the period.

The report identifies components examined, the examination methods used, the examination number, and summarizes the results. All anomalies were either corrected or an engineering evaluation was performed to accept "as is" conditions. A description of the corrective work and the corresponding work request numbers are provided in the ASME Section XI Repair/Replacement portion of the report.

This Summary Report is being submitted in accordance with the Prairie Island ASME Code Section XI Inservice Inspection and Testing Program and is intended to satisfy the inspection reporting requirements contained in IWA-6220 of the ASME Boiler and Pressure Vessel Code.

Sincerely,

Michael D Wadley  
Plant Manager  
Prairie Island Nuclear Generating Plant

c: (see next page)

9509280139 950925  
PDR ADCK 05000306  
R PDR

AC47 | 4

US NRC

September 25, 1995

Page 2

c: Regional Administrator III, NRC (2 copies of attachment)  
NRR Project Manager, NRC (1 copy of attachment)  
Senior Resident Inspector, NRC (w\o attachment)  
J E Silberg (w\o attachment)  
Chief Boiler Inspector, State of MN (1 copy of attachment)  
Paul Fisher, Hartford Ins. (1 copy of attachment)

Attachment: Unit 2 ISI Summary Report, dated September 21, 1995