

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-348
 UNIT NAME J.M. Farley-Unit 1
 DATE June 6, 1984
 COMPLETED BY W.G. Hairston, III
 TELEPHONE (205) 899-5156

REPORT MONTH April, 1984

No	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
003	840401	S	555.9	C	3	84-002-00	N/A	N/A	The Cycle V-VI refueling outage continued from 2-10-84.
004	840424	S	27.6	B	1	N/A	N/A	N/A	Unit shut down for turbine overspeed trip test.

¹
 F: Forced
 S: Scheduled

²
 Reason:
 A-Equipment Failure (Explain)
 B-Maintenance of Test
 C-Refueling
 D-Regulatory Restriction
 E-Operator Training & License Examination
 F-Administrative
 G-Operational Error (Explain)
 H-Other (Explain)

³
 Method:
 1-Manual
 2-Manual Scram.
 3-Automatic Scram.
 4-Other (Explain)

⁴
 Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

⁵
 Exhibit I - Same Source

(9/77)

B407020110 B40608
 PDR ADOCK 05000348
 R PDR