Docket Nos. 50-498 50-499 License Nos. NPF-76 NPF-80

Houston Lighting & Power Company ATTN: Donald P. Hall, Group Vice President, Nuclear P.O. Box 1700 Houston, Texas 77251

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-498/92-02; 50-499/92-02

This refers to the inspection conducted by Mr. L. T. Ricketson of this office on January 21-24, 1992. The inspection included a review of activities authorized for your South Texas Project Electric Generation Station facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements. The violation is discussed in paragraph 4 of the enclosed inspection report and involved the failure to evaluate student response concerning the course content and quality of instruction of certain general employee training. The violation was of minor safety significance and corrective actions were taken prior to the end of the inspection. Therefore, this matter meets the criteria of paragraph V.A of Appendix C to 10 CFR Part 2 and a Notice of Violation will not be issued.

We note that you have provided information as to why you believe that the above matter should not be classified as a violation. We have reviewed your position, but consider the failure to implement training procedures is a violation of Technical Specification 6.8.1.4. This issue is discussed in paragraph 4 of the enclosed inspection report.

In accordance with 10 CFR 2.790 of the NRC'S "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

We have also examined actions you have taken with regard to previously identified inspection findings. The status of these items is identified in paragraph 2 of the enclosed report.

*RIV:FIPS LTRicketsoninh

BMurray *Previously concurred N

D: DRSS LJCallan

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original signed by

A. Bill Reach, Director Division of Reactor Projects

Enclosure: Appendix - NRC Inspection Report 50-498/92-02 50-499/92-02

cc w/enclosure: Houston Lighting & Power Company ATTN: William J. Jump, Manager Nuclear Licensing P.O. Box 289 Wadsworth, Texas 77483

City of Austin Electric Utility Department ATTN: J. C. Lanier/M. B. Lee P.O. Box 1088 Austin, Texas 78767

City Public Service Board ATTN: R. J. Costello/M. T. Hardt P.O. Box 1771 San Antonio, Texas 78296

Newman & Holtzinger, P. C. ATTN: Jack R. Newman, Esq. 1615 L Street, NW Washington, D.C. 20036

Central Power and Light Company ATTN: D. E. Ward/T. M. Puckett P.O. Box 2121 Corpus Christi, Texas 78403

INPO Records Center 1100 Circle 75 Parkway Atlanta, Georgia 30339-3064 Mr. Joseph M. Hendrie 50 Bellport Lane Bellport, New York 11713

Bureau of Radiation Control State of Texas 1101 West 49th Street Austin, Texas 78756

Judge, Matagorda County Matagorda County Courthouse 1700 Seventh Street Bay City, Texas 77414

Licensing Representative Houston Lighting & Power Company Suite 610 Three Metro Center Bethesda, Maryland 20814

Houston Lighting & Power Company ATTN: Rufus S. Scott, Associate General Counsel 7.0. Box 61867 Houston, Texas 77208

bcc to DMB (1E06)

bcc distrib. by RIV:

R. D. Martin
DRF
DRS
DRSS-FIPS
RIV File
RSTS Operator
L. J. Callan, DRSS
B. Murray, FIPS
R. Hall, URFO

Resident Inspector Section Chief (DRP/D) MIS System Lisa Shea, RM/ALF R. Bachmann, OGC Project Engineer (DRP/D) J. P. Jaudon, DRP L. T. Ricketson, FIPS