50-528, 529, 530 Arizona Public Service Company June 19, 1984 ANPP-29774-TDS/TRB U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, CA 94596-5368 Attention: Mr. T. W. Bishop, Director Division of Resident

Reactor Projects and Engineering Programs

Time Extension For Report - DER 84-19 Subject: A 50.55(e) Potentially Reportable Deficiency Relating To

> Improperly Installed Blind Flanges File: 84-019-026; D.4.33.2

Reference: (A) Telephone conversation between P. Narbut and T. Bradish on April 3, 1984

(B) ANPP-29384, dated April 30, 1984 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by June 22, 1984.

A Final Report has been submitted to APS for review. It is expected a Final Report will be transmitted to the NRC by July 31, 1984.

Very truly yours,

E. E. Van Brunt, Jr. APS Vice President Nuclear Production ANPP Project Director

EEVB/TRB:db

cc: See Page Two

8407020409 84061 PDR ADOCK 050005

Mr. T. W. Bishop DER 84-19 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

L. A. Souza

D. E. Fowler

T. D. Shriver

C. N. Russo

J. Vorees

J. R. Bynum

J. M. Allen

J. A. Brand

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. D. Foster

D. R. Hawkinson

L. E. Vorderbrueggen

R. P. Zimmerman

S. R. Frost

J. Self

D. Canady

T. D. Bloom

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339