

ENCLOSURE

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

Inspection Report: 50-267/95-03

License: DPR-34

Licensee: Public Service Company of Colorado
P.O. Box 840
Denver, Colorado 80201-0840

Facility Name: Fort St. Vrain Nuclear Generating Station

Inspection At: Fort St. Vrain, Platteville, Colorado

Inspection Conducted: September 5-7, 1995

Inspector: A. B. Earnest, Physical Security Specialist,
Reactor Inspection Branch

Approved:

Blaine Murray
for Blaine Murray, Chief
Reactor Inspection Branch

9-29-95
Date

Inspection Summary

Areas Inspected: Routine, announced inspection of the physical security program, including a review of the implementation of the program, approved procedures, and activities of the guard force.

Results:

- The inspector determined that the training and qualification program for security officers appeared to be adequate (Section 1.1).
- An inspection followup item was identified in the areas of assessment aids, alarm system, and communications (Section 1.2).
- The lighting system was adequate (Section 1.3).
- The licensee had an adequate lock and key control system (Section 1.4).
- A good barrier system was installed and maintained (Section 1.5).

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

Summary of Inspection Findings:

- Inspection Followup Item 267/9503-01 was opened (Section 1.2).

Attachment:

- Persons Contacted and Exit Meeting

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED