



Nebraska Public Power District

GENERAL OFFICE
P.O. BOX 499, COLUMBUS, NEBRASKA 68601-0499
TELEPHONE (402) 564-8561

NLS8400140

May 11, 1984



Mr. John T. Collins
Regional Administrator
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76011

Subject: Semi-Annual Operating Report - Radioactive Effluents -
Errata
Cooper Nuclear Station
January 1, 1983 through June 30, 1983
NRC Docket No. 50-298, DPR-46

Dear Mr. Collins:

During preparation of the second semi-annual operating report for the Cooper Nuclear Station for the period July 1-December 31, 1983 an error was discovered in the plotting routines used to generate the Chi/Q and dose isopleths. This error resulted in a rotation of contours one sector (22.5°) counter clockwise from what they should have been.

The plotting program was corrected, and the plots contained in the July 1, 1983 - December 31, 1983 semi-annual report are correct. However, the plots provided in Appendix C of the first semi-annual report for January 1-June 30, 1983, contain the same error. Attached are corrected versions of Figures 3-20 of the January 1, 1983 - June 30, 1983 semi-annual report.

Sincerely,

Jay M. Pilant
Technical Staff Manager
Nuclear Power Group

DGL/cl

Enclosure

cc: Document Control Desk w/enc.
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8407050074 840511
PDR ADOCK 05000298
R PDR

JE 25
1/1