

ENCLOSURE

NOTICE OF VIOLATION

Tennessee Valley Authority
Sequoyah 1 and 2

Docket Nos. 50-327 and 50-328
License Nos. DPR-77 and DPR-79

The following violation was identified during an inspection conducted on March 6 - April 5, 1984. The Severity Level was assigned in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C).

10 CFR 50, Appendix B, Criteria XIII and V require that measures be established to control the storage of material and equipment in accordance with work and inspection instructions. This requirement is implemented by the licensee's approved quality assurance program "Operational Quality Assurance Manual" Part III, Section 2.2, paragraph 4.2 and Administrative Instruction AI-36 "Storage, Handling and Shipping of QA Material", which requires that all horizontal 6.6 kV electric motors be stored with the bearing reservoir filled with the proper oil.

Contrary to the above, equipment was not being stored in accordance with instructions in that on March 9 and 12, 1984 the inspector identified six 6.6 kV electric motors that were being stored in the Power Stores modification warehouse with the bearing reservoirs dry.

This is a Severity Level IV Violation (Supplement I). This violation applies to Units 1 and 2.

Pursuant to 10 CFR 2.201, you are required to submit to this office within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved.

Security or safeguards information should be submitted as an enclosure to facilitate withholding it from public disclosure as required by 10 CFR 2.790(d) or 10 CFR 73.21.

Date: MAY 14 1984