

DMB



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

Serving The Best Location in the Nation

June 7, 1984

MURRAY R. EDELMAN

VICE PRESIDENT  
NUCLEAR

Mr. James G. Keppler  
Regional Administrator, Region III  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

RE: Perry Nuclear Power Plant  
Docket Nos. 50-440; 50-441  
Restart of the Control Complex  
Chiller [RDC 70(83)]

Dear Mr. Keppler:

In our final report dated August 15, 1983, restart of Control Room Chiller following a Loss of Offsite Power (LOOP) or a Loss of Coolant Accident (LOCA) we stated that corrective action would include review of Safety Systems and issuance of design modifications by Gilbert Associates, Inc., the Architect/Engineer, and implementation of the modifications. Subsequent correspondence on this subject was dated December 21, 1983.

This letter has been written to inform you that Engineering Change Notices 15383-033-2613 and 15384-086-248 were issued to document the necessary design modifications. Implementation of these modifications is now anticipated by November 1, 1984.

Please call if there are additional questions.

Sincerely,

Murray R. Edelman  
Vice President  
Nuclear Group

MRE:pab

cc: Mr. J. A. Grobe  
NRC Site Office

Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

U.S. Nuclear Regulatory Commission  
c/o Document Management Branch  
Washington, D.C. 20555

Records Center, SEE-IN  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8407100258 840601  
PDR ADOCK 05000440  
S PDR

JUN 12 1984

IEJ7 1/0