

P.O. BOX 5000 - CLEVELAND, OHIO 44101 - TELEPHONE (216) 622-9800 - ILLUMINATING BLDG. - 55 PUBLIC SQUARE

Serving The Best Location in the Nation

June 7, 1984

MURRAY R. EDELMAN VICE PRESIDENT NUCLEAR Mr. James G. Keppler Regional Administrator, Region III Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

> RE: Perry Nuclear Power Plant Docket Nos. 50-440; 50-441 Cooling of the Reactor Core Isolation Cooling Room [RDC 72(83)]

Dear Mr. Keppler:

In our final report dated June 10, 1983, concerning cooling of the Reactor Core Isolation Cooling (RCIC) room during a Loss of Coolant Accident we stated that corrective action would include review of Safety Systems, and issuance of design modification by Gilbert Associates, Inc., the Architect/ Engineer, and implementation of the modifications. Subsequent correspondence on this subject was dated August 16, 1983, and December 21, 1983.

This letter has been written to inform you that Engineering Change Notice 18848-86-314 was issued to document the necessary design modifications for Unit 1. Implementation of these modifications is now anticipated by November 1, 1984. We will advise you by December 6, 1985, about the status of the Unit 2 design modifications.

Please call if there are additional questions.

Sincerely, una 1 Elel

Murray R. Edelman Vice President Nuclear Group

MRE: pab

cc: Mr. J. A. Grobe NRC Site Office

> Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

8407100294 840607 PDR ADOCK 05000440

U.S. Nuclear Regulatory Commission c/o Document Management Branch Washington, D.C. 20555

Records Center, SEE-IN Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, Georgia 30339

JUN 1 2 1984 JEA7 10