

DAB

JUL 06 1984

Docket No. 50-483

Union Electric Company
ATTN: Mr. Donald F. Schnell
Vice President - Nuclear
Post Office Box 149 - Mail Code 400
St. Louis, MO 63166

Gentlemen:

This refers to the announced pre-operational physical protection inspection conducted by Mr. G. L. Pirtle of this office on May 14-18 and 29-30, 1984, of activities at the Callaway County Nuclear Station, Unit 1, authorized by NRC Construction Permit No. CPPR-139 and to the discussion of our findings with Messrs. S. Miltenberger, A. Neuhoffen, and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We are concerned about the work schedule for the security force. Your commitment identified in paragraph 3b(1) of the Report Details should help resolve this issue in a timely manner. We will continue to monitor your success in this area closely.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Section 73.21(c)(2) of the NRC's "Rules of Practice," Part 73, Title 10, Code of Federal Regulations. This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, our report of this inspection will not be placed in the Public Document Room.

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

B407100470 B40706
PDR ADOCK 05000483
Q PDR

2E04

11

JUL 06 1984

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

C. J. Paperella
 for J. A. Hind, Director
 Division of Radiation Safety
 and Safeguards

Enclosure: Inspection Report
 No. 50-483/84-25(DRSS)
 (UNCLASSIFIED SAFEGUARDS INFORMATION)

cc w/encl:
 W. H. Weber, Manager, Nuclear
 Construction
 S. E. Miltenberger, Plant Manager
 R. L. Powers, Assistant Manager
 Quality Assurance
 IE File
 IE/DQASIP
 IE/ES
 NMSS/SGPL
 NRR/DL/SSPB
 ACRS

cc w/encl, w/o UNCLASSIFIED
 SAFEGUARDS INFORMATION
 DMB/Document Control Desk (RIDS)
 Resident Inspector, RIII
 Region IV
 K. Drey
 Chris R. Rogers, P.E.
 Utility Division, Missouri
 Public Service Commission

RIII
JRK for
 Pirtle/rr
 06/27/84

RIII
Creed
 Creed

RIII
Pelke
 Pelke

RIII
Axelsson
 Axelsson

RIII
Hind
 Hind

Enclosure contains
 SAFEGUARDS INFORMATION
 Upon separation this
 PAGE is Decontrolled

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-483/84-25(DRMSP)

Docket No. 50-483

License No. CPPR-139

Licensee: Union Electric Company
Post Office Box 149 - Mail Code 400
St. Louis, MO 63166

Facility Name: Callaway County Nuclear Power Station, Unit 1

Inspection At: Callaway County, MO

Inspection Conducted: May 14-18, and 29-30 (onsite)
May 25, June 1, 6-7, and 15, 1984 (Region III office)

Type of Inspection: Announced, Pre-Operational Physical Protection

Date of Previous Physical Protection Inspection: April 2-13 and 23, 1984

Inspector: J.R. Creed
for G. L. Pirtle
Physical Protection Specialist

7/6/84
Date

Approved By: J.R. Creed
J. R. Creed, Chief
Physical Security Section

7/6/84
Date

Inspection Summary

Inspection on May 14-18 and May 29 - June 15, 1984 (Report No. 50-483/84-25 [DRMSP])

Areas Inspected: Included a review of licensee's actions on previous inspection findings; Security Plan and Implementing Procedures; Security Organization - Management, Personnel, and Response; Testing and Maintenance; Locks, Keys, and Combinations; Physical Barriers - Protected Area and Vital Area; Security System Power Supply; Lighting; Assessment Aids; Access Control - Personnel - Packages - Vehicles; Detection Aids - Protected and Vital Areas; Alarm Stations; Communications; and General and Additional Training and Qualification Plan Requirements for Power Reactors. The inspection involved 72 inspector-hours by one NRC inspector. Sixteen of the 72 hours were completed during back-shift periods.

Results: All significant findings addressed in previous inspection reports have been corrected or resolved. A concern pertaining to the security force

8407100474 840706
PDR ADOCK 05000483
G PDR

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

scheduled overtime was identified during this inspection. NRC Region III will monitor the licensee's actions to reduce scheduled overtime. This matter does not impact program implementation.

(Report Details - UNCLASSIFIED SAFEGUARDS INFORMATION