

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

September 21, 1995

Southern California Edison Company San Onofre Nuclear Generating Station ATTN: Harold B. Ray, Senior Vice President, Power Systems P.O. Box 128 San Clemente, California 92674-0128

SUBJECT: NRC INSPECTION REPORT 50-361/95-14: 50-362/95-14

This refers to the inspection conducted by Mr. I. Barnes, Mr. J. Russell, and Ms. K. Weaver of this office and Mr. J. Medoff of the Office of Nuclear Reactor Regulation on July 10 through August 8, 1995. In preparation for the onsite inspection, a meeting was held with licensee staff on June 30, 1995, in the Region IV office to review steam generator activities and initiatives. Additional in-office review was performed following the onsite inspection period through August 30, 1995. The inspection included a review of activities authorized for your San Onofre Nuclear Generating Station, Units 2 and 3, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report and included a steam generator tube integrity review and inservice inspection. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements.

Overall, the results of the inspection indicate that you have implemented a comprehensive eddy current examination program for detection of degradation in steam generator tubing. Other programmatic actions have also been taken which should be beneficial in reducing the incidence of steam generator tube degradation. Of particular note were the effectiveness of your secondary water chemistry controls and scope of program activities, which reflect favorably on chemistry staff. The preparation in 1994 of a detailed steam generator strategic management plan was viewed as a positive step toward enhancing overall steam generator degradation management. The adequacy of implementation of foreign material exclusion control requirements and actions to further reduce corrosion product transport to the steam generators warrant continued management attention.

In accordance with 10 CFR 2.790(a) of the NRC's "Rules of Practice." a copy of this letter and its enclosures will be placed in the NRC Public Document Room unless you notify this office by telephone, within 10 days of the date of this letter, and submit written application to withhold information contained therein within 30 days of the date of this letter. Such application must be consistent with the requirements of 10 CFR 2.790(b)(1).

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely.

Division of Reactor Safety

Dockets: 50-361

50-362

Licenses: NPF-10

NPF-15

Enclosures:

NRC Inspection Report

50-361/95-14: 50-362/95-14

w/attachments

cc w/enclosures:

County of San Diego

ATTN: Chairman, Board of Supervisors 1600 Pacific Highway, Room 335 San Diego, California 92101

Rourke & Woodruff

ATTN: Alan R. Watts, Esq.

701 S. Parker St. No. 7000

Orange, California 92668-4702

Public Utilities Department

City of Riverside

ATTN: Sherwin Harris, Resource

Project Manager

3900 Main Street

Riverside, California 92522

Southern California Edison Company San Onofre Nuclear Generating Station ATTN: R. W. Krieger, Vice President P.O. Box 128 San Clemente, California 92674-0128

California Department of Health Services ATTN: Dr. Harvey Collins, Chief Division of Drinking Water and Environmental Management P.O. Box 942732 Sacramento, California 94234-7320

Bechtel Power Corporation ATTN: Richard Kosiba, Project Manager 12440 E. Imperial Highway Norwalk, California 90650

San Diego Gas & Electric Company ATTN: Richard Krumvieda, Manager Nuclear Department P.O. Box 1831 San Diego, California 92112

Radiological Health Branch State Department of Health Services ATTN: Mr. Steve Hsu P.O. Box 942732 Sacramento, California 94234

City of San Clemente ATTN: Mayor 100 Avenida Presidio San Clemente, California 92672 E-Mail report to D. Nelson (DJN)

E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan DRSS-FIPB

RIV File

Resident Inspector

MIS System

Branch Chief (DRP/F, WCFO)

Senior Project Inspector (DRP/F, WCFO)

Branch Chief (DRP/TSS)

Leah Tremper (OC/LFDCB, MS: TWFN 9E10) B. Henderson (PAO, WCFO)

DOCUMENT NAME: R:\ SO23\SO514RP.IXB

To receive copy of document, indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures сору E-Moul 1) alex RIV: TA OD: DRS RI:MB C:MB NRR . D: DRS D: DRPg 2 IBarnes/1b KDWeaver DAPower Of JMedoff TPGwynn JEDyer 1 TPGwynr 09/20/95 09/ /95 09/20/95

OFFICIAL RECORD COPY

09/20/95 09/ /95

09/11/95

09/11

E-Mail report to D. Nelson (DJN) E-Mail report to NRR Event Tracking System (IPAS)

bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan

DRSS-FIPB

Branch Chief (DRP/F, WCFO) RIV File

Resident Inspector

MIS System

Senior Project Inspector (DRP/F, WCFO)

Branch Chief (DRP/TSS)

Leah Tremper (OC/LFDCB, MS: TWFN 9E10) B. Henderson (PAO, WCFO)

DOCUMENT NAME: R:\\_S023\S0514RP.IXB To receive copy of document, Indicate in box: "C" = Copy without enclosures "E" = Copy with enclosures E-Moul сору NRR / D: DRS D: DRP@ 30 RIV: TA RI:MB C:MB JEDyer 1 IBarnes/1b KDWeaver OD DAPowers On JMedoff **TPGwynn** 10960/95 09/ /95 09/10/95 09/20/95 09/) N95 /95 OFFICIAL RECORD COPY

100005