

ENCLOSURE 1

NOTICE OF VIOLATION

TU Electric
Comanche Peak Steam Electric Station

Dockets: 50-445

Licenses: NPF-87

During an NRC inspection conducted on July 30 through September 9, 1995, one violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," (60 FR 34381; June 30, 1995), the violation is listed below:

Technical Specification 6.8.1 requires that written procedures be established, implemented, and maintained covering the applicable procedures recommended in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978.

Regulatory Guide 1.33, Appendix A, recommends written administrative procedures for operation of the Emergency Core Cooling and Fuel Storage Pool Purification and Cooling Systems.

Comanche Peak Steam Electric Station System Operating Procedure (SOP)-506, "Spent Fuel Pool Cooling and Cleanup System," was written to govern the operation of the refueling water purification system and requires in Step 5.12.1.U that Valve "XSF-0025, SFP DEMIN X-02 SFP RET VLV LVG-11, is closed" when performing that portion of the procedure.

Contrary to the above, while aligning the refueling water purification system to the refueling water storage tank (RWST) on August 3, 1995, licensee operators cross-connected the RWST to the spent fuel pool when they opened Valve XSF-0025, rather than ensuring Valve XSF-0025 was closed as was required by operating Procedure SOP-506, Step 5.12.1.U. This caused the RWST level to decrease below the 95 percent minimum level, as required by Technical Specifications 3.5.4 and 3.1.2.6.

This is a Severity Level IV Violation (Supplement 1). (445/9517-01)

Pursuant to the provisions of 10 CFR 2.201, TU Electric is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region IV, 611 Ryan Plaza Drive, Suite 400, Arlington, Texas 76011, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previous docketed correspondence, if

9510110136 951005
PDR ADOCK 05000445
Q PDR

the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Because the response will be placed in the NRC Public Document Room (PDR), to the extent possible, it should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction. However, if it is necessary to include such information, it should clearly indicate the specific information that should not be placed in the PDR, and provide the legal basis to support the request for withholding the information from the public.

Dated at Arlington, Texas
this 5th day of *October* 1995