RECEIVED HPC Arizona Public Service Company 1384 SEP 24 PM 4: 05 Sepcember 19, 1984 ANPP-30567-TDS/TRB U. S. Nuclear Regulatory Commission Region V Creekside Oaks Office Park 1450 Maria Lane - Suite 210 Walnut Creek, California 94596-5368 Attention: Mr. T. W. Bishop, Director Division of Resident Reactor Projects and Engineering Programs Time Extension For Report - DER 84-48 Subject: A 50.55(e) Potentially Reportable Deficiency Relating To Improper Material For Pipe Plugs On MSIV. File: 84-019-026; D.4.33.2 Reference: (A) Telephone conversation between D. Hollenbach and T. Bradish on July 24, 1984 (B) ANPP-30308, dated August 23, 1984 (Interim Report) Dear Sir: The NRC was notified of a potentially reportable deficiency in Reference (A), and an Interim Report was transmitted by Reference (B). At that time, it was estimated that a Final Report would be available by September 21, 1984. Due to the extensive investigation and evaluation required, it is now expected that this information will be finalized by October 19, 1984, at which time a complete report will be submitted. There is no new information or change to the Interim Report at this time. Very truly yours, SEVan Brust ARV E. E. Van Brunt, Jr. APS Vice President Nuclear Production ANPP Project Director EEVB/TRB/nj cc: See Page Two B410100005 B40919 PDR ADDCK 05000528 PDR 10 IE-27 Mr. T. W. Bishop DER 84-48 Page Two

cc:

Richard DeYoung, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

T. G. Woods, Jr.

D. B. Karner

W. E. Ide

D. B. Fasnacht

A. C. Rogers

L. A. Souza

D. E. Fowler

T. D. Shriver

C. N. Russo

J. Vorees

J. R. Bynum

J. M. Allen

J. A. Brand

A. C. Gehr

W. J. Stubblefield

W. G. Bingham

R. L. Patterson

R. W. Welcher

H. D. Foster

D. R. Hawkinson

L. E. Vorderbrueggen

R. P. Zimmerman

S. R. Frost

L. Clyde

M. Woods

T. J. Bloom

Records Center Institute of Nuclear Power Operations 1100 Circle 75 Parkway, Suite 1500 Atlanta, GA 30339