


September 18, 1984

W3P84-2582 Q-3-A35.07.101 3-A1.01.04

Mr. John T. Collins Regional Administrator, Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012



REFERENCE: 1) LP&L letter W3K84-0916 dated April 23, 1984

 NRR letter dated June 13, 1984 from Darrell G. Eisenhut to J.M. Cain

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3

Docket No. 50-382

Reopening of Significant Construction Deficiency No. 101 "Traceability of Stainless Steel Instrumentation Tubing"

Because of ongoing efforts associated with resolution of issues in reference 2, it may be necessary to modify reference 1. We therefore have elected to reopen SCD101 pending completion of those efforts. A final report will be issued upon completion of this effort which is currently scheduled for October 5, 1984.

Very truly yours,

KW Cook

K.W. Cook

Nuclear Support & Licensing Manager

KWC/RJB/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8410100329 840918 PDR ADOCK 05000382 S PDR

IE27

Mr. John T. Collins W3P84-2582 Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson Monroe & Lemann 1424 Whitney Building New Orleans, Louisiana 70130

Mr. W. A. Cross 7910 Woodmont Avenue Suite 1200 Bethesda, Maryland 20814