

MIDDLE SOUTH UTILITIES SYSTEM


LOUISIANA POWER & LIGHT

142 DELARONDE STREET • P.O. BOX 6008
NEW ORLEANS, LOUISIANA 70174-8008 • (504) 368-2345

September 18, 1984

W3P84-2580
Q-3-A35.07.84
3-A1.01.04

Mr. John T. Collins
Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



- REFERENCE: 1) LP&L letter W3K84-0029 dated January 5, 1984
- 2) NRR letter dated June 13, 1984 from Darrell G. Eisenhut to J.M. Cain

Dear Mr. Collins:

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Reopening of Significant Construction Deficiency No. 84
"Tube Track Welding Deficiencies"

Because of ongoing efforts associated with resolution of issues in reference 2, it may be necessary to modify reference 1. We therefore have elected to reopen SCD84 pending completion of those efforts. A final report will be issued upon completion of this effort which is currently scheduled for October 5, 1984.

Very truly yours,

K.W. Cook
Nuclear Support & Licensing Manager

KWC/RJB/ss

cc: Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8410100336 840918
PDR ADOCK 05000382
S PDR

12-27 1/0

Mr. John T. Collins

W3P84-2580

Page 2

cc: Mr. E. L. Blake
Shaw, Pittman, Potts & Trowbridge
1800 M. Street, N.W.
Washington, D.C. 20036

Mr. W. M. Stevenson
Monroe & Lemann
1424 Whitney Building
New Orleans, Louisiana 70130

Mr. W. A. Cross
7910 Woodmont Avenue
Suite 1200
Bethesda, Maryland 20814